

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19021318/KPS3Q2

**Date:** 13/11/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0002519
<b>Claimant Vehicle No :</b>	SLB7997A	<b>Insured Vehicle No :</b>	PC8003J
Date of Loss:	29/11/2019	Nature of Claim:	TP
		Claim No:	MCV2019D0001560

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB7997A		
Make & Model:	TOYOTA VELLFIRE, 2.4 DBA-ANH20W (A)	Engine No:	2ARH661615
Reg. Date:	22/04/2016 (Man. Year: 2015)	Chassis No:	AGH300049561
Colour:	Metallic Black	Odometer:	240912 km
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	West Lake 9 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	West Lake 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,654.40	4,839.11	6,815.29	58.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,355.00	1,420.00	935.00	39.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>14,009.40</b>	<b>6,259.11</b>	<b>7,750.29</b>	<b>55.32</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,000.00</b>		
<b>Nett Amount (\$\$)</b>	<b>14,009.40</b>	<b>5,000.00</b>	<b>9,009.40</b>	<b>64.31</b>
<b>+ Car Rental (5.0 x S\$130.00/day) (\$\$)</b>		650.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>5,652.00</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>5,600.00</b>		

### INSPECTION

Date of Assignment:	03/12/2019		
Date Inspected:	03/12/2019	Inspected At:	Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01 Singapore 575721
Estimated Period of Repair:	6.0 days		

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2020)
<b>Parts:</b>	M1-MPV	TOYOTA VELLFIRE 2.4 DBA-ANH20W (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB7997A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	2,843.40 FL	*1,380.00 FL
2	1		*FRONT BUMPER SIDE GRILLE	Serviceable	564.30 FL	*- FL
3	1		*FRONT BUMPER SIDE GRILLE CHROME TRIM	Mtg Cracked	321.50 FL	*145.00 FL
4	1		*FRONT BUMPER FOG LAMP	Serviceable	453.80 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER	Distorted	78.30 FL	*78.30 FL
6	1		*FRONT BUMPER SIDE PARK SENSOR	Scratched	348.40 FL	*348.40 FL
7	1		*FRONT TOP GRILLE CHROME	Mtg Cracked	684.60 FL	*684.60 FL
8	1		*FRONT FENDER	Buckled	968.20 FL	*789.20 FL
9	1		*FRONT FENDER DUST COVER	Serviceable	196.40 FL	*- FL
10	1		*FRONT FENDER BLIND SPOTS MIRROR	Serviceable	369.60 FL	*- FL
11	1		*FRONT HEAD LAMP ASSY	Cut	2,533.30 FL	*2,322.90 FL
12	1		*FRONT HEAD LAMP LOWER BRACKET	Serviceable	78.50 FL	*- FL
13	1		*FRONT HEAD LAMP APRON PANEL	Serviceable	159.80 FL	*- FL
14	1		*FRONT SIDE MIRROR ASSY	Serviceable	854.70 FL	*- FL
15	1		*ALLOY RIM	Repair	968.50 FL	*- FL
16	1		*FRONT LOWER ARM	Serviceable	585.20 FL	*- FL
17	1		*FRONT SHOCK ABSORBER	Serviceable	674.30 FL	*- FL
18	1		*FRONT SHOCK ABSORBER TOP MOUNT	Serviceable	257.20 FL	*- FL
19	1		*FRONT STEERING TIE ROD	Serviceable	263.30 FL	*- FL
20	1		*FRONT STEERING TIE ROD END	Serviceable	227.50 FL	*- FL
21	1		*FRONT STEERING ANTI ROLL BAR LINKAGE	Serviceable	85.40 FL	*- FL
22	1		*FRONT KNUCKLE	Bent	568.90 FL	*522.00 FL
23	1		*FRONT WHEEL BEARING HUB	Necessary	468.40 FL	*181.75 FL
24	1		*DRIVE SHAFT LH	Repair	985.70 FL	*- FL

F=Franchise part. L=ListItemDisc.

**Sub Total (\$\$)** **15,539.20** **6,452.15**  
**- List Item Discount on L Items 25.00/25.00% (\$\$)** **3,884.80** **1,613.04**

**Total Parts (\$\$)** **11,654.40** **4,839.11**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	860.00	500.00
2	TO CHECK WIRING SYSTEM	New	60.00	20.00
3	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	100.00	30.00
4	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	100.00	0.00
5	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	220.00	60.00
6	TO INSTALL REVERSE SENSORS & REVERSE CAMERA	New	80.00	50.00
7	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT	New	85.00	60.00
8	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	850.00	700.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,355.00</b>	<b>1,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >