



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JRQ 5443

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	HANDLE BAR (CONSISTENT)	NOT NECESSARY	185.00	-
1	FRONT LEFT SIDE SIGNAL (CONSISTENT)	BROKEN	75.00	75.00
1	HANDLE COVER (CONSISTENT)	NOT NECESSARY	78.00	-
1	FRONT SIDE LEFT FAIRING (CONSISTENT)	TO REPAIR SEE LABOUR	185.00	-
1	FRONT FOOTREST BAR LEFT (CONSISTENT)	BENT	105.00	105.00
1	LEFT SIDE MIRROR (CONSISTENT)	BROKEN	80.00	80.00
1	SET FRONT FORK (CONSISTENT)	NOT NECESSARY	480.00	-
1	FRONT RIM (CONSISTENT)	CUT / DISTORTED	320.00	320.00
1	PILLION FOOTREST LEFT (CONSISTENT)	BROKEN	80.00	80.00
1	SET PILLION FOOTREST BRACKET (N/S) (CONSISTENT)	BROKEN	135.00	67.50
1	PILLION HANDLE BAR (CONSISTENT)	CUT	95.00	95.00
1	LEFT SIDE FAIRING (CONSISTENT)	TO REPAIR SEE LABOUR	80.00	-
1	REAR MUDGUARD (CONSISTENT)	CUT /BENT	185.00	185.00
1	FRONT DISC (CONSISTENT)	NOT NECESSARY	230.00	-
1	SIDE SIGNAL (CONSISTENT)	NOT NECESSARY	150.00	-
1	EXHAUST COVER (CONSISTENT)	NOT NECESSARY	180.00	-
1	BALANCER LEFT (CONSISTENT)	CUT	75.00	75.00
1	REAR LEFT SIGNAL LAMP (CONSISTENT)	BROKEN	85.00	85.00
1	FRONT HEAD LAMP COVER (CONSISTENT)	CUT	135.00	135.00
	LESS 10% DISCOUNT		-293.80	-130.25
			2,644.20	1,172.25
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	15.00	15.00
			15.00	15.00
	<b><u>LABOUR</u></b>			
	TOWING FEE.	NOT NECESSARY	60.00	-
	REMOVE & REPLACE NEW PARTS ,ALIGN & ETC.INCLUSIVE OF THE REPAIR OF FRONT SIDE LEFT FAIRING AND LEFT SIDE FAIRING .		350.00	180.00

Report Ref No. CC4/ASM19021320/Dgs3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REPLACE FORK ASSY ,BRAKE DISC & RIM. REPLACE BODY NEW STICKER AND SPRAY PAINTING.	NOT NECESSARY	150.00	-
			80.00	80.00
			640.00	260.00
GRAND TOTAL			3,299.20	1,447.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,150.00

Report Ref No. CC4/ASM19021320/Dgs3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.