

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM19021320/Dgs3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KITTY			Date: 16-07-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	EH 66J	Veh. Inspected	JRQ 5443	
	Policy No.	GA242415	Coverage (\$)	0.00	
	Claim No.	S9M027XQ	Excess (\$)	0.00	
	Assign From		Assign Date	03/12/2019	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA AFS	c.c	109	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	PMKJA2690GB115213	Colour	RED/ BLACK	
	Odometer	43167	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	70/90 R17	DUNLOP	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	80/90 R17	DUNLOP	4 mm	
	L/H Rear Tyre			mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/11/2019	Inspection Date	03/12/2019	
	Survey held at	SG 98 MOTOR PTE LTD			
		BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				