

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG19021328/R1TD3E2

Date: 14/05/2020

REFERENCE

Insured/Claimant:	MR NGOH KOH FUI FRANK	Policy No:	2100509485
Date of Loss:	29/11/2019	Nature of Claim:	OD
		Claim No:	0053802327SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8420C	Engine No:	PE20893279
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN (A)	Chassis No:	JM6GL1071H0118381
Reg. Date:	19/05/2017 (Man. Year: 2017)	Odometer:	59665 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,132.06	4,859.12	2,272.94	31.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,955.00	3,540.00	6,415.00	64.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,087.06	8,399.12	8,687.94	50.85
Approved Total (Overridden) (\$\$)		6,700.00		
(\$\$)	17,087.06	6,700.00	10,387.06	60.79
+ GST 7.00/7.00% (\$\$)	1,196.09	469.00	727.09	60.79
Nett Amount (\$\$)	18,283.15	7,169.00	11,114.15	60.79

INSPECTION

Date of Assignment:	03/12/2019	
Date Inspected:	06/12/2019	Inspected At:
		Trans Eurokars Pte Ltd (Ubi)
		5 Ubi Close
		Singapore 408605
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,266.60 FL	*1,266.60 FL
2	1		*BRACKET CENTER	Necessary	5.40 FL	*5.40 FL
3	1		*RETAINER LHS	Necessary	41.00 FL	*41.00 FL
4	1		*TOWING COVER LHS	Cracked	24.90 FL	*24.90 FL
5	1		*TOWING COVER RHS	Missing	24.90 FL	*24.90 FL
6	1		*REAR REINFORCEMENT	Bent	538.30 FL	*538.30 FL
7	2		*RETAINER CENTER SENSOR	Necessary	36.40 FL	*36.40 FL
8	2		*SENSOR CENTER, ULTRASONIC	Not Necessary	361.80 FL	*- FL
9	4		*TAPE PROTECTOR, SENSOR	Necessary	34.40 FL	*34.40 FL
10	2		*GROMMET, REAR BUMPER	Necessary	6.00 FL	*6.00 FL
11	4		*GROMMET, REAR BUMPER	Necessary	12.00 FL	*12.00 FL
12	6		*FASTENER, REAR BUMPER	Necessary	18.00 FL	*18.00 FL
13	1		*REFLECTOR LHS	Not Necessary	53.00 FL	*- FL
14	1		*REAR END PANEL	Repair	700.10 FL	*- FL
15	1		*TRIM END PANEL	Not Necessary	122.30 FL	*- FL
16	6		*FASTENER, TRIM	Not Necessary	18.00 FL	*- FL
17	1		*BOOTLID	Bent	1,115.00 FL	*1,115.00 FL
18	1		*WEATHERSTRIP, BOOTLID	Not Necessary	135.60 FL	*- FL
19	1		*ORNAMENT, MAZDA	Necessary	28.90 FL	*28.90 FL
20	1		*ORNAMENT, 6	Necessary	16.50 FL	*16.50 FL
21	1		*MASCOT, REAR	Necessary	49.20 FL	*49.20 FL
22	1		*ORNAMENT, SKYACTIVE	Necessary	74.70 FL	*74.70 FL
23	1		*CHROME FINISHER CENTER	Cracked	302.00 FL	*302.00 FL
24	1		*CHROME FINISHER LHS	Not Necessary	133.40 FL	*- FL
25	1		*CAP CENTER, FINISHER	Not Necessary	15.20 FL	*- FL
26	2		*CAP SIDE, FINISHER	Not Necessary	30.40 FL	*- FL
27	2		*GROMMET, BOOTLID	Necessary	6.60 FL	*6.60 FL
28	1		*LAMP LHS, BOOTLID	Not Necessary	768.80 FL	*- FL
29	1		*TAILLAMP LHS	Cracked	1,592.30 FL	*1,592.30 FL
30	1		*FASTENER, TAILLAMP	Necessary	4.10 FL	*4.10 FL
31	1		*FASTENER, TAILLAMP	Necessary	3.50 FL	*3.50 FL
32	1		*FASTENER, TAILLAMP	Necessary	15.70 FL	*15.70 FL
33	1		*GASKET LHS, BOOTLID	Necessary	52.50 FL	*52.50 FL
34	1		*GASKET RHS, BOOTLID	Necessary	52.50 FL	*52.50 FL
35	1		*GASKET LHS, TAILLAMP	Necessary	27.70 FL	*27.70 FL
36	1		*GASKET RHS, TAILLAMP	Necessary	27.70 FL	*27.70 FL
37	1		*GUARD STONE LHS	Not Necessary	17.40 FL	*- FL
38	2		*LAMP, NUMBER PLATE	Not Necessary	80.60 FL	*- FL
39	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,913.40	5,396.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	781.34	537.68
Total Parts (\$\$)	7,132.06	4,859.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID TO REPAIR REAR FLOOR PANEL, REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT	New	3,780.00	1,260.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL, BOOT LID AND REAR FENDER LH	New	3,600.00	1,800.00
3	TO TRANSFER REVERSE SENSOR	New	180.00	180.00
4	TO TRANSFER REVERSE CAMERA	New	180.00	0.00
5	TO SUPPLY NUMBER PLATE	New	70.00	0.00
6	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	945.00	0.00
7	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	New	350.00	0.00
8	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	0.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (S\$)			9,955.00	3,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >