

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG19021330/USD3E2**Date:** 06/05/2020REFERENCE

Insured/Claimant:	PAK MEW YEEN LISA	Policy No:	2100490312	
Date of Loss:	25/11/2019	Nature of Claim:	OD	Claim No: 2319064906SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH7205X		
Make & Model:	MAZDA 3, 1.5 (A)	Engine No:	P520376940
Reg. Date:	16/11/2016 (Man. Year: 2016)	Chassis No:	JM6BM42A8G0347195
Colour:	Red	Odometer:	29245 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$64,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,568.11	5,729.87	1,838.24	24.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	3,045.00	1,535.00	33.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,148.11	8,774.87	3,373.24	27.77
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	11,848.11	8,474.87	3,373.24	28.47
+ GST 7.00/7.00% (S\$)	829.37	593.24	236.13	28.47
Nett Amount (S\$)	12,677.48	9,068.11	3,609.37	28.47

INSPECTION

Date of Assignment:	03/12/2019		
Date Inspected:	03/12/2019	Inspected At:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Torn	1,083.30 FL	*1,083.30 FL
2	1		*RETAINER LHS	Not Necessary	19.70 FL	*- FL
3	1		*GARNISH LHS, FOGLAMP	Missing	111.50 FL	*111.50 FL
4	1		*COVER LHS, FOGLAMP	Missing	48.80 FL	*48.80 FL
5	1		*COVER LHS, FRONT BUMPER	Missing	29.40 FL	*29.40 FL
6	1		*BRACKET LHS, FRONT BUMPER	Not Necessary	15.90 FL	*- FL
7	1		*FRONT REINFORCEMENT	Bent	466.80 FL	*466.80 FL
8	1		*STIFFA, FRONT BUMPER	Not Necessary	87.90 FL	*- FL
9	12		*CLIP, FRONT BUMPER	Necessary	44.40 FL	*44.40 FL
10	2		*FASTENER, FRONT BUMPER	Necessary	6.00 FL	*6.00 FL
11	1		*CORD SHORT, FOGLAMP	Not Necessary	39.20 FL	*- FL
12	1		*GRILLE TOP	Dented / Deformed	351.80 FL	*351.80 FL
13	6		*RIVET, GRILLE TOP	Necessary	24.00 FL	*24.00 FL
14	4		*RIVET, GRILLE TOP	Necessary	36.80 FL	*36.80 FL
15	1		*BRACKET TOP, GRILLE	Cracked	107.60 FL	*107.60 FL
16	8		*FASTENER, GRILLE	Necessary	25.60 FL	*25.60 FL
17	1		*MASCOT, FRONT	Necessary	46.50 FL	*46.50 FL
18	1		*CHROME LHS	Cracked	185.60 FL	*185.60 FL
19	1		*FRONT GRILLE	Dented / Cracked	610.70 FL	*610.70 FL
20	1		*BRACKET LHS, FRONT GRILLE	Bent / Necessary	15.90 FL	*15.90 FL
21	1		*BRACKET RHS, FRONT GRILLE	Not Necessary	15.90 FL	*- FL
22	2		*PIN LOCATOR, FRONT GRILLE	Necessary	5.80 FL	*5.80 FL
23	2		*GROMMET, FRONT GRILLE	Necessary	5.80 FL	*5.80 FL
24	2		*RIVET, FRONT GRILLE	Necessary	16.00 FL	*16.00 FL
25	1		*TOWING COVER	Torn	30.10 FL	*30.10 FL
26	1		*COVER LHS, HEADLAMP WASHER	Missing	89.40 FL	*89.40 FL
27	1		*COVER RHS, HEADLAMP WASHER	Missing	89.40 FL	*89.40 FL
28	1		*ACTUATOR LHS	Cracked	254.60 FL	*254.60 FL
29	1		*ACTUATOR RHS	Not Necessary	254.60 FL	*- FL
30	2		*CLAMP, ACTUATOR	Not Necessary	34.60 FL	*- FL
31	1		*PIPE, ACTUATOR	Not Necessary	128.90 FL	*- FL
32	1		*HEADLAMP LHS	Cracked	2,357.30 FL	*2,357.30 FL
33	1		*HID CONTROL UNIT	Serviceable	940.30 FL	*- FL
34	1		*GASKET, CONTROL UNIT	Necessary	14.30 FL	*14.30 FL
35	2		*CLIP, HEADLAMP	Necessary	8.00 FL	*8.00 FL
36	1		*RIVET, HEADLAMP	Necessary	3.50 FL	*3.50 FL
37	1		*LAMP LHS, SIDE TURN	Cracked	165.20 FL	*165.20 FL
38	1		*FOGLAMP LHS	Not Necessary	369.00 FL	*- FL
39	1		*BRACKET LHS, FOGLAMP	Not Necessary	18.20 FL	*- FL
40	1		*COVER RHS, FRONT BUMPER	Serviceable	29.40 FL	*- FL
41	1		*PLATE SET, FRONT REINFORCEMENT	Torn	97.40 FL	*97.40 FL
42	4		*FASTENER, PLATE SET	Necessary	12.80 FL	*12.80 FL
43	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,397.90	6,364.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	829.79	634.43
Total Parts (\$\$)	7,568.11	5,729.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,260.00	945.00
2	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET	New	2,400.00	1,800.00
3	TO SUPPLY NUMBER PLATE	New	70.00	0.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (S\$)			4,580.00	3,045.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >