

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021334/ARS3Q2

Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900011106
Claimant Vehicle No :	SLL7417E	Insured Vehicle No :	SCX7117P
Date of Loss:	02/12/2019	Nature of Claim:	TP
		Claim No:	4847591808SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL7417E	Engine No:	2AZF044776
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR500040720
Reg. Date:	14/09/2007 (Man. Year: 2007)	Odometer:	261417 km
Colour:	Red		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Linglong 6 mm	Rear Left Side:	Linglong 6 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,486.00	5,399.75	12,086.25	69.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	2,120.00	970.00	31.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,576.00	7,519.75	13,056.25	63.45
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	20,576.00	6,000.00	14,576.00	70.84
+ Car Rental (14.0 x S\$198.00/day) (S\$)		2,772.00		
		(S\$)	8,772.00	
Liabile Amount (50.00%) (S\$)		4,386.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,393.45		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment:	04/12/2019	Best Solution Autocare Pte Ltd (HQ)
Date Inspected:	04/12/2019 Inspected At:	53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK
Estimated Period of Repair:	6.0 days	Singapore 408934

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S FRONT DOOR	Dented	1,415.00 F	*1,415.00 FL
2	1		*N/S FRONT DOOR OUTER HANDLE	Not Necessary	417.00 F	*- FL
3	2		*SET N/S FRONT DOOR HINGE	Not Necessary	160.00 F	*- FL
4	1		*N/S FRONT DOOR W/STRIP	Not Necessary	225.00 F	*- FL
5	1		*N/S SLIDING DOOR	Dented	1,485.00 F	*1,485.00 FL
6	1		*N/S SLIDING DOOR W/STRIP	Not Necessary	234.00 F	*- FL
7	1		*N/S SIDE PANEL LOWER GARNISH	Not Necessary	690.00 F	*- FL
8	1		*N/S SLIDING DOOR POWER WINDOW MOTOR & REGULATOR	Not Necessary	988.00 F	*- FL
9	1		*N/S SLIDING DOOR OUTER HANDLE	Not Necessary	210.00 F	*- FL
10	1		*N/S REAR FENDER	Repair	985.00 F	*- FL
11	1		*N/S REAR SPORT RIM	Cut	750.00 FS	*500.00 FS
12	1		*N/S REAR FENDER GLASS SEALANT	Not Necessary	80.00 F	*- FL
13	2		*N/S SLIDING DOOR HINGE	Not Necessary	450.00 F	*- FL
14	1		*N/S SLIDING DOOR AUTO DOOR MOTOR	Not Necessary	3,385.00 F	*- FL
15	1		*N/S SLIDING DOOR RAIL	Not Necessary	255.00 F	*- FL
16	1		*N/S SLIDING DOOR ROLLER	Bent	267.00 F	*267.00 FL
17	1		*N/S SLIDING DOOR LOCK ACTUATOR	Damaged	583.00 F	*583.00 FL
18	1		*N/S FRONT DOOR LOWER GARNISH	Cut	987.00 F	*465.00 FL
19	1		*SET N/S FRONT DOOR LOWER GARNISH CLIP	Necessary	40.00 F	*40.00 FL
20	1		*N/S REAR SLIDING DOOR LOWER GARNISH	Cut	987.00 F	*485.00 FL
21	1		*SET N/S REAR SLIDING DOOR LOWER GARNISH CLIP	Necessary	40.00 F	*40.00 FL
22	1		*N/S REAR FENDER LOWER GARNISH	Cut	297.00 F	*297.00 FL
23	1		*SET N/S REAR FENDER LOWER GARNISH CLIP	Necessary	40.00 F	*40.00 FL
24	1		*N/S REAR BUMPER RETAINER	Necessary	98.00 F	*56.00 FL
25	1		*N/S SLIDING DOOR SENSOR	Damaged	675.00 F	*675.00 FL
26	1		*N/S REAR SHOCK ABSORBER	Not Necessary	275.00 F	*- FL
27	1		*REAR BUMPER	Torn	685.00 F	*685.00 FL
28	1		*N/S REAR WHEEL HUB BEARING	Not Necessary	783.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,486.00	7,033.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,633.25
Total Parts (\$\$)	17,486.00	5,399.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,PANEL BEAT ,REPAIR	New	1,200.00	900.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	900.00
3	ANTI RUST	New	50.00	50.00
4	TRANSFER DOOR FITTINGS	New	300.00	160.00
5	REMOVE & REFIX REAR FENDER GLASS	New	250.00	0.00
6	WIRING CHECK	New	50.00	30.00
7	REMOVE & REFIX FUEL TANK	New	120.00	0.00
8	REAR WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (S\$)			3,090.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >