



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 8940R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID (CONSISTENT)	BENT	1,259.30	1,125.10
1	REAR BOOT LID LOCK (CONSISTENT)	DENTED	183.40	183.40
1	REAR BOOT EMBLEM LOGO (CONSISTENT)	NECESSARY	67.40	67.40
1	REAR BOOT INNER TRIM (CONSISTENT)	SERVICEABLE	548.30	-
1	REAR BOOT WEATHERSTRIP (CONSISTENT)	SERVICEABLE	353.90	-
1	REAR BUMPER (CONSISTENT)	MTG CRACKED	528.90	497.60
1	REAR BUMPER SPONGE (CONSISTENT)	SERVICEABLE	183.20	-
2	REAR BUMPER SIDE RETAINER @\$48.50 (CONSISTENT)	SERVICEABLE	97.00	-
1	REAR BUMPER REFLECTOR (CONSISTENT)	SCRATCHED	93.80	93.80
1	REAR BUMPER TOP (CONSISTENT)	DENTED / CUT	461.20	280.70
1	REAR WINDSCREEN GLASS MOULDING (CONSISTENT)	NECESSARY	176.90	176.90
1	REAR END PANEL GARNISH (CONSISTENT)	MTG CRACKED	318.40	195.20
1	REAR KEY LOCK SENSOR RECEIVER (CONSISTENT)	CRACKED	377.60	155.20
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	470.50	-
LESS 25% DISCOUNT			-1,279.95	-693.83
			3,839.85	2,081.47
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	250.00	200.00
1	SET WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	SET WINDSCREEN SEAL (SN) (CONSISTENT)	NECESSARY	80.00	30.00
			410.00	270.00
<b><u>LABOUR</u></b>				
TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS.			800.00	500.00
TO CHECK WIRING SYSTEM.			50.00	15.00
TO APPLY RUST PROOFING ON AFFECTED AREAS.			80.00	30.00
TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS.		NOT NECESSARY	80.00	-
TO SPRAY PAINTING ON AFFECTED AREAS.			800.00	600.00

Report Ref No. CC4/ASM19021337/Kga3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO INSTALL REVERSE SENSORS & REVERSE CAMERA.	NOT NECESSARY	50.00	50.00
	TO REMOVE CARPET ,TRIMMING AND SEATS TO ENABLE REPAIR.		60.00	-
	TO REMOVE REAR WINDSCREEN GLASS TO ENABLE REPAIR.		120.00	120.00
	TO TRANSFER BOOT LID ACCESSORIES.		80.00	60.00
			2,120.00	1,375.00
<b>GRAND TOTAL</b>			<b>6,369.85</b>	<b>3,726.47</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,900.00</b>

Report Ref No. CC4/ASM19021337/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.