

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19021369/GKA3Q2  
**Date:** 14/08/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900108995  
**Claimant**  
**Vehicle No :** SHC7266T **Insured Vehicle No :** SMK8822E  
 Date of Loss: 01/12/2019 Nature of Claim: TP Claim No: 7205752435SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC7266T**  
 Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A) Engine No: G4LEKU298642  
 Reg. Date: 10/07/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU164787  
 Colour: Yellow Odometer: 0 km  
 Engine Capacity: 1580 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,663.98	1,029.90	634.08	38.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	740.00	210.00	22.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,613.98</b>	<b>1,769.90</b>	<b>844.08</b>	<b>32.29</b>
<b>+ GST 7.00/7.00% (S\$)</b>	182.98	123.89	59.09	32.29
<b>Nett Amount (S\$)</b>	<b>2,796.96</b>	<b>1,893.79</b>	<b>903.17</b>	<b>32.29</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$125.19/day) (S\$)</b>		375.57		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>2,426.85</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,426.00</b>		

#### INSPECTION

Date of Assignment: 02/12/2019  
 Date Inspected: 03/12/2019 Inspected At: ComfortDelGro Engineering Pte Ltd  
 (Loyang)  
 59 Loyang Drive  
 Singapore 508969

Estimated Period of Repair: 2.0 days

---

**Adjuster:** XING GUO QIANG**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
3	1		*REAR BUMPER LOER CENTRE MOLDING ASSY	Not Necessary	270.10 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT STAY -RH	Not Necessary	138.10 FL	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REAR BUMPER UNDER CENTRE	Deformed	53.85 FL	*53.85 FL
8	1		*REAR BUMPER SIDE UNDER -RH	Not Necessary	27.50 FL	*- FL
9	1		*REAR BUMPER REFLECTOR -RH	Not Necessary	31.90 FL	*- FL
10	1		*REAR LICENSE LAMP -RH	Not Necessary	30.20 FL	*- FL
11	1		*REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
12	1		*REAR NUMBER PLATE	Missing	25.00 FS	*25.00 FS
13	1		*REAR NUMBER PLATE CASING	Missing	30.00 FS	*30.00 FS
14	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,019.80</b>	<b>1,227.20</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	355.82	197.30
<b>Total Parts (\$\$)</b>	<b>1,663.98</b>	<b>1,029.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	320.00	320.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	WIRING CHARGE	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	40.00
5	COMPUTER PROGRAMMING FOR BSD	New	250.00	180.00
			<b>Gross Labour Cost (\$\$)</b>	<b>740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >