1/8/2020 Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG19021373/AVD3S2

AIG Building, 78 Shenton Way #08-16
Singapore 079120

Date: 08/01/2020

**REFERENCE** 

Insured/Claimant: KHIU SHEN WOO JOSHUA Policy No: 1700076736

Date of Loss: 01/12/2019 Nature of Claim: OD Claim No: 5985555620SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLU348U

Make & Model: AUDI A6, 1.8 TFSI S-tronic (A) Engine No: CYG020784

Reg. Date: 20/11/2017 (Man. Year: 2017) Chassis No: WAUZZZ4G8HN129401

Colour: Silver Odometer: 49384 km

Engine Capacity: 1798 cc
Market Value/New Car Price: \$\$142,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	0.00	0.00	0.00	
	- Excess (S\$)	800.00	800.00	0.00	0.00
	Nett Amount (S\$)	-800.00	-800.00	0.00	0.00

INSPECTION

Date of Assignment: 04/12/2019

Date Inspected: 03/12/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### TOTAL LOSS ASPECT

New Car Value : \$222,000.00 Market Value : \$142,000.00 OMV : \$40,459.00 PARF Rebate (1) : \$32,732.00 \$57,414.00 Quota Premium Paid: COE Rebate (2) : \$45,691.00 Total Rebate (1) + (2) = : \$78,423.00

The total amount incurred will be Market Value \$142,000.00 minus Total Rebate \$78,423.00 = \$63,577.00 before excess.

The total amount incurred will be New Car Value \$222,000.00 minus Total Rebate \$78,423.00 = \$143,577.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## **REPAIR DETAILS**

# **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

1/8/2020

Report was unsubmitted during this print-out.

< END OF ESTIMATES >