



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19021380/Kyd3e2

73 BRAS BASAH ROAD

Date: 30-06-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : CHESTER CHONG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | SKZ 1109Y | Veh. Inspected | SGJ 1214H |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1073749-002 | Excess (\$) | 0.00 |
| Assign From | ANNIE KOH | Assign Date | 04/12/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|--------------------|
| Make & Model | TOYOTA VIOS (A) | c.c | 1497 |
| Engine No. | HIDDEN | Year of Reg. | 2006 |
| Chassis No. | MR053HY4204192606 | Colour | METALLIC RED |
| Odometer | 319244 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|-------|---------|
| R/H Front Tyre | 175/65 R14 | APLUS | 8 mm |
| L/H Front Tyre | 175/65 R14 | APLUS | 8 mm |
| R/H Rear Tyre | 175/65 R14 | APLUS | 7 mm |
| L/H Rear Tyre | 175/65 R14 | APLUS | 7 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|----------------|--|---------------------|-------------------------|
| Accident Date | 30/11/2019 | Inspect Date / Time | 04/12/2019 (10:37 AM) |
| Survey held at | H C AUTO PTE LTD 160 SIN MING DRIVE #05-09 SIN MING AUTOCITY SINGAPORE 575722 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 12 Working Days |
|-------------------------------------|-----------------|