

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG19021387/USD3E2

Date: 08/05/2020

REFERENCE

Insured/Claimant:	WONG SIEW PENG	Policy No:	2100504536	
Date of Loss:	02/12/2019	Nature of Claim:	OD	Claim No: 2385465305SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM1085M		
Make & Model:	MAZDA MAZDA5, 2.0 5-DOOR WAGON 2.0L SP.6EAT SUNR (A)	Engine No:	PE10468041
Reg. Date:	21/03/2017 (Man. Year: 2017)	Chassis No:	JM6CW1071H0125416
Colour:	White	Odometer:	24898 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,098.59	1,537.29	2,561.30	62.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,880.00	3,030.00	4,850.00	61.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,978.59	4,567.29	7,411.30	61.87
+ GST 7.00/7.00% (S\$)	838.50	319.71	518.79	61.87
Nett Amount (S\$)	12,817.09	4,887.00	7,930.09	61.87

INSPECTION

Date of Assignment:	04/12/2019		
Date Inspected:	04/12/2019	Inspected At:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	961.20 FL	*961.20 FL
2	1		*REAR REINFORCEMENT	Serviceable	155.40 FL	*- FL
3	4		*GROMMET REAR BUMPER	Necessary	10.80 FL	*10.80 FL
4	2		*GROMMET	Necessary	9.40 FL	*9.40 FL
5	2		*FASTENER, REAR BUMPER	Necessary	6.00 FL	*6.00 FL
6	2		*FASTENER, REAR BUMPER	Necessary	6.40 FL	*6.40 FL
7	4		*RIVET, REAR BUMPER	Necessary	22.80 FL	*22.80 FL
8	2		*TAPE PROTECTOR, REAR BUMPER	Necessary	7.00 FL	*7.00 FL
9	1		*TAILGATE	Repair	1,637.00 FL	*- FL
10	2		*VALVE ONEWAY, TAILGATE	Not Necessary	24.00 FL	*- FL
11	5		*FASTENER, TRIM	Necessary	15.00 FL	*15.00 FL
12	1		*LOCK, TAILGATE	Not Necessary	256.20 FL	*- FL
13	1		*STRIKER, LOCK	Not Necessary	57.90 FL	*- FL
14	3		*CLIP, FINISHER	Necessary	17.10 FL	*17.10 FL
15	1		*ORNAMENT, MAZDA	Necessary	45.30 FL	*45.30 FL
16	1		*ORNAMENT, 5	Necessary	36.30 FL	*36.30 FL
17	1		*ORNAMENT, SKYACTIVE	Necessary	80.00 FL	*80.00 FL
18	1		*REAR WINDSCREEN MOULDING	Not Necessary	60.50 FL	*- FL
19	6		*FASTENER, REAR WINDSCREEN	Not Necessary	16.80 FL	*- FL
20	1		*SPACER, REAR WINDSCREEN	Not Necessary	7.20 FL	*- FL
21	2		*FASTENER, REAR WINDSCREEN	Not Necessary	16.40 FL	*- FL
22	4		*SPACER, REAR WINDSCREEN	Not Necessary	51.20 FL	*- FL
23	2		*PIN STUD, REAR WINDSCREEN	Not Necessary	29.40 FL	*- FL
24	2		*PROTECTOR, SPOILER	Not Necessary	11.00 FL	*- FL
25	2		*PROTECTOR, SPOILER	Not Necessary	28.20 FL	*- FL
26	2		*PROTECTOR, SPOILER	Not Necessary	24.00 FL	*- FL
27	3		*CLIP, SPOILER	Not Necessary	23.10 FL	*- FL
28	1		*CLIP, SPOILER	Not Necessary	8.70 FL	*- FL
29	1		*GASKET LHS, TAILGATE	Necessary	95.40 FL	*95.40 FL
30	1		*GASKET RHS, TAILGATE	Necessary	95.40 FL	*95.40 FL
31	1		*REVERSE SENSOR	Shorted	315.00 FS	*180.00 FS
32	1		*REVERSE CAMERA	Not Necessary	180.00 FS	*- FS
33	1		*NUMBER PLATE	Scratched	70.00 FS	*70.00 FS
34	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,480.10	1,678.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	381.51	140.81
Total Parts (\$\$)	4,098.59	1,537.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT	New	1,890.00	1,260.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE	New	2,400.00	1,200.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	560.00	0.00
4	TO SUPPLY SEALER ON THE WINDSCREEN GLASS	New	120.00	0.00
5	TO TRANSFER TAILGATE MECHANISM	New	315.00	0.00
6	TO REMOVE AND INSTALL SPOILER TAILGATE	New	180.00	0.00
7	TO BREAK AND RESEAL VEHICLE WEEKEND NUMBER PLATE LTA REGISTRATION FEE	New	150.00	150.00
8	TO SEND THE CAR TO INSPECTION CENTRE FOR THE INSTALLATION OF THE WEEKEND NUMBER PLATE	New	120.00	120.00
9	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	945.00	0.00
10	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	New	350.00	0.00
11	TO CARRY-OUT CAVITY PRESERVATION	New	250.00	0.00
12	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
13	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (S\$)			7,880.00	3,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >