



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/ASM19018274/Fgb3s2-1

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 17-12-2019



ATTN: DANIEL PAY

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SKR 4675B	Veh. Inspected	SKC 3612T
Policy No.	VPA/P2037317	Coverage (\$)	0.00
Claim No.	S9M023BW	Excess (\$)	0.00
Assign From	DANIEL PAY	Assign Date	04/12/2019

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET CRUZE	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KL1JA69E9CK542596	Colour	WHITE
Odometer	161614	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	DUNLOP	6 mm
L/H Front Tyre	225/40 R18	DUNLOP	6 mm
R/H Rear Tyre	225/40 R18	DUNLOP	6 mm
L/H Rear Tyre	225/40 R18	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.
--

5. General Information

Accident Date	09/10/2019	Inspection Date	06/12/2019
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------