

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III19021416/AGA3Q2

**Date:** 26/06/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SJW1999Y	<b>Insured Vehicle No :</b>	SHD3254Z
Date of Loss: 01/12/2019	Nature of Claim: TP	Claim No: MCT19120006

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJW1999Y</b>	
Make & Model:	MAZDA 3, 1.6 (A)	Engine No: Z6851317
Reg. Date:	25/01/2010 (Man. Year: 2009)	Chassis No: JM6BL10Z1A0141721
Colour:	Silver	Odometer: 113777 km
Engine Capacity:	1598 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,427.40	2,718.08	1,709.32	38.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,600.00	1,380.00	46.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,407.40</b>	<b>4,318.08</b>	<b>3,089.32</b>	<b>41.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,407.40</b>	<b>2,000.00</b>	<b>5,407.40</b>	<b>73.00</b>
<b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b>		250.00		
<b>Nett Liability (S\$)</b>		<b>2,250.00</b>		

### INSPECTION

Date of Assignment:	03/12/2019	
Date Inspected:	03/12/2019 Inspected At:	Flying High Spray Painting (HQ) BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
<b>Parts:</b>	144	MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJW1999Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	1		*REAR BUMPER	Deformed	1,049.00 F	*1,049.00 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
5	2		*REAR BUMPER SIDE HOLDER	Not Necessary	74.00 F	*- FL
6	1		*REAR BUMPER REFLECTOR	O/S Cracked	118.40 F	*59.20 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	529.60 F	*529.60 FL
8	1		*REAR BUMPER TOW COVER	Not Necessary	22.00 F	*- FL
9	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
10	1		*REAR END PANEL	Repair	529.00 F	*- FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	203.00 F	*- FL
12	1		*TAILGATE	Dented	933.10 F	*933.10 FL
13	1		*TAILGATE LOCK	Damaged	202.60 F	*202.60 FL
14	1		*TAILGATE WEATHERSTRIPE	Not Necessary	142.60 F	*- FL
15	1		*TAILGATE GLASS MOULDING	Necessary	108.00 F	*108.00 FL
16	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
17	1		*MAZDA LOGO	Necessary	29.20 F	*29.20 FL
18	1		*MAZDA 3 WORDING	Necessary	56.90 F	*56.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,427.40</b>	<b>3,317.60</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	599.52
<b>Total Parts (\$\$)</b>	<b>4,427.40</b>	<b>2,718.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO UNDERSEAL	New	150.00	60.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,980.00</b>	<b>1,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >