Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19021420/APA3Q2

Date: 06/08/2020

REFERENCE

MCOM0015 Handling Insurer: India International Insurance Pte Ltd Policy No: Claimant **SLR1815Y** Insured Vehicle No: SHB4023C

Vehicle No:

Date of Loss: ΤP 30/11/2019 Nature of Claim: Claim No: MCT19110818

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLR1815Y Reg No:

Make & Model: HONDA VEZEL, 1.5 X HYBRID CVT (A) Engine No: LEB5923588 Reg. Date: 01/08/2017 (Man. Year: 2016) Chassis No: RU31223574 Colour: Odometer: 199056 km Silver

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 215/60 R16 Rear Tyre Size: Rear Left Side: Front Left Side: Habilead 6 mm Habilead 6 mm Rear Right Side: Front Right Side: Habilead 6 mm Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,010.96	895.76	115.20	11.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	940.00	680.00	260.00	27.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,950.96	1,575.76	375.20	19.23
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	1,950.96	1,200.00	750.96	38.49
+ GST 7.00/7.00% (S\$)	136.57	84.00	52.57	38.49
Nett Amount (S\$)	2,087.53	1,284.00	803.53	38.49
Global Sum S	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 04/12/2019

Date Inspected: 04/12/2019 Inspected At: N-51 Automotive Pte Ltd (HQ)

BLK 2 KAKI BUKIT, #01-17/18 KAKI

BUKIT AUTOHUB Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference			
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2020)	
Parts:	M1-SUV	HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	e: (Unsubmitted, no print-code for SLR1815Y)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented	1,080.50 FL	*1,080.50 FL
2	1		*FRONT RH DOOR BLACK TAPE	Necessary	39.20 FL	*39.20 FL
3	1		*FRONT RH DOOR HINGE LOWER	Not Necessary	55.00 FL	*-FL
4	1		*FRONT RH DOOR WEATHERSTRIP (LOWER)	Not Necessary	89.00 FL	*- FL
F=Fra	anchise	part. L=Listl	temDisc List Item Discount on L Items 20.	Sub Total (S\$) 00/20.00% (S\$)	1,263.70 252.74	1,119.70 223.94
			,	Total Parts (S\$)	1,010.96	895.76
			Report was unsubmitted during this p	rint out		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO TRANSFER DOOR GLASS ,REGULATOR GEAT ,MOTOR ,RAILING CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	80.00	80.00
2	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	500.00	400.00
3	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THI ABOVE DAMAGED BODYPARTS ,REPAIR ,RE- CONSTRUCT AND RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	E New	300.00	200.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	60.00	0.00
	Gross Labor	940.00	680.00	
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >