

INS. CASE OWNER:

CC3 / CTI19021432, Kesh

LKK:
IDAC:

Surveyor:

Kinnetu

DOI:

ASSIGNMENT

4/11/19

Date / Time:

4/11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

YP8429P

Claim No. :

Name of Insured :

NG NAM BEE MARKETING PTE LTD

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :S\$

D.O.A :

29/11/19

Place of Accident :

Is driver the owner? (YES)

(NO)

Nature of Accident :

If NO, Driver Name / Age : YU JUNTAO

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Insured Liability :

%

Final ? Yes / No

SHC 5533K



INSRS:
WSP:
Tel:
Liability:
RMKS:

Trans
Cnh



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SHC 5533K - C YP8429P - C

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

29/11/19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by: WSK

FINALIZATION

Date/Time:

Confirm with:

Confirm by: WSK

Repair Cost:

45 S\$ 650.00

(1 days) Reduction:

98 %

Email

Call

FINAL SETTLEMENT

Date/Time: 21-02-20

Confirm with: JPM/MSH

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 15

If NO or B 28, Ass. Lia :

Repair Cost:

0/167 S\$ 695.50

DID CHANGED WASTE HIN TP

Loss of Rental (LOR):

S\$ 324.50

(4 days) x 81.13

Loss of Use (LOU):

S\$ -

(3 x days)

Loss of Income (LOI):

S\$ 200.00

(S\$0 x 4 days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$ 7.99

Medical:

S\$ -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

S\$ -

(e.g. Tow/ Independent)

2) Report Format:

TP

Legal Cost:

S\$ -

3) Survey fee:

400

Total:

S\$ 1,221.51

Global Sum S\$:

FINAL PAYMENT

Date/Time: 21-02-20

Confirm with: JPM/MSH

Email

Call

Payee 1:

S\$ 1,221.51

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
9/3/2020

ASS. REC. BY:

REF:

C72/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HG 5533K Yr Regn: 08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c. 1995

Colour:

M. White/Red AC: Insured / Std / NI / NA

Sp. Reading

614 P67 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 278875

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Data/Time, File Pass to?



: Prell. Report

1)

Data/Time, File Return to?



: Final Report

2)

Report Format :

Lump Sum / L.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fuel

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI19021432/Keb3

Date: 04.12.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC5533K

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04.12.2019 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	38,270.33
Revised Estimate Amount	: S\$	650.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 1 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5533K**AAD1912-001***Not Notarized*
6/1 Sep 8 6501

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

03 DEC 2019

SHC 5533K

VF1ABL15AUC278875

RENAULT

LATITUDE

29.11.19

CHINA TAIPING

15/8/2014

PART		LIST	
1	BUMPER COVER FRT	\$	747.20
1	BUMPER SPOILER FRT	\$	344.70
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT LH	\$	101.40
1	BUMPER SUPPORT FRT	\$	10.70
1	BUMPER UNDERTRAY FRT	\$	292.50
1	BUMPER GRILLE LOWER FRT	\$	147.00
1	BUMPER FOG LAMP GRILLE LH	\$	207.21
1	BUMPER BEAM FRT	\$	663.70
1	HEADLAMP LH	\$	743.60
1	HEADLAMP PANEL FRT LH	\$	127.70
1	FENDER PANEL FRT LH	\$	414.40
1	WHEELARCH FRT LH	\$	112.30
1	FENDER BRACKET FRT LH	\$	38.90
1	FENDER BRACKET LOWER LH	\$	11.80
1	FENDER INSULATOR LH	\$	65.50
1	FENDER BRACKET FRT LH	\$	38.90
1	FRONT BRACE PANEL	\$	177.22
1	BONNET	\$	1,312.70
1	BONNET INSULATOR	\$	294.30
1	BONNET STRUT LH	\$	53.30
1	BONNET STRUT RH	\$	53.30
1	BONNET HINGE LH	\$	236.50
1	BONNET HINGE RH	\$	237.40
1	BONNET LOCK	\$	152.80
1	BONNET CABLE	\$	55.20
1	BONNET CABLE COVER	\$	80.60

Sum
X

Trans-cab Auto Services Pte Ltd

AAD1912-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5533K

1	BONNET SEAL OUTER	\$	83.20	} <i>SHC X</i>
1	BONNET SEAL INNER	\$	70.10	
1	RADIATOR GRILLE	\$	969.90	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36	
1	RADIATOR GRILLE FRAME	\$	686.00	
1	FRAME FULL SUPPORT PANEL	\$	592.70	
1	FRAME FULL SUPPORT BRACKET	\$	41.60	
1	AIR CLEANER BOX	\$	464.20	
1	AIR CLEANER HOSE	\$	175.85	
1	AIR CLEANER LOWER	\$	271.26	
1	DOOR PANEL FRT LH	\$	2,844.66	} <i>SHC X</i>
1	DOOR MIRROR ASSY LH	\$	727.90	
1	DOOR MIRROR GLASS LH L70Y	\$	151.70	} <i>B.S.</i>
1	DOOR MIRROR BACK COVER LH L70Y	\$	128.70	
1	DOOR MIRROR LAMP LH	\$	134.10	} <i>SHC X</i>
1	DOOR HARNESS WIRE LH	\$	<i>SHC</i> 2,670.00	
1	ROCKER PANEL INNER GARNISH LH	\$	<i>SHC</i> 466.51	} <i>X</i>
1	ROCKER PANEL INNER LH	\$	<i>SHC</i> 1,024.79	
1	ROCKER PANEL OUTER LH	\$	<i>SHC</i> 1,184.99	
1	ROCKER PANEL CENTER LH	\$	<i>SHC</i> 990.25	
1	LOWER ARM LH L70Y	\$	<i>SHC</i> 192.70	
1	KNUCKLE ARM LH L70Y	\$	<i>SHC</i> 481.50	
1	ABSORBER FRT LH L70Y	\$	<i>SHC</i> 274.10	
1	DRIVESHAFT LH	\$	<i>SHC</i> 1,355.70	
1	STABILIZER BAR FRT	\$	<i>SHC</i> 427.90	
TOTAL		\$	23,751.18	
10%		\$	2,375.12	
		\$	21,376.06	

Special Nett

1	BUMPER CLIP FRT	\$	<i>SHC</i> 66.00	} <i>X</i>
1	BUMPER BRACKET CLIP FRT LH	\$	<i>SHC</i> 12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>SHC</i> 10.50	
1	BUMPER GRILLE LOWER CLIP	\$	<i>SHC</i> 69.00	
1	WHEELARCH CLIP FRT LH	\$	<i>SHC</i> 30.50	
1	FRAME FULL SUPPORT PANEL CLIP	\$	<i>SHC</i> 70.00	

Trans-cab Auto Services Pte Ltd**AAD1912-001**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5533K

1SET	FRAME FULL SUPPORT PANEL NUT	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00
1SET	RADIATOR GRILLE SCREW	\$	16.00
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00
1	FRONT LEFT TYRE	\$	300.00
1	FRONT LEFT TYRE RIM	\$	380.00
1SET	Front licence plate with holder	\$	80.00
1	WINDSCREEN SEALANT	\$	253.80
1	FRONT WINDSCREEN MOULDING	\$	120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00
6	BONNET INSULATOR CLIP L70Y	\$	7.30
2	BONNET CABLE CLIP L70Y	\$	6.31
2	BONNET CABLE COVER SCREW L70Y	\$	10.85
1	FRONT DOOR STICKER 'Trans-Cab'	\$	80.00
1	FRONT DOOR STICKER 'Classic'	\$	80.00
TOTAL		\$	1,794.27

~
X

TOTAL PARTS \$ 23,170.33

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 *60k*

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ ~ 170.00 X

To transfer of front fender fittings, attachment and perform water seepage test.

\$ ~ 170.00 X

To transfer of front windscreen glass to facilitate bodywork repair.

\$ ~ 170.00 X

To check steering geometry and computer wheel alignment

\$ ~ 220.00 X

Trans-cab Auto Services Pte Ltd**AAD1912-001**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5533K

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	601
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↪ 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	↪ 170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	↪ 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To rust-proofing of the affected areas.	\$	↪ 170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	↪ 380.00	X

TOTAL \$ 15,100.00**Over All Total \$ 38,270.33****LUMP SUM (REPAIR DAY)****20 days****1 day**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	5HC5533K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Dec 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001843
Chassis No.:	VF1ABL15AUC278875
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	15 Aug 2014
First Registration Date:	15 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2022
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	14 Aug 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,088.00
COE Rebate Amount:	\$16,897.00
Total Rebate Amount:	\$25,645.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Dec 2019

OK

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19021432/Kea3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 19-03-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 8429P	Veh. Inspected	SHC 5533K
Policy No.	DMCVSN1937091900	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/12/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278875	Colour	METALLIC WHITE / RED
Odometer	614967	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	SAILUN	9 mm
L/H Front Tyre	215/60 R16	SAILUN	9 mm
R/H Rear Tyre	215/60 R16	SAILUN	9 mm
L/H Rear Tyre	215/60 R16	SAILUN	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S DOOR MIRROR.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/11/2019	Inspection Date	03/12/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5533K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	SERVICEABLE	747.20	-
1	BUMPER SPOILER FRT	SERVICEABLE	344.70	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	101.40	-
1	BUMPER SUPPORT FRT	SMASHED	10.70	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	292.50	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	147.00	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	SERVICEABLE	663.70	-
1	HEADLAMP LH	SERVICEABLE	743.60	-
1	HEADLAMP PANEL FRT LH	SERVICEABLE	127.70	-
1	FENDER PANEL FRT LH	SERVICEABLE	414.40	-
1	WHEELARCH FRT LH	SERVICEABLE	112.30	-
1	FENDER BRACKET FRT LH	SERVICEABLE	38.90	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	11.80	-
1	FENDER INSULATOR LH	SERVICEABLE	65.50	-
1	FENDER BRACKET FRT LH	SERVICEABLE	38.90	-
1	FRONT BRACE PANEL	SERVICEABLE	177.22	-
1	BONNET	SERVICEABLE	1,312.70	-
1	BONNET INSULATOR	SERVICEABLE	294.30	-
1	BONNET STRUT LH	SERVICEABLE	53.30	-
1	BONNET STRUT RH	SERVICEABLE	53.30	-
1	BONNET HINGE LH	SERVICEABLE	236.50	-
1	BONNET HINGE RH	SERVICEABLE	237.40	-
1	BONNET LOCK	SERVICEABLE	152.80	-
1	BONNET CABLE	SERVICEABLE	55.20	-
1	BONNET CABLE COVER	SERVICEABLE	80.60	-
1	BONNET SEAL OUTER	SERVICEABLE	83.20	-
1	BONNET SEAL INNER	SERVICEABLE	70.10	-
1	RADIATOR GRILLE	SERVICEABLE	969.90	-
1	RADIATOR GRILLE BADGE 'RENAULT'	SERVICEABLE	225.36	-

Report Ref No. CC3/CT119021432/Kea3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR GRILLE FRAME	SERVICEABLE	686.00	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	592.70	-
1	FRAME FULL SUPPORT BRACKET	SERVICEABLE	41.60	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	DOOR PANEL FRT LH	SERVICEABLE	2,844.66	-
1	DOOR MIRROR ASSY LH }	BROKEN	727.90	727.90
1	DOOR MIRROR GLASS LH L70Y }	BROKEN	151.70	-
1	DOOR MIRROR BACK COVER LH L70Y }	BROKEN	128.70	-
1	DOOR MIRROR LAMP LH }	BROKEN	134.10	-
1	DOOR CHASSIS WIRE LH	SERVICEABLE	2,670.00	-
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	1,184.99	-
1	ROCKER PANEL CENTER LH	TO REPAIR SEE LABOUR	990.25	-
1	LOWER ARM LH L70Y	SERVICEABLE	192.70	-
1	KNUCKLE ARM LH L70Y	SERVICEABLE	481.50	-
1	ABSORBER FRT LH L70Y	SERVICEABLE	274.10	-
1	DRIVESHAFT LH	TO REPAIR SEE LABOUR	1,355.70	-
1	STABILIZER BAR FRT	SERVICEABLE	427.90	-
	LESS 10% DISCOUNT		-2,375.12	-72.79
			21,376.06	655.11
	SPECIAL NETT ITEMS			
1	BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-

Report Ref No. CC3/CTI19021432/Kea3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	FRONT LEFT TYRE (SN)	NOT NECESSARY	300.00	-
1	FRONT LEFT TYRE RIM (SN)	NOT NECESSARY	380.00	-
1	SET FRONT LICENCE PLATE HOLDER (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN)	NOT NECESSARY	10.85	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER 'CLASSIC' (SN)	NOT NECESSARY	80.00	-
			1,794.26	-
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF ROCKER PANEL INNER LH,ROCKER PANEL OUTER LH,ROCKER PANEL CENTER LH AND DRIVESHAFT LH.		6,000.00	60.00
	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR .	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-

Report Ref No. CC3/CT119021432/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		6,000.00	60.00
	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			15,100.00	140.00
GRAND TOTAL			38,270.32	795.11
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				650.00

Report Ref No. CC3/CTI19021432/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.