

23/03/2001

ASS. REC. BY:

REF: CS/PCI 19021433/ Kyf3⁰²

Special Instruction:

Survivor:

Kenny

ASSIGNMENT (Office)

From (Person):

May Chun

of

PCI

Date/Time:

4.12.19 2.08pm

Estimated Cost:

Bill to:

OI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 4607T

Insured:

SHC 8390K

at Workshop m/s

A7 Auto Consultant

Tel:

83868989

of

BIC 113 Teck Uy Loong # 05-660

Policy No:

Claim No:

D19007616 MP5H

Sum Insured:

Excess:

Make of Veh:

D.O.A

30.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

4.12.19 3.38pm

Person Contacted:

Alan

H.O.D. Endorsement:

Vehicle: IN OUT

Date/Time

Action/Instruction (✓) Estimate

PC 4607T - X

SHC 8390K - CS/PCI 13022417/bqcl3u2

Run = 10/12/2019

21/11 11.15am @ 4800 - email & confirm Alan
(Red \$6706.75, 58%)

REF: FCI

ASSIGNMENT

From:

Date: 20.12.2019

Veh No:

PC 4607T

Vr Regn:

04 06

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

PC 4607T

Make:

Toy Hiac

C.C:

2494

at Workshop m/s:

AT Auto consultant

Colour:

Multi Colour

A/C: Insured / Std / NI / NA

of

Blk 7 on my 401-82

Sp. Reading:

826765

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

KDH 200 - 0011671

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

83868989 Alan

Modl: Nil / S/Rim / STD A/Rim or

(Policy Condition)


Tyre Size:

F:

195R15 X8

R:

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

814/c

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Black lion

IDAC Accident Report:

Consistent? : Yes or No

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

9

mm

L/Bal.

9

mm

Est. Repairs:

04 days

Res: Yes or No

D.O.A:

30/11/19

D.O.I:

20/12/19

Lum Dam:

20 %

3 Val: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

sup

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

Date:

4/21

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/1/20

Prel sent email to Insurance

MV = \$14000/-
 LTA = \$5539/-
 Net = \$8461/-

RECEIVED 22 JAN 2020

Date/Time, File Pass to:



Prof. Report

Days Of Repair:

4

1)



Final Report

Resurvey No. of Trip:

2

Date/Time, File Return to:

2)

22/1/Typist

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

3 + 15 = 18

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.I. (\$)

\$4800/-

170 + 15

50

50

31

316



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D19007616MFSH
Our Ref: CS/FCI19021433/Kyf3

Date: 13 Jan 2020

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. PC4607T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/12/2019 at the premises of M/s AT AUTO CONSULTANT, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,732.50</u>
Revised Estimate Amount	: S\$ <u>2,126.20</u>
"Check" Items Amount	: S\$ <u>3,567.75</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front portion.



Yours faithfully

Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	02-12-2019	Our Ref No. D19007616MFSH
Accident Date	30-11-2019	Claim Type. Third Party
Insured Vehicle	SHC8390K	Third Party Vehicle. PC4607T
Survey Location	BLK 113 Teck Whye Lane #05-650	
Contact Person.	MR ALAN TAN	
Contact No.	83868989/ 83868989	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	A T AUTO CONSULTANT	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Monday, January 13, 2020 11:25 AM
To: 'CWS Motor Claims'
Cc: 'May Chua'
Subject: RE: SURVEY ASSESSMENT - D19007616MFSH/1
Attachments: PC4607T DOA 30112019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle PC4607T
Date of survey : 30/11/2019
Number of days : 4 days
Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, December 04, 2019 3:37 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'May Chua' <maychua@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007616MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	406R
Vehicle Details	
Vehicle No.:	PC4607T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 2.5 M
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	2KD1434254
Chassis No.:	KDH2000041671
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	10 Apr 2006
First Registration Date:	10 Apr 2006
Transfer Count:	2
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Apr 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,831.00
COE Rebate Amount:	\$5,539.00
Total Rebate Amount:	\$5,539.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 23 Jan 2020

OK

Page 1 of 1

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 Email:atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 19.12.2019
Vehicle No: PC4607T
Owner: SIN U LIAN TRAVEL & COACH PTE LTD
Date of Accident: 30.11.2019
Make & Model: TOYOTA HIACE COMMUTER GL 2.5M
Chassis No : KDH2000041671

SUPPLEMENTARY ESTIMATE FOR ACCIDENT VEHICLE NO PC4607T

PARTS

1	1	Condensor	1216.
2	1	Radiator spare tank	286.30

SUB TOTAL
LESS 25%
DISCOUNTED SUB TOTAL

1216.	\$1,523.00	✓
286.30	\$536.00	✓
	<u>\$2,059.00</u>	
	<u>\$514.75</u>	
	<u>\$1,544.25</u>	

S. NETT ITEM

1	1	Aircon gas top up
---	---	-------------------

SUB TOTAL
LESS 0 %
DISCOUNTED SUB TOTAL

1	\$80.00	X
	<u>\$80.00</u>	
	<u>\$0.00</u>	
	<u>\$80.00</u>	

LABOUR

1	1	Pressure leakage test for aircon
---	---	----------------------------------

SUB TOTAL (LABOUR)

	<u>\$150.00</u>	100%
	<u>\$150.00</u>	

SUB TOTAL (PARTS) \$1,544.25

S. NETT (PARTS) \$80.00

SUB TOTAL (LABOUR) \$150.00

ESTIMATED GRAND TOTAL \$1,774.25



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19021433/Kyf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-01-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8390K	Veh. Inspected	PC 4607T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007616MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	04/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	KDH2000041671	Colour	MULTI	
Odometer	826765	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BLACKLION	9 mm	
L/H Front Tyre	195 R15X8	BLACKLION	9 mm	
R/H Rear Tyre	195 R15X8	BLACKLION	9 mm	
L/H Rear Tyre	195 R15X8	BLACKLION	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/11/2019	Inspection Date	20/12/2019	
Survey held at	AT AUTO CONSULTANT 113 TECK WHYE LANE #05-650 SINGAPORE 680113			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 4607T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED / CRACKED	890.00	681.90
2	FRONT BUMPER BRACKET LH @\$179.00	TO REPAIR SEE LABOUR	358.00	-
2	HEADLAMP LH/RH @\$950.00	N/S MTG CRACKED / O/S SERVICEABLE	1,900.00	750.50
2	HEADLAMP BRACKET LH/RH @\$76.00	SERVICEABLE	152.00	-
1	FRONT PANEL	BENT	911.00	872.90
1	FRONT PANEL EMBLEM "TOYOTA"	NECESSARY	76.00	76.00
1	FRONT CORNER APRON (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT GRILLE CENTER	CRACKED	456.00	456.00
1	FRONT REINFORCEMENT	BENT	452.00	329.60
1	RADIATOR TOP SUPPORT REINFORCEMENT	BENT	230.00	145.20
1	RADIATOR	SERVICEABLE	2,230.00	-
1	INTERCOOLER	BENT / PUNCTURE	1,638.00	1,336.10
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	389.00	-
1	WIPER SPARE TANK	DENTED	588.00	61.10
1	CONDENSOR (ADDITIONAL)	BENT / PUNCTURE	1,523.00	1,216.00
1	RADIATOR SPARE TANK (ADDITIONAL)	MTG CRACKED	536.00	286.30
	LESS 25% DISCOUNT		-3,082.25	-1,552.90
			9,246.75	4,658.70
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	30.00	30.00
1	AIRCON GAS TOP UP (ADDITIONAL)(SN)	NOT NECESSARY	80.00	-
			160.00	80.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET LH, FRONT CORNER APRON AND FRONT SUPPORT PANEL.		800.00	500.00
	SPRAY PAINTING ON ACCIDENT AREAS X 3 COLOURS.		900.00	600.00
	WIRING CHARGES.		100.00	20.00
	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS.		150.00	30.00
	PRESSURE LEAKAGE TEST FOR AIRCON (ADDITIONAL).		150.00	100.00
			2,100.00	1,250.00
	GRAND TOTAL		11,506.75	5,988.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00

Report Ref No. CS/FC19021433/Kyf3n2

MARKET VALUE: \$14,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$5,539.00=NETT VALUE: \$8,461.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.