

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19021455/GQF3E2

Date: 14/01/2020

REFERENCE

| | |
|---|---|
| Handling Insurer: India International Insurance Pte Ltd | Policy No: MCOM0015 |
| Claimant Vehicle No : SGN3162P | Insured Vehicle No : SHD3545J |
| Date of Loss: 01/12/2019 | Nature of Claim: TP Claim No: MCT19120021 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No: | SGN3162P | | |
| Make & Model: | HONDA AIRWAVE, 1.5 (A) | Engine No: | L15A5107862 |
| Reg. Date: | 15/11/2006 (Man. Year: 2006) | Chassis No: | GJ11106289 |
| Colour: | Grey | Odometer: | 343199 km |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 195/55 R15 | Rear Tyre Size: | 195/55 R15 |
| Front Left Side: | Continental 5 mm | Rear Left Side: | Continental 5 mm |
| Front Right Side: | Continental 5 mm | Rear Right Side: | Continental 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|------------------|--------------|
| Parts | 10,955.76 | 7,388.48 | 3,567.28 | 32.56 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,540.00 | 2,590.00 | 1,950.00 | 42.95 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 15,495.76 | 9,978.48 | 5,517.28 | 35.61 |
| Approved Total (Overridden) (S\$) | | 3,000.00 | | |
| (S\$) | 15,495.76 | 3,000.00 | 12,495.76 | 80.64 |
| + GST 7.00/7.00% (S\$) | 1,084.70 | 210.00 | 874.70 | 80.64 |
| Nett Amount (S\$) | 16,580.46 | 3,210.00 | 13,370.46 | 80.64 |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 04/12/2019 | |
| Date Inspected: | 05/12/2019 Inspected At: | Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047 |
| Estimated Period of Repair: | 8.0 days | |

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$13,000.00(est)

LTA REBATE: \$10,027.00

NETT VALUE: \$2,973.00

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Reference

| | |
|---|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 10 Jan 2020) |
| Parts: M1-MPV | HONDA AIRWAVE 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: LKK Auto Consultants Pte Ltd/SGN3162P/14/01/2020 09:20 | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 1,150.00 FL | *1,150.00 FL |
| 2 | 10 | | *FRONT BUMPER CLIPS | Necessary | 39.00 FL | *39.00 FL |
| 3 | 2 | | *FRONT BUMPER BRACKETS | Not Necessary | 96.60 FL | *- FL |
| 4 | 1 | | *FRONT BUMPER REINFORCEMENT | Not Necessary | 320.20 FL | *- FL |
| 5 | 1 | | *FRONT BUMPER TOW COVER | Not Necessary | 10.00 FL | *- FL |
| 6 | 1 | | *GRILLE | Cracked | 355.00 FL | *355.00 FL |
| 7 | 1 | | *GRILLE GARNISH | Cracked | 185.00 FL | *185.00 FL |
| 8 | 1 | | *GRILLE EMBLEM | Necessary | 32.00 FL | *32.00 FL |
| 9 | 2 | | *HEADLAMPS | Scratched | 1,251.60 FL | *1,251.60 FL |
| 10 | 2 | | *HEADLAMP LOWER BRACKETS | Not Necessary | 96.60 FL | *- FL |
| 11 | 1 | | *RADIATOR | Not Necessary | 1,450.50 FL | *- FL |
| 12 | 1 | | *AIR CON CONDENSER | Not Necessary | 880.00 FL | *- FL |
| 13 | 1 | | *BONNET MOULDING | Scratched | 140.00 FL | *140.00 FL |
| 14 | 1 | | *TAILGATE | Buckled | 1,450.00 FL | *1,450.00 FL |
| 15 | 1 | | *TAILGATE GLASS MOULDING TOP | Necessary | 86.00 FL | *86.00 FL |
| 16 | 2 | | *TAILGATE GLASS MOULDING SIDES | Necessary | 90.00 FL | *90.00 FL |
| 17 | 1 | | *TAILGATE GLASS MOULDING BOTTOM | Necessary | 86.00 FL | *86.00 FL |
| 18 | 1 | | *TAILGATE OUTER GARNISH | Deformed | 451.50 FL | *451.50 FL |
| 19 | 8 | | *TAILGATE OUTER GARNISH CLIPS | Necessary | 40.00 FL | *40.00 FL |
| 20 | 1 | | *TAILGATE BADGE AIRWAVE | Necessary | 42.00 FL | *42.00 FL |
| 21 | 1 | | *TAILGATE LOCK | Bent | 109.40 FL | *109.40 FL |
| 22 | 1 | | *TAILGATE LOCK CATCH | Not Necessary | 28.00 FL | *- FL |
| 23 | 1 | | *TAILGATE WEATHERSTRIP | Twisted | 196.00 FL | *196.00 FL |
| 24 | 1 | | *TAILGATE TRIM BOARD | Broken | 278.30 FL | *278.30 FL |
| 25 | 10 | | *TAILGATE TRIM BOARD CLIPS | Necessary | 38.00 FL | *38.00 FL |
| 26 | 1 | | *TAILGATE INNER HANDLE GRIP | Necessary | 23.50 FL | *23.50 FL |
| 27 | 1 | | *TAILGATE STOPPER RH | Missing | 12.00 FL | *12.00 FL |
| 28 | 1 | | *REAR BUMPER | Deformed | 1,078.50 FL | *1,078.50 FL |
| 29 | 10 | | *REAR BUMPER CLIPS | Necessary | 40.00 FL | *40.00 FL |
| 30 | 2 | | *REAR BUMPER BRACKETS | Not Necessary | 63.20 FL | *- FL |
| 31 | 1 | | *END PANEL | Buckled | 508.70 FL | *508.70 FL |
| 32 | 1 | | *END PANEL TOP GARNISH | Deformed | 138.60 FL | *138.60 FL |
| 33 | 2 | | *REAR FENDER TRIM BOARDS | Cracked | 602.00 FL | *602.00 FL |
| 34 | 1 | | *SPARE TYRE TOP BOARD | Cut | 350.00 FL | *350.00 FL |
| 35 | 1 | | *SPARE TYRE PANEL | Repair | 1,126.50 FL | *- FL |
| 36 | 1 | | *FRONT NUMBER PLATE | Bent | 45.00 FS | *45.00 FS |
| 37 | 1 | | *TAILGATE GLASS SEALANT | Necessary | 50.00 FS | *50.00 FS |
| 38 | 1 | | *TAILGATE GLASS SEALER | Not Necessary | 30.00 FS | *- FS |
| 39 | 1 | | *TAILGATE GLASS FASTENER | Necessary | 50.00 FS | *50.00 FS |
| 40 | 1 | | *REAR NUMBER PLATE | Scratched | 45.00 FS | *45.00 FS |
| 41 | 1 | | *REAR BUMPER REVERSE SENSOR | Not Necessary | 280.00 FS | *- FS |
| 42 | 1 | | *SPARE TYRE PANEL INSULATION | Buckled | 180.00 FS | *180.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,524.70 9,143.10

LKK Auto Consultants Pte Ltd/SGN3162P/14/01/2020 09:20. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|-------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO CONDUCT FRONT ELECTRICAL CHECK, FOCUS HEADLAMP ETC | New | 30.00 | 30.00 |
| 2 | TO REMOVE / REFIT AIR CON CONDENSER & REFILL AIR CON GAS | New | 120.00 | 0.00 |
| 3 | TO REMOVE / REFIT, RADIATOR SYSTEM, BLEED, REFILL COOLANT | New | 60.00 | 0.00 |
| 4 | TO TRANSFER TAILGATE FITTINGS / ANCILLARY ACCESSORIES | New | 120.00 | 60.00 |
| 5 | TO DISMANTLE / REFIT TAILGATE GLASS | New | 160.00 | 100.00 |
| 6 | TO DISMANTLE / REFIT TRUNK COMPARTMENT BOARDS & TRIMS | New | 80.00 | 60.00 |
| 7 | TO SUPPLY END PANEL, SPARE TYRE PANEL BODY SEALANT | New | 100.00 | 40.00 |
| 8 | TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL | New | 150.00 | 60.00 |
| 9 | TO CONDUCT REAR ELECTRICAL CHECK, REPLACE REVERSE SENSOR, MODULE ETC | New | 120.00 | 40.00 |
| 10 | LABOUR CHARGE - PANEL BEATING, REPAIRING OF FRONT SUPPORT PANEL, REAR CHASSIS MEMBER, INNER PANEL, FLOOR PANEL ETC. CNT, WELD END PANEL, SPARE TYRE PANEL AND PARTS REPLACEMENT | New | 2,000.00 | 1,200.00 |
| 11 | TO SPRAY PAINT AFFECTED AREAS | New | 1,600.00 | 1,000.00 |
| | | | Gross Labour Cost (\$) | 2,590.00 |

LKK Auto Consultants Pte Ltd/SGN3162P/14/01/2020 09:20. Not valid without Reference section.

< END OF ESTIMATES >