


來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UE V: 199407592C

INSURER: AIG Asia Pacific Insurance Pte. Ltd. (SG)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	71084
Policy No:	999994322	Date of Loss:	02/12/2019
Vehicle Reg. No.:	SMD4305U	Driveable?	
Driver Age/Info:	50 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD	Contact No:	+6596626300
Driver:	POON CHEE SHIN		
Make/Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Vehicle Reg. Date:	20/08/2018
Vehicle Colour:	White		
Engine No:	D4FDJH553063	Chassis No:	KNAHU315VJ7208196
Odometer:	123838 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 day		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / DERRICK TAY		



Not Notified
Perjury Bypass

COST OF CLAIMS	Amount
Parts	1,724.80
Miscellaneous Items	11.00
Labour	720.00
Paintwork Labour	450.00
Towing	0.00
Calculated Gross Total (S\$)	2,905.80
- Excess (S\$)	1,500.00
(S\$)	1,405.80
+ GST 7.00% (S\$)	98.41
Nett Amount (S\$)	1,504.21

This claim is handled by: DERRICK TAY

REPAIR DETAILS**Reference**

Part Source: MRM-SC Version: 1.0 (Last Synchronised: 04 Dec 2019)
Parts: M1-MPV KIA CARENS 1.7 D DCT 5 DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-nominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SMD4305U/04/12/2019 13:17
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper	0.00	0.00	*250.00 F ✓
2	1		*Front fog lamp LH	<i>Ang side</i> 0.00	0.00	*90.00 F ✓
3	1		*Front fog lamp cover LH	0.00	0.00	*50.00 F ✓
4	1		*Front bumper side retainer LH	0.00	0.00	*10.00 F ✓
5	1		*Front fender LH	0.00	0.00	*130.00 F ✓
6	1		*Front fender inner shield LH	0.00	0.00	*38.00 F ✓
7	1		*Front headlamp LH	<i>Ang side</i> 0.00	0.00	*650.00 F ✓
8	1		*Front support panel	<i>Ang Bump</i> 0.00	0.00	*230.00 F ✓
Sub Total (S\$)						1,568.00
+ Margin on L,N Items 10.00% (S\$)						156.80
Total Parts (S\$)						1,724.80

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SMD4305U/04/12/2019 13:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Labr.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint	New	450.00
<u>Labour Items</u>			
2	To check wheel alignment	New	60.00
3	To remove + refix front bumper parking sensor holders (x4)	New	40.00
4	To remove + refix front fender quarter glass LH	New	80.00
5	To supply sealant	New	40.00
6	To straighten front body and renew of parts	New	500.00
Gross Labour Cost (S\$)			1,170.00

Lai Huat (Meng Kee) Motor Pte Ltd/SMD4305U/04/12/2019 13:17. Not valid without Reference section.
Generated using Merlimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: