

ASS. REC. BY:

REF: CS/MSG/902/461/DS f3

Special Instructions:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Pauline Tham

of

ms76

Date/Time: 4.12.19 16:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 8933U

Insured:

GBE 8564

at Workshop m/s Channi

Tel:

65425119

of BIK 10 # 01-05/06

Policy No: 29011669 MKC

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 2.12.2019

CA / REV / REP. / REV 24 HRS

mp

5.12.2019

Date/Time: 4.12.19 5:57pm

Person Contacted:

Lyon

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 8933U - AS/AC 12/2019 411/123

PA - 12/10/2012

GBE 8564 - X

23/12/19

@ 15:46 pm revised PA to Pauline Tham vis mrimer.

APP. REC. BY: Bryan

REP:

ASSIGNMENT

COE April 2024

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP: / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 8933U

Yr Regn: 2016 / April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp.Rending: N.A. T/Radio: Insured / Std / NI / NA

Eng/No: D4FD 64614118

C/No: KMHLB41UM 6U087816

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 716

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 5' mm R/Bal. 5' mm

L/Bal. 5' mm L/Bal. 5' mm

D.O.A. 02/12/2019 D.O.I. 05/12/2019

Survey held at Chunnai AMK

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front 7 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MSIG GBE 856Y

14/01/2020 Jagan 2/5 11700/- with 7 days 2m
(\$ 12,142.78 Real - 51%)

RECEIVED 14 JAN 2020

Date/Time, File Pass k/7

14/01/20

1)

Jagan

Date/Time, File Return k/2

2)

Rep. Form:

Lump Sum / U/C: \$ 11,700/- 45

☐ : Preli. Report☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Wheel end (\$)

Survey Fee:

Transportation:

S + PS: \$

Photos

Notes

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins. Auth'd	Status
Main	04 Dec 2019 10:02		04 Dec 2019 16:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	AIR VENTURE AIRCONDITIONING PTE LTD, Co. Reg. No.: 200210250R		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHC8933U	Date of Loss:	02/12/2019 19:00 - :59 [43 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29011669MKC (Comprehensive) Coverage: 01/09/2019 - 31/08/2020
Vehicle Reg. No. (Insured):	GBE856Y	Policy No. (Claimant):	
		Excess:	
RePAIRer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/12/2019]		
Driver/Custodian (Insured):	CHONG KAI SHEN (/ Male) , NRIC: G2704648M Email:		
Adj Asg. Remarks:	on WP. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn / Ms Irene at 6542 5119 or 6542 7162.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 23 Dec 2019

Preliminary Advice

Insured Vehicle No	: GBE856Y	Accident Date	: 02/12/2019
TP Vehicle No	: SHC8933U	Assignment Date	: 04/12/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 7 days
Date of Inspection	: 05/12/2019		
Inspection At	: Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,842.78
Revised Amount	:S\$	14,633.18
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,633.18
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

MC051915M68 / ComtonDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 03/12/2019 14:03
 SUBMITTED BY: Catherine Per May Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2019 14:03
Date Of Accident	02/12/2019 19:05
Exact Location Of Accident	ANG MO KIO AVE 5 (CTE-SLE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8933U
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TEO SIN BENG
NRIC No	S2534782Z
Date Of Birth	13/04/1961
Occupation	OUTDOOR
Date Of Driving Pass	31/07/1980
Driving Experience	39 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96531145
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 945 07-147 HOUGANG STREET 92
Postcode 530945
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 4
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 4
Passenger 1
NAME: : -
GENDER: : FEMALE
Passenger 2
NAME: : -
GENDER: : MALE
Passenger 3
NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE856Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 03.12.2019
@ 12:00 hrs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



Along Ang Mo Kio Ave 5 TWDS CTE (SLE)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 02.12.2019 at about 19:05 hours I was travelling Ang Mo Kio Ave 5 TWDS CTE
(SLE) with One Female and Two Child passenger onboard .
While I see veh C (SHD 137Z) in front of me stop , I followed too . Suddenly I felt an
impact from my taxi A - rear portion and cause my taxi to surge forward and collided into
Veh C .
After the accident my taxi sustain my damages on both front and rear portion .
No injury in this accident .
I have company video and photos at scene to support my claims .
All vehicles above are male driver

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 03.12.2019
@ 12:00 hrs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SHC 8933U

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>1st</i>			\$ 2,174.90	✓
	Boot Lid Lock Upper <i>Down</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>rev</i>			\$ 31.70	X
	Boot Lid 'H' Emblem <i>Hec</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>Hec</i>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <i>NH</i>	\$	565.60	\$ 1,131.20	X
	Boot Lid Trimboard <i>NH</i>			\$ 116.40	X
	Boot Lid Trimboard Clips (10pcs) <i>NH</i>			\$ 11.00	X
	Bootlid Moulding <i>NH</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>NH</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>NH</i>			\$ 227.90	X
	Rear Bumper <i>distorted</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>Crack</i>			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>1st</i>	\$	80.30	\$ 160.60	✓
	Rear Bumper Clip 10 pcs <i>Hec</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>NH</i>	\$	35.60	\$ 71.20	X
	Rear Bumper Sponge <i>firm</i>			\$ 118.40	✓
	Rear Bumper Under Cover <i>distorted / deformed</i>			\$ 228.00	✓
	Tail Lamp (LH/RH) <i>Crack</i>	\$	697.80	\$ 1,395.60	✓
	Rear Panel <i>Distorted</i>			\$ 526.70	✓
	Rear Panel Garnish <i>mainly broken</i>			\$ 57.70	✓
	Rear Panel Lower Panel <i>Distorted</i>			\$ 495.50	✓
	Spare Tyre Holder <i>broken / 1st</i>			\$ 248.00	✓
	Spare Tyre Panel <i>Distorted</i>			\$ 852.80	✓
	Spare Tyre Panel Cushion <i>NH</i>			\$ 209.05	X
	Rear Towing Hook <i>NH</i>			\$ 94.60	X
	Member Assy- Rear Floor Centre <i>NH</i>			\$ 570.40	X
	Exhaust Pipe Insulator <i>NH</i>	\$	58.55	\$ 117.10	X
	Exhaust Silencer <i>Distorted / 1st</i>	\$	967.70	\$ 1,935.40	✓ photo
	Exhaust Pipe Hanger <i>NH</i>	\$	58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>NH</i>			\$ 730.10	X
			9356.20		
			7484.96		
	SUB TOTAL			\$ 12,896.85	
	LESS 20%			\$ 2,579.37	
	DISCOUNTED TOTAL			\$ 10,317.48	
	Boot Lid Comfort Logo & Tel No. Sticker <i>Hec</i>			\$ 30.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Down</i>			\$ 135.70	Nett ✓
	Rear Bumper Rubber Mat <i>Hec</i>			\$ 50.00	Nett ✓
			215.70		
				\$ 215.70	

SHC 8933U

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			S 1,600.00 700/-
	Spray Painting Charge			S 1,000.00 700/-
	Wiring Charge			S 50.00 30/-
	Tuff Kote		1570.00	S 50.00 40/-
	Remove/Refix Reverse Sensor			S 120.00 40/-
	Remove/Refix Exhaust Pipe			S 300.00 60/-
	TOTAL LABOUR			S 3,120.00
	ESTIMATE TOTAL			S 23,842.78
	05/12/2019 @ 0930am		14633.18	
	N/A Antenna			
	2 Hrs 7 days		4/8 11700/-	
				
	LKK Auto			
				
	<p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

...CLAIM SUBFOLDER...(Pending for Survey Report)
























































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Dec 2019 10:02		04 Dec 2019 16:55 Edit Adj Rpt	S\$11,700.00 Edit Estimates	S\$11,700.00 View Rpt		Pending for Survey Report Cancel Case















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	AIR VENTURE AIRCONDITIONING PTE LTD, Co. Reg. No.: 200210250R								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC8933U	Date of Loss:	02/12/2019 19:00 - :59 [43 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 613514	Policy/Cover Note No.:	29011669 (Comprehensive) Coverage: 01/09/2019 - 31/08/2020						
Vehicle Reg. No. (Insured):	GBE856Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 03/01/2020]								
Driver/Custodian (Insured):	CHONG KAI SHEN (/ Male) , NRIC: G2704648M Email:								
Adj Asg Remarks:	on WP. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn / Ms Irene at 6542 5119 or 6542 7162.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									















































Claim Documents














*SHC8933U (613514)
[GBE856Y]
TP
COMFORT TRANSPORTATION PTE LTD
Dec 2 2019 7:00PM
[AIR VENTURE AIRCONDITIONING PTE LTD]
Chunni Motor Work Pte Ltd - Amk

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	23/12/19 15:46	Adjuster Immediate Advice							1			Load HTM		
									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	03/01/20 11:38	Front View Left							1			Load JPG		
2	03/01/20 11:38	Front View Right							1			Load JPG		
3	03/01/20 11:39	General View							1			Load JPG		
4	03/01/20 11:39	General View							1			Load JPG		
5	03/01/20 11:39	General View							1			Load JPG		
6	03/01/20 11:39	General View							1			Load JPG		
7	03/01/20 11:39	General View							1			Load JPG		
8	03/01/20 11:39	General View							1			Load JPG		
9	03/01/20 11:39	General View							1			Load JPG		
10	03/01/20 11:39	General View							1			Load JPG		
11	03/01/20 11:39	General View							1			Load JPG		
12	03/01/20 11:39	General View							1			Load JPG		
13	03/01/20 11:39	General View							1			Load JPG		
14	03/01/20 11:39	General View							1			Load JPG		
15	03/01/20 11:39	General View							1			Load JPG		
16	03/01/20 11:39	General View							1			Load JPG		
17	03/01/20 11:39	General View							1			Load JPG		
18	03/01/20 11:39	General View							1			Load JPG		
19	03/01/20 11:39	General View							1			Load JPG		
20	03/01/20 11:39	General View							1			Load JPG		
21	03/01/20 11:39	General View							1			Load JPG		
22	03/01/20 11:39	General View							1			Load JPG		
23	03/01/20 11:39	General View							1			Load JPG		
24	03/01/20 11:39	General View							1			Load JPG		
25	03/01/20 11:39	General View							1			Load JPG		
26	03/01/20 11:39	General View							1			Load JPG		
27	03/01/20 11:39	General View							1			Load JPG		
28	03/01/20 11:39	General View							1			Load JPG		
29	03/01/20 11:39	General View							1			Load JPG		
30	03/01/20 11:39	General View							1			Load JPG		
31	03/01/20 11:39	General View							1			Load JPG		
32	03/01/20 11:39	General View							1			Load JPG		
33	03/01/20 11:39	General View							1			Load JPG		
34	03/01/20 11:39	General View							1			Load JPG		
35	03/01/20 11:39	General View							1			Load JPG		
36	03/01/20 11:39	General View							1			Load JPG		
37	03/01/20 11:39	General View							1			Load JPG		
38	03/01/20 11:39	General View							1			Load JPG		
39	03/01/20 11:39	General View							1			Load JPG		
40	03/01/20 11:39	General View							1			Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	03/01/20 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/01/20 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/01/20 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/01/20 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/01/20 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/01/20 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/01/20 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/01/20 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/01/20 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/01/20 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/01/20 11:40	Rear View Right	 Load JPG	<input checked="" type="checkbox"/>
52	03/01/20 11:40	Rear View Left	 Load JPG	<input checked="" type="checkbox"/>
53	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
67	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
68	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
69	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
70	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
71	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
72	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
73	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
74	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
75	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
76	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
77	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
78	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
79	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
80	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
81	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
82	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
83	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
84	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
85	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
86	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
87	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
88	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
89	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
90	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
91	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
92	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
93	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
94	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
95	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
97	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
98	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
99	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
100	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
101	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
102	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
103	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
104	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
105	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
106	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
107	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
108	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
109	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
110	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
111	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
112	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
113	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
114	03/01/20 11:40	General View	 Load JPG	<input checked="" type="checkbox"/>
115	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
116	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
117	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
118	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
119	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
120	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
121	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
122	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
123	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
124	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
125	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
126	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
127	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
128	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
129	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
130	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
131	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
132	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
133	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
134	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
135	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
136	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
137	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
138	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
139	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
140	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
141	03/01/20 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
142	03/01/20 11:41	General View	Load JPG	<input checked="" type="checkbox"/>
143	03/01/20 11:41	General View	Load JPG	<input checked="" type="checkbox"/>
144	03/01/20 11:41	General View	Load JPG	<input checked="" type="checkbox"/>
145	03/01/20 11:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
146	03/01/20 11:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
147	03/01/20 11:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
148	03/01/20 11:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
149	03/01/20 11:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
150	03/01/20 11:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
151	03/01/20 11:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
152	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	03/01/20 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	03/01/20 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	03/01/20 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	03/01/20 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
168	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
169	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
170	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
171	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
172	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
173	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
174	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
175	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
176	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
177	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
178	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
179	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
180	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
181	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
182	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
183	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
184	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
185	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
186	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
187	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
188	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
189	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
190	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
191	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
192	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
193	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
194	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
195	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
196	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
197	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
198	03/01/20 11:49	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
199	03/01/20 11:49	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
200	03/01/20 11:49	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
201	03/01/20 11:49	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
202	03/01/20 11:49	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
203	03/01/20 11:49	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
204	03/01/20 11:49	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
205	03/01/20 11:49	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
206	03/01/20 11:49	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
207	03/01/20 11:49	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
208	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
209	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
210	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
211	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
212	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
213	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
214	03/01/20 11:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/12/19 10:04	OI GIA Report - 3/4	 Load PDF	
2	04/12/19 10:04	TP SHD137Z GIA REPORT - 1/4	 Load PDF	
3	04/12/19 10:04	TP SHC8933U GIA REPORT - 2/4	 Load PDF	
4	04/12/19 10:04	TP SDS7722G GIA REPORT - 4/4	 Load PDF	
5	04/12/19 10:05	Estimate	 Load PDF	
6	04/12/19 10:46	Agree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</div> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19021461/DSF3Q2

Date: 15/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29011669
Claimant	Insured Vehicle No :	GBE856Y
Vehicle No : SHC8933U	Nature of Claim:	TP
Date of Loss: 02/12/2019	Claim No:	613514

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8933U	Engine No:	D4FDGU614118
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU087816
Reg. Date:	21/04/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,742.78	12,533.18	6,209.60	33.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	2,100.00	3,000.00	58.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,842.78	14,633.18	9,209.60	38.63
Approved Total (Overridden) (S\$)		11,700.00		
(S\$)	23,842.78	11,700.00	12,142.78	50.93
+ GST 7.00/7.00% (S\$)	1,668.99	819.00	849.99	50.93
Nett Amount (S\$)	25,511.77	12,519.00	12,992.77	50.93

INSPECTION

Date of Assignment:	04/12/2019	
Date Inspected:	05/12/2019 Inspected At:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	7.0 days	

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8933U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
2	1		*RADIATOR GRILLE H EMBLEM	Necessary	39.50 FL	*39.50 FL
3	1		*FRONT BUMPER COVER	Mtg Cracked	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	402.10 FL	*- FL
6	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
7	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
8	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Bent	907.40 FL	*907.40 FL
10	2		*HEADLAMP (LH/RH)	Mtg Cracked	2,776.00 FL	*2,776.00 FL
11	1		*RADIATOR	Not Necessary	698.30 FL	*- FL
12	1		*RADIATOR FAN BLADE,COWLING ,MOTOR ASSY	Not Necessary	792.95 FL	*- FL
13	2		*RADIATOR BRACKET (LH/RH)	Not Necessary	13.00 FL	*- FL
14	1		*AIRCON CONDENSER	Not Necessary	927.50 FL	*- FL
15	1		*INTER COOLER	Not Necessary	1,032.50 FL	*- FL
16	2		*INTER COOLER MOUNTING	Not Necessary	25.90 FL	*- FL
17	1		*FRONT NUMBER PLATE)	Cracked	25.00 FS	*45.00 FS
18	1		*FRONT NO PLATE TRIM COVER)	Broken	30.00 FS	*- FS
19	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
20	1		*BOOT LID LOCK UPPER	Damaged	102.60 FL	*102.60 FL
21	1		*BOOT LID LOCK LOWER	Repair	31.70 FL	*- FL
22	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
23	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
24	2		*BOOT LID LAMP (LH/RH)	Not Necessary	1,131.20 FL	*- FL
25	1		*BOOT LID TRIMBOARD	Not Necessary	116.40 FL	*- FL
26	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
27	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
28	1		*BOOTLID I40 EMBLEM	Not Necessary	27.90 FL	*- FL
29	1		*BOOTLID LOWER GARNISH	Not Necessary	227.90 FL	*- FL
30	1		*REAR BUMPER	Distorted	553.00 FL	*553.00 FL
31	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
32	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent	160.60 FL	*160.60 FL
33	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
34	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
35	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
36	1		*REAR BUMPER UNDER COVER	Distorted / Deformed	228.00 FL	*228.00 FL
37	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL
38	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
39	1		*REAR PANEL GARNISH	Mtg Broken	57.70 FL	*57.70 FL
40	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*SPARE TYRE HOLDER	Broken / Bent	248.00 FL	*248.00 FL
42	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
43	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
44	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
45	1		*MEMBER ASSY -REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
46	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
47	2		*EXHAUST SILENCER	Dented / Bent	1,935.40 FL	*1,935.40 FL
48	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
49	2		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
50	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	30.00 FS	*30.00 FS
51	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
52	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,360.80	15,601.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,618.02	3,068.12
Total Parts (\$\$)	18,742.78	12,533.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,600.00	1,000.00
2	SPRAY PAINTING CHARGE	New	1,250.00	900.00
3	WIRING CHARGE	New	100.00	60.00
4	TUFF KOTE	New	100.00	40.00
5	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
6	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
7	REMOVE /REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE/REFIX EXHAUST PIPE	New	300.00	60.00
Gross Labour Cost (S\$)			5,100.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >