

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021468/GKA3Q2
Date: 12/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100223699
Claimant
Vehicle No : SHA2306E **Insured Vehicle No :** SJG1505Z
 Date of Loss: 02/12/2019 Nature of Claim: TP Claim No: 0078253789SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA2306E**
 Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A) Engine No: G4LEKU295296
 Reg. Date: 26/06/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU164317
 Colour: Blue Odometer: 0 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Davanti 6 mm Rear Left Side: Davanti 6 mm
 Front Right Side: Davanti 6 mm Rear Right Side: Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,731.06	521.70	1,209.36	69.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	560.00	460.00	45.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,751.06	1,081.70	1,669.36	60.68
+ GST 7.00/7.00% (S\$)	192.57	75.72	116.85	60.68
Nett Amount (S\$)	2,943.63	1,157.42	1,786.21	60.68
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$125.19/day) (S\$)		312.98		
Nett Liability (S\$)		1,595.40		
Global Sum Settlement (S\$)		1,550.00		

INSPECTION

Date of Assignment: 03/12/2019
 Date Inspected: 04/12/2019 Inspected At: ComfortDelGro Engineering Pte Ltd
 (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	*- FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	276.20 FL	*- FL
4	1		*REAR BUMPER CENTRE MOULDING ASSY	Scratched	451.25 FL	*451.25 FL
5	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Not Necessary	155.00 FL	*- FL
6	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
7	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Not Necessary	66.20 FL	*- FL
8	1		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
9	1		*REAR NO PLATE	Cracked	25.00 FS	*25.00 FS
10	1		*REAR NO PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
11	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
12	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,103.65	611.95
- List Item Discount on L Items 20.00/20.00% (\$\$)	372.59	90.25
Total Parts (\$\$)	1,731.06	521.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING CHARGE -FRT BUMPER	New	250.00	0.00
2	PANEL BEATING	New	350.00	320.00
3	SPRAY PAINTING CHARGE	New	250.00	200.00
4	WIRING CHARGE	New	50.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
			Gross Labour Cost (\$)	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >