

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19021469/DDA3Q2

**Date:** 16/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900082711

**Claimant**  
**Vehicle No :** SH8888K **Insured Vehicle No :** GBJ3668C

Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: 2120818289SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8888K	Engine No:	2ZRS054758
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU203560843
Reg. Date:	26/07/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,833.97	3,869.24	1,964.73	33.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	470.00	180.00	27.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,483.97</b>	<b>4,339.24</b>	<b>2,144.73</b>	<b>33.08</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,450.00</b>		
<b>(S\$)</b>	6,483.97	3,450.00	3,033.97	46.79
<b>+ GST 7.00/7.00% (S\$)</b>	453.88	241.50	212.38	46.79
<b>Nett Amount (S\$)</b>	<b>6,937.85</b>	<b>3,691.50</b>	<b>3,246.35</b>	<b>46.79</b>
<b>+ Loss of Use (3.5 x S\$50.00/day) (S\$)</b>		175.00		
<b>+ Car Rental (3.5 x S\$125.40/day) (S\$)</b>		438.90		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,307.40</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,300.00</b>		

### INSPECTION

Date of Assignment: 03/12/2019

Date Inspected: 04/12/2019 Inspected At:

Chunni Motor Work Pte Ltd (HQ)  
Blk 10 Ang Mo Kio Industrial Park 2A,  
#03-19 AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 3.0 days

---

**Adjuster:** BRYAN TANI

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Not Necessary	438.00 FL	*- FL
2	1		*RADIATOR GRILLE EMBLEM	Not Necessary	88.00 FL	*- FL
3	1		*LAMP ASSY ,FOG ,RH	Mtg Cracked	920.00 FL	*920.00 FL
4	1		*FRONT BUMPER COVER	Distorted	499.90 FL	*499.90 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	696.40 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT ABSORBER	Not Necessary	115.70 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Not Necessary	78.80 FL	*- FL
8	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	301.90 FL	*- FL
9	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
10	1		*FRONT BUMPER SIDE RETAINER ,RH	Serviceable	77.00 FL	*- FL
11	1		*COVER ,FRONT BUMPER HOLE ,RH	Dislodged	28.38 FL	*28.38 FL
12	1		*COVER ,FRONT BUMPER HOLE ,LH	Dislodged	28.38 FL	*28.38 FL
13	1		*BRACKET ,FRONT BUMPER EXTENSION MOUNTING	Not Necessary	110.40 FL	*- FL
14	1		*UNIT ASSY ,HEADLAMP ,RH (LED)	Mtg Cracked / Broken	3,455.00 FL	*3,455.00 FL
15	1		*HEAD LAMP PANEL (RH)	Not Necessary	240.10 FL	*- FL
16	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
17	1		*FRONT NO PLATE TRIM COVER	Broken	30.00 FS	*30.00 FS
18	1		*FRONT NO.PLATE GARNISH	Broken	99.00 FS	*99.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,253.96</b>	<b>5,107.66</b>
<b>- List Item Discount on L Items 20.00/25.00% (\$)</b>	<b>1,419.99</b>	<b>1,238.42</b>
<b>Total Parts (\$)</b>	<b>5,833.97</b>	<b>3,869.24</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	250.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	WIRING CHARGE	New	50.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>650.00</b>	<b>470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >