

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021470/HDA3Q2

Date: 27/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100440916

Claimant
Vehicle No : GBE5948H **Insured Vehicle No :** GBE4083J

Date of Loss: 25/11/2019 Nature of Claim: TP Claim No: 0174837811SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE5948H		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2584643
Reg. Date:	22/01/2016 (Man. Year: 2015)	Chassis No:	JTFHT02P200188371
Colour:	Silver	Odometer:	114039 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/ R15C	Rear Tyre Size:	195/ R15C
Front Left Side:	Neuton 4 mm	Rear Left Side:	Neuton 4 mm
Front Right Side:	Neuton 4 mm	Rear Right Side:	Neuton 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,308.21	2,222.79	2,085.42	48.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	930.00	460.00	33.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,698.21	3,152.79	2,545.42	44.67
Approved Total (Overridden) (\$\$)		2,500.00		
(\$\$)	5,698.21	2,500.00	3,198.21	56.13
+ GST 7.00/7.00% (\$\$)	398.87	175.00	223.87	56.13
Nett Amount (\$\$)	6,097.08	2,675.00	3,422.08	56.13
+ Loss of Use (5.0 x S\$100.00/day) (\$\$)		500.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,177.00		

INSPECTION

Date of Assignment: 17/12/2019

Date Inspected: 17/12/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E.,
#01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	874.50 F	*727.10 FL
2	1		*BONNET HINGE LH	Repair	75.20 F	*- FL
3	1		*BONNET INNER LOCK	Jammed	75.20 F	*75.20 FL
4	1		*SUPPORT PANEL	Repair	392.46 F	*- FL
5	1		*HEADLAMP LH	Crumpled	799.50 F	*799.50 FL
6	1		*FRONT WASHER TANK	Crumpled	86.62 F	*86.62 FL
7	1		*FRONT GRILLE ASSEMBLY	Cracked	1,270.86 F	*624.70 FL
8	1		*FRONT GRILLE BASE GARNISH (NPA)	No such part	0.00 F	*- FL
9	1		*FRONT BUMPER	Bent	589.57 F	*496.30 FL
10	2		*FRONT GRILLE CLIP	Necessary	24.80 F	*24.80 FL
11	1		*BONNET EMBLEM	Necessary	89.50 F	*89.50 FL
12	1		*FRONT NUMBER PLATE	Scratched	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,308.21	2,953.72
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	730.93
Total Parts (\$\$)	4,308.21	2,222.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	700.00	500.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	500.00	400.00
3	ANTI RUST COATING	New	150.00	0.00
4	WIRING	New	40.00	30.00
Gross Labour Cost (\$\$)			1,390.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >