

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021474/GKA3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMN2065Y **Insured Vehicle No :** SKM7003Y

Date of Loss: 02/11/2019 **Nature of Claim:** TP **Claim No:** 2617413933SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN2065Y		
Make & Model:	BLUECAR BLUECAR, (A)	Engine No:	HIDDEN
Reg. Date:	29/07/2019 (Man. Year: 2018)	Chassis No:	VL4BCEB4RJT003533
Colour:	White	Odometer:	0 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,150.45	3,893.50	1,256.95	24.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	1,100.00	300.00	21.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,550.45	4,993.50	1,556.95	23.77
+ GST 7.00/7.00% (S\$)	458.53	349.55	108.98	23.77
Nett Amount (S\$)	7,008.98	5,343.05	1,665.93	23.77
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		4.00		
Nett Liability (S\$)		5,647.05		

INSPECTION

Date of Assignment: 05/12/2019

Date Inspected: 05/12/2019 Inspected At: Indeco Engineers Pte Ltd (Defu)
No. 39 Defu Lane 12
Singapore 539315

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT FENDER (WCP)	Repair	1,040.00 F	*- F
2	1		*RIGHT DOOR (WCP)	Buckled	2,705.00 F	*2,705.00 F
3	10		*RIGHT DOOR CLIP & RIVET (WCP)	Necessary	20.00 F	*20.00 F
4	1		*RIGHT DOOR OUTER LOCK WITH KEY (WCP)	Cut	165.00 F	*165.00 F
5	1		*RIGHT DOOR STICKER	Necessary	70.00 FS	*70.00 FS
6	1		*REAR RIGHT FENDER STICKER	Necessary	40.00 FS	*40.00 FS
7	1		*REAR RIGHT FENDER COVER (WCP)	Scratched	195.00 F	*195.00 F
8	5		*REAR RIGHT FENDER COVER SCREW (WCP)	Necessary	10.00 F	*10.00 F
9	1		*RIGHT SIDE SKIRT (WCP)	Cut	195.00 F	*195.00 F
10	1		*REAR RIGHT RIM COVER (WCP)	Not Necessary	53.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,493.00	3,400.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	657.45	493.50
Total Parts (\$\$)	5,150.45	3,893.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,REPLACE FRONT RIGHT FENDER ,RH DOOR REAR RIGHT FENDER ,RIGHT SIDE SKIRT AND AFFECTED AREA	New	800.00	600.00
2	TO SPRAY FRONT RIGHT FENDER ,RH INNER DOOR & OUTER DOOR ,REAR RIGHT FENDER AND AFFECTED AREA	New	600.00	500.00
Gross Labour Cost (\$)			1,400.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >