

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG19021493/GBA3Q2

Date:

17/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999993989

Claimant Vehicle No : SHC929K**Insured Vehicle No :**

SLV4100K

Date of Loss: 03/12/2019

Nature of Claim:

TP

Claim No:

9495752836SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC929K**

Make & Model: MERCEDES-BENZ VIANO, 2.1 D CDI Ambiente (W639) (A)

Engine No:

HIDDEN

Reg. Date: 10/10/2013 (Man. Year: 2013)

Chassis No:

WDF63981323801650

Colour: White

Odometer:

781651 km

Engine Capacity: 2143 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R16

Rear Tyre Size:

225/60 R16

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,028.16	5,028.16	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	820.00	740.00	47.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,588.16	5,848.16	740.00	11.23
Approved Total (Overridden) (S\$)		4,700.00		

(S\$)	6,588.16	4,700.00	1,888.16	28.66
+ GST 7.00/7.00% (S\$)	461.17	329.00	132.17	28.66
Nett Amount (S\$)	7,049.33	5,029.00	2,020.33	28.66
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$161.18/day) (S\$)		967.08		
Nett Liability (S\$)		6,296.08		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment: 04/12/2019

Date Inspected: 04/12/2019

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE ASSY	Buckled	3,951.98 FL	*3,951.98 FL
2	1		*TAIL GATE MERCEDES STAY LOGO	Necessary	45.46 FL	*45.46 FL
3	1		*TAIL GATE 2.2 LOGO	Necessary	78.00 FL	*78.00 FL
4	1		*TAIL GATE CDI LOGO	Necessary	78.00 FL	*78.00 FL
5	1		*TAIL GATE VIA NO LOGO	Necessary	78.00 FL	*78.00 FL
6	1		*TAIL LAMP ASSY ,LH	Scratched	622.44 FL	*622.44 FL
7	1		*TAIL LAMP REFLECTOR UPPER ,LH	Cut	105.74 FL	*105.74 FL
8	1		*REAR FENDER PROTECTOR (LH)	Cut	56.48 FL	*56.48 FL
9	1		*REAR BUMPER	Deformed	581.90 FL	*581.90 FL
10	1		*REAR BUMPER SIDE LH	Deformed	237.20 FL	*237.20 FL
11	1		*REVERSE SENSOR	Damaged	280.00 FS	*280.00 FS
12	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
13	1		*TAIL GATE MAXICAB LOGO	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,195.20	6,195.20
- List Item Discount on L Items 20.00/20.00% (\$)	1,167.04	1,167.04
Total Parts (\$)	5,028.16	5,028.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	360.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	WIRING CHARGE	New	30.00	20.00
4	TUFF KOTE	New	50.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
6	TOWING FEE	New	60.00	0.00
Gross Labour Cost (\$\$)			1,560.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >