

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 929K

MAKE :

MODEL : MERCEDES BENZ VIANO (REAR)

Ag B1a-4S

DATE 4/12/2019

TS

1210

LKK - Guo Qiang

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Tail Gate Assy / Bnc			\$ 3,951.98
	Tail Gate Mercedes Star Logo			\$ 45.46
	Tail Gate "2.2" Logo			\$ 78.00
	Tail Gate "CDI" Logo			\$ 78.00
	Tail Gate Via No Logo			\$ 78.00
	Tail Lamp Assy, LH / SR			\$ 622.44
	Tail Lamp Reflector Upper, LH			\$ 105.74
	Rear Fender Protector (LH) / SR Cert			\$ 56.48
	SUB TOTAL			\$ 5,016.10
	LESS 20%			\$ 1,003.22
	DISCOUNTED TOTAL			\$ 4,012.88
	Rear Bumper Rubber Mat / SR MC			\$ 50.00
	Tail Gate "MAXICAB" Logo / SR MC			\$ 30.00
	Reverse Sensor / DM			\$ 80.00
	Labour Charge			
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 500.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOWING FEE			60.00
	TOTAL LABOUR			\$ 1,500.00
	ESTIMATE TOTAL			\$ 5,592.88
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Nett

Nett

280 nett

360

460

20

X NA

40

60.00 nett X

NA

3 Days.

Unsup sum repair.

After repair photos.

Guo Qiang

04/12/19.