

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021500/BES3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMC143B **Insured Vehicle No :** SDJ3858Y

Date of Loss: 12/11/2019 **Nature of Claim:** TP **Claim No:** 5053784846SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No: | SMC143B | | |
| Make & Model: | TOYOTA PRIUS, 1.5 (A) | Engine No: | 2ZR8288451 |
| Reg. Date: | 25/06/2018 (Man. Year: 2017) | Chassis No: | ZVW506105325 |
| Colour: | White | Odometer: | 83091 km |
| Engine Capacity: | 1797 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|----------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Citicomfort 6 mm | Rear Left Side: | West Lake 6 mm |
| Front Right Side: | Citicomfort 6 mm | Rear Right Side: | West Lake 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 2,096.24 | 695.00 | 1,401.24 | 66.85 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,970.00 | 1,260.00 | 710.00 | 36.04 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 4,066.24 | 1,955.00 | 2,111.24 | 51.92 |
| + GST 7.00/7.00% (\$\$) | 284.64 | 136.85 | 147.79 | 51.92 |
| Nett Amount (\$\$) | 4,350.88 | 2,091.85 | 2,259.03 | 51.92 |
| + Loss of Use (7.0 x S\$100.00/day) (\$\$) | | 700.00 | | |
| + Doc/Search Fee (\$\$) | | 29.00 | | |
| Nett Liability (\$\$) | | 2,820.85 | | |
| Global Sum Settlement (\$\$) | | 2,820.00 | | |

INSPECTION

Date of Assignment: 05/12/2019

Date Inspected: 05/12/2019 Inspected At: Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------|---------------|-------------|------------|
| 1 | 1 | | *FRONT DOOR | Repair | 1,103.00 FL | * - FL |
| 2 | 1 | | *FRONT DOOR WEATHERSTRIP | Not Damaged | 183.30 FL | * - FL |
| 3 | 1 | | *FRONT DOOR OUTER HANDLE | Cut | 143.60 FL | *143.60 FL |
| 4 | 1 | | *FRONT WING MIRROR ASSY } | Broken | 567.40 FL | *676.40 FL |
| 5 | 1 | | *FRONT WING MIRROR GARNISH } | Broken | 109.00 FL | * - FL |
| 6 | 1 | | *FRONT DOOR OUTER GARNISH | Not Damaged | 189.00 FL | * - FL |
| 7 | 1 | | *SUNDRIES | Not Necessary | 80.00 FS | * - FS |
| 8 | 1 | | *FRONT DOOR SEALANT | Necessary | 120.00 FS | *50.00 FS |
| 9 | 1 | | *DOOR INNER TRIMBOARD CLIPS | Necessary | 60.00 FS | *30.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|---------------|
| Sub Total (\$) | 2,555.30 | 900.00 |
| - List Item Discount on L Items 20.00/25.00% (\$) | 459.06 | 205.00 |
| Total Parts (\$) | 2,096.24 | 695.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | PANEL BEATING | New | 800.00 | 500.00 |
| 2 | RUST PROOFING | New | 100.00 | 30.00 |
| 3 | R&R SIDE MIRROR (QUARTER GLASS) GARNISH | New | 150.00 | 80.00 |
| 4 | SPRAY PAINTING | New | 800.00 | 600.00 |
| 5 | CHECK WIRING | New | 120.00 | 50.00 |
| Gross Labour Cost (\$\$) | | | 1,970.00 | 1,260.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >