

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021502/UDS3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700054024

Claimant
Vehicle No : SMP7477Z **Insured Vehicle No :** SLR9251X

Date of Loss: 28/11/2019 Nature of Claim: TP Claim No: 2027089251SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7477Z	Engine No:	PE31337631
Make & Model:	MAZDA CX-3, 2.0 (A)	Chassis No:	JM6DK2W7AK0416187
Reg. Date:	29/08/2019 (Man. Year: 2018)	Odometer:	4556 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R18	Rear Tyre Size:	215/50 R18
Front Left Side:	Toyo 9 mm	Rear Left Side:	Toyo 9 mm
Front Right Side:	Toyo 9 mm	Rear Right Side:	Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,881.01	1,030.88	850.13	45.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,775.00	1,830.00	1,945.00	51.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,656.01	2,860.88	2,795.13	49.42
+ GST 7.00/7.00% (S\$)	395.92	200.26	195.66	49.42
Nett Amount (S\$)	6,051.93	3,061.14	2,990.79	49.42
+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)		385.20		
Nett Liability (S\$)		3,446.34		

INSPECTION

Date of Assignment: 04/12/2019

Date Inspected: 09/12/2019 Inspected At:

Trans Eurokars Pte Ltd (Sungei Kadut)
12 Sungei Kadut Ave
Singapore 729648

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,040.10 FL	*1,040.10 FL
2	1		*STAY ,REAR BUMPER	Not Necessary	52.20 FL	*- FL
3	1		*GUARD CENTER ,REAR BUMPER	Not Necessary	17.10 FL	*- FL
4	1		*REAR REINFORCEMENT	Not Necessary	362.80 FL	*- FL
5	2		*RETAINER CENTER ,SENSOR	Not Necessary	22.60 FL	*- FL
6	2		*SENSOR CENTER ,ULTRASONIC	Serviceable	401.00 FL	*- FL
7	2		*PAD PROTECTOR ,SENSOR	Necessary	15.60 FL	*15.60 FL
8	10		*FASTENER ,REAR BUMPER	Necessary	30.00 FL	*30.00 FL
9	6		*CLIP ,REAR BUMPER	Necessary	17.40 FL	*17.40 FL
10	6		*GROMMET ,REAR BUMPER	Necessary	16.20 FL	*16.20 FL
11	1		*PIN LOCATOR ,REAR BUMPER	Necessary	3.90 FL	*3.90 FL
12	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,078.90	1,143.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	197.89	112.32
Total Parts (\$\$)	1,881.01	1,030.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT .REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,260.00	630.00
2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT	New	1,200.00	600.00
3	TO TRANSFER REVERSE SENSORS	New	315.00	180.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	150.00
7	TO SUPPLY BRILA PREMIUM COATING	New	150.00	150.00
Gross Labour Cost (\$\$)			3,775.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >