

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19021504/KKS3S2**Date:** 10/03/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900102537
Claimant Vehicle No :	SMC4625B	Insured Vehicle No :	SLN8240E
Date of Loss:	26/11/2019	Nature of Claim:	TP
		Claim No:	7196778460SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC4625B		
Make & Model:	MERCEDES-BENZ CLA180, 1.6 AMG LINE (R18 BI (A)	Engine No:	27091031614001
Reg. Date:	29/06/2018 (Man. Year: 2018)	Chassis No:	WDD1173422N653563
Colour:	Metallic Pearl White	Odometer:	13053 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,203.60	20,111.40	7,092.20	26.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,670.00	4,030.00	640.00	13.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	31,873.60	24,141.40	7,732.20	24.26
+ GST 7.00/7.00% (S\$)	2,231.15	1,689.90	541.25	24.26
Nett Amount (S\$)	34,104.75	25,831.30	8,273.45	24.26

INSPECTION

Date of Assignment:	04/12/2019	
Date Inspected:	04/12/2019	Inspected At: MBM Wheelpower Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-15, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	21.0 days	

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/10/2020

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$5,834.40 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	2,200.00 FL	*2,200.00 FL
2	1		*REAR BUMPER TRIM	Missing	130.00 FL	*130.00 FL
3	1		*REAR BUMPER LOWER GARNISH	Missing	450.00 FL	*450.00 FL
4	1		*REAR BUMPER SIDE GARNISH LH	Serviceable	48.00 FL	*- FL
5	1		*REAR BUMPER SIDE GARNISH RH	Serviceable	48.00 FL	*- FL
6	1		*REAR BUMPER BOTTOM TRIM	Missing	380.00 FL	*380.00 FL
7	1		*REAR BUMPER TOWING COVER	Missing	55.00 FL	*55.00 FL
8	1		*REAR BUMPER BAND	*Check	8.00 FL	*- FL
9	1		*REAR BUMPER RETAINER	Cracked	135.00 FL	*135.00 FL
10	1		*REAR BUMPER SIDE BRACKET LH	Cracked	45.00 FL	*45.00 FL
11	1		*REAR BUMPER SIDE BRACKET RH	Cracked	45.00 FL	*45.00 FL
12	1		*REAR BUMPER SIDE RETAINER LH	Cracked	90.00 FL	*90.00 FL
13	1		*REAR BUMPER SIDE RETAINER RH	Cracked	90.00 FL	*90.00 FL
14	1		*REAR BUMPER SIDE MOUNTING RAIL LH	Cracked	35.00 FL	*35.00 FL
15	1		*REAR BUMPER SIDE MOUNTING RAIL RH	Cracked	35.00 FL	*35.00 FL
16	1		*REAR BUMPER BASIC CARRIER LH	*Check	45.00 FL	*- FL
17	1		*REAR BUMPER BASIC CARRIER RH	*Check	45.00 FL	*- FL
18	4		*REAR SENSOR DECOUPLING RING	Necessary	36.00 FL	*36.00 FL
19	4		*REAR DISTANCE SENSOR	Shorted 2pcs Only	1,200.00 FL	*600.00 FL
20	1		*REAR BUMPER MOUNTING PLATE	Necessary	10.00 FL	*10.00 FL
21	1		*REAR BUMPER WIRING HARNESS	*Check	220.00 FL	*- FL
22	12		*REAR BUMPER EXPANSION RIVET	Necessary	84.00 FL	*84.00 FL
23	1		*REAR SIDE WALL DAMPING LH	*Check	45.00 FL	*- FL
24	1		*REAR SIDE WALL DAMPING RH	*Check	45.00 FL	*- FL
25	1		*REAR BUMPER RIVET	Necessary	180.00 FL	*180.00 FL
26	1		*REAR FENDER LH	Buckled	3,100.00 FL	*3,100.00 FL
27	1		*REAR FENDER RH	Buckled	3,100.00 FL	*3,100.00 FL
28	1		*REAR FENDER INNER SHIELD LH	Distorted	255.00 FL	*255.00 FL
29	1		*REAR FENDER INNER SHIELD RH	Distorted	255.00 FL	*255.00 FL
30	1		*REAR SIDE BOTTOM PANEL LH	Bent	320.00 FL	*320.00 FL
31	1		*REAR SIDE BOTTOM PANEL RH	Bent	320.00 FL	*320.00 FL
32	1		*REAR SIDE VENT FLAP LH	Distorted	280.00 FL	*280.00 FL
33	1		*REAR SIDE VENT FLAP RH	Distorted	280.00 FL	*280.00 FL
34	1		*TANK COVER	*Check	110.00 FL	*- FL
35	1		*REAR BOOT LID	Bent	3,100.00 FL	*3,100.00 FL
36	1		*REAR BOOT LOCK	Jammed	320.00 FL	*320.00 FL
37	1		*REAR BOOT WEATHER STRIPE	Distorted / Cut	220.00 FL	*220.00 FL
38	1		*REAR BOOT RETAINER (NPA)	*Check	0.00 FL	*- FL
39	1		*REAR BOOT INNER LAYER	*Check	12.00 FL	*- FL
40	1		*REAR BOOT END STOPPER	Dented	18.00 FL	*18.00 FL
41	1		*REAR BOOT HINGE LH	Bent	45.00 FL	*45.00 FL
42	1		*REAR BOOT HINGE RH	Bent	45.00 FL	*45.00 FL
43	1		*REAR BOOT HINGE BRACKET LH	Distorted	160.00 FL	*160.00 FL
44	1		*REAR BOOT HINGE BRACKET RH	Distorted	160.00 FL	*160.00 FL
45	1		*REAR BOOT LAMP	*Check	60.00 FL	*- FL
46	1		*REAR TAIL LAMP LH	Broken	380.00 FL	*380.00 FL
47	1		*REAR TAIL LAMP RH	Broken	380.00 FL	*380.00 FL
48	1		*REAR REINFORCEMENT	Bent	1,550.00 FL	*1,550.00 FL
49	1		*CROSSMEMBER SEAL PLATE	*Check	90.00 FL	*- FL
50	2		*CROSSMEMBER NUT	*Check	12.00 FL	*- FL
51	1		*REAR END PANEL	Bent	1,900.00 FL	*1,900.00 FL
52	1		*REAR END TOP PANEL	Bent	920.00 FL	*920.00 FL
53	1		*REAR HEAT INSULATION (NPA)	Serviceable	0.00 FL	*- FL
54	1		*TAIL PIPE TRIM LH	Serviceable	320.00 FL	*- FL
55	1		*TAIL PIPE TRIM RH	Dented	320.00 FL	*320.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR SPRING LINK ARM LH	*Check	220.00 FL	*- FL
57	1		*REAR SPRING LINK ARM RH	*Check	220.00 FL	*- FL
58	1		*REAR WHEEL HUB LH	*Check	1,350.00 FL	*- FL
59	1		*REAR WHEEL HUB RH	*Check	1,350.00 FL	*- FL
60	1		*REAR TRAILING ARM LH	Bent	150.00 FL	*150.00 FL
61	1		*REAR TRAILING ARM RH	*Check	150.00 FL	*- FL
62	1		*REAR CONTROL ARM LH	Bent	155.00 FL	*155.00 FL
63	1		*REAR CONTROL ARM RH	*Check	155.00 FL	*- FL
64	1		*REAR CONTROL BEARING LH	*Check	40.00 FL	*- FL
65	1		*REAR CONTROL BEARING RH	*Check	40.00 FL	*- FL
66	1		*REAR TIE ROD LH	*Check	75.00 FL	*- FL
67	1		*REAR TIE ROD RH	*Check	75.00 FL	*- FL
68	1		*REAR TIE ROD BEARING LH	*Check	38.00 FL	*- FL
69	1		*REAR TIE ROD BEARING RH	*Check	38.00 FL	*- FL
70	1		*REAR SUSPENSION SUB-FRAME	*Check	2,850.00 FL	*- FL
71	1		*WHEEL RIM	Dented	2,600.00 FL	*2,600.00 FL
72	1		*BODY SEALANT	Necessary	80.00 FS	*80.00 FS
73	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
74	1		*REAR NUMBER PLATE WITH HOLDER	Dented	80.00 FS	*45.00 FS
75	1		*SET REVERSE SENSOR	Repeated	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	33,852.00	25,098.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,648.40	4,986.60
Total Parts (\$\$)	27,203.60	20,111.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	New	1,600.00	1,600.00
2	TO CHECK & RECONNECT ALL NECESSARY WIRING.	New	120.00	30.00
3	TO APPLY ANTI RUST COATING.	New	250.00	120.00
4	TO REMOVE & REFIT REAR WINDSCREEN.	New	150.00	120.00
5	TO CONDUCT CHASSIS ALIGNMENT.	New	120.00	80.00
6	TO REMOVE & INSTALL REVERSE SENSOR.	New	80.00	80.00
7	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS.	New	150.00	150.00
8	TO MOUNT UP TO CAR-O-LINER TO STRAIGHTEN REAR MAIN CHASSIS.	New	600.00	250.00
9	TO SPRAY PAINT ON AFFECTED AREAS.	New	1,600.00	1,600.00
Gross Labour Cost (\$)			4,670.00	4,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >