

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19021505/AEA3Q2

**Date:** 28/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994289

**Claimant**  
**Vehicle No :** SJJ1174D **Insured Vehicle No :** SJZ6397K

Date of Loss: 25/11/2019 Nature of Claim: TP Claim No: 7153452402SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ1174D		
Make & Model:	NISSAN LATIO, 1.5 L (A)	Engine No:	HR15252914A
Reg. Date:	01/09/2008 (Man. Year: 2007)	Chassis No:	JN1BAAC11Z0009297
Colour:	Black	Odometer:	112615 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,551.78	936.45	615.33	39.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	480.00	280.00	36.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,311.78</b>	<b>1,416.45</b>	<b>895.33</b>	<b>38.73</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,100.00</b>		
<b>(\$\$)</b>	2,311.78	1,100.00	1,211.78	52.42
<b>+ GST 7.00/7.00% (\$\$)</b>	161.82	77.00	84.82	52.42
<b>Nett Amount (\$\$)</b>	<b>2,473.60</b>	<b>1,177.00</b>	<b>1,296.60</b>	<b>52.42</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (\$\$)</b>		240.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>1,424.45</b>		

### INSPECTION

Date of Assignment: 02/12/2019

Date Inspected: 02/12/2019 Inspected At:

Success United Pte Ltd (HQ)  
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit  
AutoHub  
Singapore 417921

Estimated Period of Repair: 3.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Deformed	750.00 FN	*460.00 FN
2	10		*FRT BUMPER CLIPS	Necessary	31.00 FN	*31.00 FN
3	1		*FRT BUMPER SIDE HOLDER RH	Necessary	32.10 FN	*32.10 FN
4	1		*FRT BUMPER BRACKET RH	Not Necessary	22.00 FN	*- FN
5	1		*FRT BUMPER INNER SPONGE	Not Necessary	240.90 FN	*- FN
6	1		*HEADLAMP RH	Cracked	517.40 FN	*517.40 FN
7	1		*FRT FOGLAMP GARNISH	Not Necessary	130.80 FN	*- FN

F=Franchise part. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>1,724.20</b>	<b>1,040.50</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	172.42	104.05
<b>Total Parts (S\$)</b>	<b>1,551.78</b>	<b>936.45</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	60.00	30.00
2	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	350.00	250.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	350.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>760.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >