Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021508/AHA3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SMD8992J Insured Vehicle No: SML4356E

Date of Loss: 28/11/2019 Nature of Claim: TP Claim No: 5824567177SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD8992J

 Make & Model:
 HONDA ACCORD, 2.0 (A)
 Engine No:
 K20A6055335

 Reg. Date:
 10/10/2008 (Man. Year: 2008)
 Chassis No:
 CL73304640

 Colour:
 White
 Odometer:
 141768 km

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
3,760.14	2,646.02	1,114.12	29.63
0.00	0.00	0.00	
2,680.00	1,290.00	1,390.00	51.87
0.00	0.00	0.00	
0.00	0.00	0.00	
6,440.14	3,936.02	2,504.12	38.88
	3,100.00		
6,440.14	3,100.00	3,340.14	51.86
450.81	217.00	233.81	51.86
6,890.95	3,317.00	3,573.95	51.86
30.00/day) (S\$)	480.00		
+ Medical Costs (S\$) + Doc/Search Fee (S\$) Nett Liability (S\$) Global Sum Settlement (S\$)			
	3,760.14 0.00 2,680.00 0.00 0.00 6,440.14 450.81 6,890.95 30.00/day) (\$\$) (cal Costs (\$\$) earch Fee (\$\$)	3,760.14 2,646.02 0.00 0.00 2,680.00 1,290.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	3,760.14 2,646.02 1,114.12 0.00 0.00 0.00 0.00 2,680.00 1,290.00 1,390.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0

INSPECTION

Date of Assignment: 02/12/2019

Date Inspected: 02/12/2019 Inspected At: Success United Pte Ltd (HQ)

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit

AutoHub

Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*REAR BUMPER ASSY	Deformed	1,050.00 FL	*1,050.00 FL		
2	12		*REAR BUMPER CLIPS	Necessary	78.00 FL	*78.00 FL		
3	2		*REAR BUMPER SIDE HOLDER L/R	Necessary	85.00 FL	*85.00 FL		
4	2		*REAR BUMPER BRACKET L/R	Not Necessary	55.20 FL	*-FL		
5	1		*REAR END PANEL	Dented	550.60 FL	*550.60 FL		
6	2		*REAR BUMPER REFLECTOR LAMP L/R	Not Necessary	150.00 FL	*-FL		
7	1		*REAR END PANEL INNER TOP GARNISH	Deformed	158.60 FL	*158.60 FL		
8	2		*REAR LAMP L/R	N/S Cracked / O/S Cut	713.60 FL	*713.60 FL		
9	1		*REAR BOOT LID LAMP L/R	O/S Cut	630.00 FL	*315.00 FL		
10	1		*REAR BOOT LID WEATHERSTRIP	Not Necessary	151.00 FL	*-FL		
11	1		*REAR BOOT LID MECHANISM LOCK	Not Necessary	218.00 FL	*- FL		
12	2		*REAR BOOT HINGE L/R	Not Necessary	97.20 FL	*-FL		
13	1		*REAR BOOT LID HONDA LOGO	Necessary	52.40 FL	*52.40 FL		
14	1		*REAR BOOT LID ACCORD EMBLEM	Necessary	54.32 FL	*54.32 FL		
15	1		*SET REVERSE SENSOR	Damaged	480.00 FS	*200.00 FS		
16	1		*SET REAR NO.PLATE W/FRAME	Not Necessary	45.00 FS	*-FS		
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.					
				Sub Total (S\$)		3,257.52		
	- List Item Discount on L Items 20.00/20.00% (\$\$) 808.78 611.					611.50		
				Total Parts (S\$)	3,760.14	2,646.02		
	Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO REMOVE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	80.00	30.00
TO REMOVE, REINSTAL UPHOLSTRY, INNER TRIM GARNISHES & SPOILER	New	400.00	60.00
TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	600.00
TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,000.00	600.00
Gross Labour Cost (S\$)		2,680.00	1,290.00
	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING TO REMOVE,REINSTAL UPHOLSTRY ,INNER TRIM GARNISHES & SPOILER TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	TO REMOVE ,REARRANGE ELECTRICAL New WIRINGS ,CHECK LIGHTING TO REMOVE,REINSTAL UPHOLSTRY ,INNER TRIM New GARNISHES & SPOILER TO REMOVE,REPAIR AND REPLACED DAMAGED New BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT TO PUTTY AND RESPRAY PAINTING ON AFFECTED New AREA	TO REMOVE ,REARRANGE ELECTRICAL New 80.00 WIRINGS ,CHECK LIGHTING TO REMOVE,REINSTAL UPHOLSTRY ,INNER TRIM New 400.00 GARNISHES & SPOILER TO REMOVE,REPAIR AND REPLACED DAMAGED New 1,200.00 BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT TO PUTTY AND RESPRAY PAINTING ON AFFECTED New 1,000.00 AREA

< END OF ESTIMATES >

Report was unsubmitted during this print-out.