Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19021511/QEA3Q2

Date: 05/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No: SHD6434B Insured Vehicle No: SME8734H

Date of Loss: 02/12/2019 Nature of Claim: TP Claim No: 4499228765SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD6434B

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZR8256581

Reg. Date: 12/12/2017 (Man. Year: 2017) Chassis No: JTDKB3FU303576274

Colour: Maroon Odometer: 355224 km

Engine Capacity: 1798 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm
Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,621.80	964.52	4,657.28	82.84
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,163.00	520.00	1,643.00	75.96
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	7,784.80	1,484.52	6,300.28	80.93
	+ Loss of Use (3.0 x	S\$50.00/day) (S\$)	150.00		
	+ Car Rental (3.0 x S	\$118.24/day) (S\$)	354.72		
	+ Do	c/Search Fee (S\$)	7.00		
		Nett Liability (S\$)	1,996.24		

INSPECTION

Date of Assignment: 04/12/2019

Date Inspected: 04/12/2019 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN Manager: Asher Sng Rong Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%)	Necessary	1.50 F	*1.13 F
2	1		*GUARD ,RR BUMPER ,LOWER (DISC 25%)	Dented	558.30 F	*418.73 F
3	1		*FILLER RR BUMPER ,RH (DISC 25%)	Dented	119.90 F	*89.93 F
4	1		*COVER ,RR BUMPER ASSY (DISC 25%)	Dented	423.90 F	*317.93 F
5	1		*SEAL ,RR BUMPER ARM ,RH & LH (DISC 25%) (2 PCS)	Necessary	11.00 F	*8.25 F
6	1		*PAD ,RR BUMPER ,RH & LH ,1 (DISC 25%) (2 PCS)	Necessary	3.80 F	*2.85 F
7	1		*PAD ,RR BUMPER ,RH & LH ,2 (DISC 25%) (2 PCS)	Necessary	3.80 F	*2.85 F
8	1		*PAD ,RR BUMPER ,RH & LH ,3 (DISC 25%) (2 PCS)	Necessary	3.80 F	*2.85 F
9	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
10	1		*FILLER ,RR BUMPER ,LH	Serviceable	119.90 F	*- F
11	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
12	1		*COVER ,REAR FLOOR UNDER ,RH	Serviceable	169.50 F	*- F
13	1		*COVER ,REAR FLOOR UNDER ,RH	Serviceable	234.30 F	*- F
14	1		*COVER ,REAR FLOOR UNDER CENTER	Serviceable	222.60 F	*- F
15	1		*ANTENNA ,ELECTRICAL KEY	Serviceable	60.30 F	*- F
16	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Serviceable	438.10 F	*- F
17	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH	Serviceable	438.10 F	*- F
18	1		*LENS & BODY ASSY ,RR BUMPER RH	Serviceable	486.80 F	*- F
19	1		*LENS & BODY ASSY ,RR BUMPER LH	Serviceable	486.80 F	*- F
20	1		*PANEL SUB-ASSY ,FENDER REAR LH	Serviceable	824.80 F	*- F
21	1		*REAR BUMPER REINFORCEMENT	Serviceable	318.80 F	*- F
22	1		*RETAINER ,RR BUMPER ,RH	Serviceable	112.70 F	*- F
23	1		*RETAINER ,RR BUMPER ,LH	Serviceable	112.70 F	*- F
24	1		*SEAL ,RR BUMPER ,RH	Serviceable	85.20 F	*- F
25 E=Ers	1 anchise	nart	*SEAL ,RR BUMPER ,LH	Serviceable	85.20 F	*- F
1 -116		puit.		Total Parts (S\$)	5,621.80	964.52

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING & BODY WORK	New	507.00	200.00
2	SPRAY PAINT	New	1,296.00	280.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
4	TO REPLACE SUNDRY PARTS	New	100.00	20.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
6	TO WASH AND VACUUM	New	60.00	0.00
	Gross La	bour Cost (S\$)	2,163.00	520.00
	Report was unsubmitted	during this print-out		

< END OF ESTIMATES >