VEHICLE NO **SLE 2837X**

HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
1 1 1 1 1 1 2 1 1 1 1 1 1 1 1	PARTS (LIST ITEMS) LHS Front Fender LHS Front Fender wheel arch garnish LHS Front Fender Inner splash Shield Front Bumper Front Bumper fog lamp cover LHS Front Bumper fog lamp LHS Front Bumper lower skirt Front Bumper side retainers RHS & LHS LHS Headlamp LHS Headlamp lower bracket SPECIAL NETT ITEMS LHS Front fender inner shield clips Front bumper clips	762	980.00 283.00 1 267.00 267.00 1428.00 1 428.00 1 142.00 1 142.00 1 1280.00 1 1280.00 1 248.00 248.00 248.00 248.00 4864.00	X X X X Y Z 20%
1set	Front fender wheel arch LH clips LHS Front sports rim	TOTAL PARTS	11 60.00 11 60.00 1 980.00	X

Not Allow 1 1/5 4 2 100.

P-1806.00 \(\frac{\lambda^2}{0^2}\)
\(\frac{\lambda^2}{\lambda}\)
\(\frac{\lambda^2}{\lambda}\)
\(\frac{\lambda}{\lambda}\)
\(\frac{\lambda}{

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illeg a modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO SLE 2837X HONDA VEZEL

s/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1000.00	250
2	To supply paint materials, expandable items & putty,	600.00	400
	respray paint on parts replaced (PEARL WHITE)	(17)	-
3	To check wiring and focus headlamp beam	150.00	20
4	To carry out anti rust treatment on affected areas	120.00	NAX
5	To conduct full computerised wheel alignment test	120.00	nnx
	Labour Total :	1990.00	
TOTAL (PARTS & LABOUR):		8004.00	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts