



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFM 2001U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER SIDE GRILLE (LH) (CONSISTENT)	CUT	180.00	180.00
1	FRONT BONNET LOCK (CONSISTENT)	NOT NECESSARY	380.00	-
1	FRONT BONNET INNER RUBBER (CONSISTENT)	NOT NECESSARY	68.20	-
1	FRONT BONNET OUTER RUBBER (CONSISTENT)	NOT NECESSARY	86.20	-
1	FRONT BUMPER INNER SPONGE (CONSISTENT)	NOT NECESSARY	135.90	-
1	FRONT BUMPER SIDE RETAINERS (LH/RH) (CONSISTENT)	BROKEN	145.20	145.20
1	FRONT HEADLAMP LOWER BRACKET (CONSISTENT)	NOT NECESSARY	186.00	-
1	FRONT GRILLE CHROME MOULDING (CONSISTENT)	NOT NECESSARY	285.90	-
1	FRONT GRILLE LOGO (CONSISTENT)	NOT NECESSARY	188.80	-
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	628.60	-
2	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	680.60	-
1	L/H MUD FLAP (CONSISTENT)	NOT NECESSARY	160.00	-
1	L/H HEADLIGHT (CONSISTENT)	CUT	660.00	660.00
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	950.00	-
1	FRONT BUMPER (CONSISTENT)	BROKEN	880.00	630.00
1	CAR PLATE AND CARPLATE HOLDER (CONSISTENT)	NOT NECESSARY	190.00	-
1	FRONT SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,670.00	-
1	FRT FEND LH (CONSISTENT) (ADDITIONAL)	DENTED	837.60	837.60
1	FRT LH RIM FENDER (CONSISTENT) (ADDITIONAL)	TORN	165.93	165.93
	LESS 25% DISCOUNT		-	-654.68
			8,478.93	1,964.05
<u>LABOUR</u>				
	TO ESTABLISH MIRROR MOTOR & RESET WIRING FOCUSING.		210.00	30.00
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.	NOT NECESSARY	320.00	-
	TO APPLY TUFF KOTE.		330.00	30.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BONNET AND FRONT SUPPORT PANEL.		800.00	500.00

Report Ref No. CC4/ASM19021521/Ega3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SAND-DOWN, PATCH-WORK, RE-SPRAY PAINT.		800.00	600.00
			2,460.00	1,160.00
GRAND TOTAL			10,938.93	3,124.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CC4/ASM19021521/Ega3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.