



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 5464U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT LH SIGNAL	CUT	75.00	75.00
1	HANDLE BAR	BENT	80.00	80.00
1	CLUTCH LEVER	CUT	65.00	65.00
1	HANDLE BAR EXTENSION BRACKET	BENT / BROKEN	50.00	50.00
1	BALANCER -BAR-END	BENT	35.00	35.00
1	HEAD LAMP ASSY	SCRATCHED	360.00	360.00
1	HEAD LAMP HOLDER	SCRATCHED	50.00	50.00
1	FRONT MUDGUARD	BROKEN	80.00	80.00
1	FRONT RIM	DENTED / DISTORTED	360.00	360.00
1	BRAKE DISC	DISTORTED	160.00	160.00
1	SET FORK TUBE	BENT	1,040.00	1,040.00
1	FORK UNDER BRACKET	DAMAGED	160.00	160.00
1	FRONT SIDE COVER L/RH	CUT / BROKEN	70.00	70.00
2	TANK COVER	BROKEN	90.00	90.00
1	FUEL TANK	DENTED	600.00	600.00
1	RADIATOR ASSY	BENT	350.00	350.00
1	FAN MOTOR ASSY	BROKEN	150.00	150.00
1	REAR LH SIDE PANEL	BROKEN / CUT	65.00	65.00
1	RH FRAME CENTRE COVER	BROKEN / CUT	65.00	65.00
1	RH ENGINE LOWER COVER	BROKEN / CUT	55.00	55.00
1	SIGNAL LIGHT HOLDER	BROKEN	78.00	78.00
	LESS 10% DISCOUNT		-403.80	-403.80
			3,634.20	3,634.20
	<u>SPECIAL NETT ITEMS</u>			
1	METER ASSY (SN)	CUT / BROKEN	520.00	520.00
1	FRONT NUMBER PLATE (SN)	MISSING	15.00	15.00
			535.00	535.00
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	40.00	-

Report Ref No. CC4/FCI19021525/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RE-ALIGN BODY ALIGNMENT.		350.00	80.00
	REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC.		280.00	200.00
	REMOVE & REPLACE FORK ASSY ,BRAKE DISC, FRONT RIM & RE-ALIGN & ETC.		250.00	80.00
	RE-CHECK HARNESS WIRING.		60.00	30.00
	TO RESPRAY & TOUCH UP PAINT WORK.		250.00	150.00
	REMOVE REFIT ENGINE TO FACILITATE REPAIR TO BODY ALIGNMENT.	NOT NECESSARY	200.00	-
			1,430.00	540.00
GRAND TOTAL			5,599.20	4,709.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CC4/FCI19021525/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.