

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 9857M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TRUNK LID (SN)	BUCKLED	1,914.28	1,914.28
1	SPOILER SATIN BLACK LHR (SN)	NECESSARY	242.77	242.77
1	SPOILER SATIN BLACK RHR (SN)	NECESSARY	242.77	242.77
1	PUSHBUTTON FOR ELECTRIC L (SN)	NOT NECESSARY	1,324.00	-
2	1K WINDOW ADHESIVE (SN)	NECESSARY	99.76	99.76
1	ADHESIVE REMOVER (SN)	NECESSARY	115.74	115.74
1	PRIMER (SN)	NECESSARY	25.92	25.92
2	APPLICATOR (SN)	NECESSARY	18.96	18.96
1	ACTIVATOR FOR PRECOATED W (SN)	NECESSARY	24.00	24.00
1	GASKET WEATHERSTRIP (SN)	NOT NECESSARY	285.78	-
1	VW SIGN BLACK / BRIGHT CHRO (SN)	NECESSARY	89.76	89.76
1	INSCRIPTION BRIGHT CHROME TOURAN (SN)	NECESSARY	58.66	58.66
1	COVER FOR BUMPER PRIMED REAR BUMPER (SN)	DEFORMED	1,139.96	1,139.96
1	SPOILER SATIN BLACK (SN)	CUT	273.34	273.34
1	BUMPER REINFORCEMENT (SN)	NOT NECESSARY	442.56	-
1	ATTACHMENT STRIP RR CTR BRACKET (SN)	NOT NECESSARY	55.98	-
1	GUIDE PIECE LHR SIDE BRACKET (SN)	NOT NECESSARY	29.49	-
1	GUIDE PIECE RHR SIDE BRACKET (SN)	NOT NECESSARY	29.49	-
1	GUIDE PIECE LHR TAILLIGHT BRACKET (SN)	NOT NECESSARY	36.27	-
1	GUIDE PIECE RHR TAILLIGHT BRACKET (SN)	NOT NECESSARY	36.27	-
1	EXHAUST SILENCER REAR (SN)	NOT NECESSARY	1,078.62	-
1	DUAL CLAMP (SN)	NOT NECESSARY	55.54	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	400.00	-
1	PACKING ADHESICE (SN) (ADDITIONAL)	NECESSARY	27.03	27.03
2	RIVETTED CAP NUT (SN) (ADDITIONAL)	NECESSARY	3.76	3.76
			8,050.71	4,276.71
	<u>LABOUR</u>			
	DIAGNOSTIC AND PROGRAMMING.		480.00	480.00
	CHECK SHORT CIRCUIT / HARNESS REPAIR.		280.00	280.00
	LABOUR.		4,200.00	1,680.00

Report Ref No. CS/SMO19021527/Gyf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	R&R REAR WINDSCREEN.	NOT NECESSARY	840.00	840.00
	R&R REAR EXHAUST.		840.00	-
	TRANSFER BOOTLID MECHANISM.		840.00	420.00
	SPRAY PAINTING.		4,000.00	1,600.00
			11,480.00	5,300.00
GRAND TOTAL			19,530.71	9,576.71
RECOMMENDED COST OF REPAIRS				9,576.71

Report Ref No. CS/SMO19021527/Gyf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.