

27/03/2002

ASS. REC. BY:

REF: CS/FC19021539/USF302

Special Instruction:

Surveyor: namus

ASSIGNMENT (Office)

From (Person): Rachel Ann Linn of FC1 Date/Time: 5.12.19 5.48pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SME 1335Y Insured: SHB 35805at Workshop m/s Automobile Hub Tel: 97864483of 1 Kaki Bukit Ave 6 # 02 11Policy No: _____ Claim No: D19007690MPSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 6.12.19 9.20am Person Contacted: Alfred H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SHB 35805 NA/INC 19021395/24 D.O.A. 03/12/2019

SME 1335Y NA/INC 19021395/24 D.O.A. 03/12/2019

10/12/19 @ 16:31pm revised PA to Rachel via email

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

0764

Vehicle: IN / OUT

Veh No:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/12/19 LTA 36590 lawyer case
 1/5 \$5000 conf. with AH Xiong
 (\$11,394.28 Red - 70%)

RECEIVED 27 01 2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 5,000/- 45)

6x15=90

170+90

50

50

64

424



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007690MFSH

Date: 10 December 2019

Our Ref: CS/FCI19021539/Usf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SME 1335Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/12/2019 at the premises of M/s Automobile Hub Enterprise and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 16,394.28</u> .
Revised Estimate Amount	: <u>S\$ 6,257.16</u> .
"Check" Items Amount	: <u>S\$ -</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.


Comments/ Present Status:

Damages Consistent.

Repair days: 5 days

Yours faithfully

Marcus Chua
Automotive Assessor



MOTOR SURVEY ASSIGNMENT

Date	04-12-2019	Our Ref No. D19007690MFSH
Accident Date	03-12-2019	Claim Type. Third Party
Insured Vehicle	SHB3580S	Third Party Vehicle. SME1335Y
Survey Location	1 KAKI BUKIT AVE 6 #02-11 AUTOBAY @ KAKI BUKIT	
Contact Person.	ALFRED NG	
Contact No.	97864483/ 97864483	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AUTOMOBILE HUB ENTERPRISE	Attention. NIL
Cc : TP Solicitor	JUSEQUITY LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	RACHELWU LIMEI	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 10 December 2019 4:31 pm
To: 'Rachel Wu'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19007690MFSH/1
Attachments: PRELI ADVISE - SME 1335Y.pdf

Dear Rachel,

Enclosed preliminary revised of vehicle SME 1335Y.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 6 December 2019 9:24 am
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Rachel Wu' <RachelWu@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007690MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Thursday, 5 December, 2019 5:48 PM

New Cars

Used Cars

Sell My Car


Directory

Products

Insurance

Articles

Forum



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Hot Alfa Romeo Hatch!



It's An Alfa!

Direct Owner

StarAd

ABWIN

ONE-STOP



Browse by Category

« Back (1 2) Next »

Sort by Date Posted

25 vehicles

Honda Shuttle

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	Honda Shuttle		Any	Any	2018	Any	Any	Any

**Honda Shuttle Hybrid 1.5A X****\$83,800****\$8,950 /yr****30-Jun-2018****1,496 cc****31,888 km****Stationwagon****Fuel Type:** Petrol-Electric

Almost New 2018 New Facelifted Honda Vezel Hybrid. Best Fuel Consumption SUV In Town. 10 Years Repayment, In House Loan Or Balloon Scheme Available. Make And Assemble In Japan. Call Now And View To Appreciate.

Autotruster Traders Pte Ltd

Posted: 05-Dec-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A****\$82,800****\$8,840 /yr****14-Sep-2018****1,496 cc****40,888 km****Stationwagon****Fuel Type:** Petrol-Electric

100% Loan Available. Immediate Transfer Of Ownership Upon Collection. 1 Owner. Reasonable Mileage Done. Beautiful Blue On Grey Interior. Comes With 1 Year Warranty Inclusive Of Hybrid Battery Upon Purchase. Please Call For Viewing/Test Drive Now.

Esteem Performance Pte Ltd

Posted: 05-Dec-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle 1.5A G****\$71,000****\$8,050 /yr****23-Mar-2018****1,496 cc****-****Stationwagon**

Best Fuel Efficient Stationwagon In Town. Almost New Honda Shuttle. Selling Cheap! Drive With Assurance! Genuine And Transparent Deal! Bank/In House Up To 100% Loan.

Car Empire Automobiles Pte Ltd

Posted: 04-Dec-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle 1.5A G****\$70,800****\$7,960 /yr****13-Mar-2018****1,496 cc****27,000 km****Stationwagon**

One Owner Only. Showroom Condition. Buy With Peace Of Mind. Low Down Payment, Low Interest Rate. Call/SMS For More Details.

Posted: 03-Dec-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**D1 Spec Throttle Controller Selling @ \$180**

Suitable for electronic throttle car with specific cable set from \$180.

More info about this product

Compare

1a Shuttle Hybrid 1.5A**\$76,000****\$8,640 /yr****28-May-2018****1,496 cc****-****Stationwagon****e: Petrol-Electric**

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	076A
Vehicle Details	
Vehicle No.:	SME1335Y
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	LEB6559618
Chassis No.:	GP71216139
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,766.00
Original Registration Date:	19 Sep 2018
First Registration Date:	19 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$12,473.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Sep 2028
PARF Rebate Amount:	\$9,354.00
Intended COE Rebate Details	
COE Expiry Date:	18 Sep 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$31,001.00
COE Rebate Amount:	\$27,236.00
Total Rebate Amount:	\$36,590.00

The information contained herein is correct as at 05 Dec 2019

OK


Automobile Hub Enterprise

$\frac{2}{5} \times 5000$

Claim Type: TP

VRN: SME1335Y

not authorized
date
Telephone After repair
5-27.



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate	1	\$ 1,950.00	\$ 1,950.00
2	Tailgate lock	1	\$ 285.00	\$ 285.00
3	Tailgate lock sensor	1	\$ 320.00	\$ 320.00
4	Tailgate weatherstrip	1	\$ 221.00	\$ 221.00
5	Tailgate 'HONDA' logo	1	\$ 99.70	\$ 99.70
6	Tailgate 'SHUTTLE' emblem	1	\$ 79.80	\$ 79.80
7	Tailgate inner trim	1	\$ 745.00	\$ 745.00
8	Tailgate chrome moulding	1	\$ 385.00	\$ 385.00
9	Tailgate lamp	2	\$ 590.00	\$ 1,180.00
10	Rear windscreen moulding	1	\$ 194.00	\$ 194.00
11	Rear bumper	1	\$ 1,299.30	\$ 1,299.30
12	Rear bumper side retainer	2	\$ 76.00	\$ 152.00
13	Rear bumper bracket	2	\$ 68.00	\$ 136.00
14	Rear bumper reinforcement	1	\$ 691.70	\$ 691.70
15	Rear bumper sponge	1	\$ 161.50	\$ 161.50
16	Rear bumper reflector	2	\$ 199.20	\$ 398.40
17	Rear bumper reflector garnish	2	\$ 200.70	\$ 401.40
18	Rear bumper tow cover	1	\$ 69.50	\$ 69.50
19	Taillamp	2	\$ 689.00	\$ 1,378.00
20	Taillamp panel	2	\$ 165.00	\$ 330.00
21	Smart buzzer sensor	1	\$ 269.00	\$ 269.00
22	Rear antenna sensor	1	\$ 281.70	\$ 281.70
23	End panel	1	\$ 685.00	\$ 685.00
24	End panel top garnish	1	\$ 284.00	\$ 284.00
25	Tailgate hinge	2	\$ 135.00	\$ 270.00
26	Tailgate absorber	2	\$ 177.00	\$ 354.00
27	Tailgate stopper	2	\$ 16.00	\$ 32.00
28	Rear fender inner trim	2	\$ 476.00	\$ 952.00
29	Exhaust assy	1	\$ 797.00	\$ 797.00
30	Exhaust assy gasket	1	\$ 34.00	\$ 34.00
31	Exhaust assy mounting	2	\$ 45.00	\$ 90.00
32	Exhaust assy heatshield	1	\$ 210.60	\$ 210.60
Subtotal				\$ 14,736.60
List discount				20.00%
Total				\$ 11,789.28

Repair Estimate

S.N

u1 X
u2 ✓
u3 X
u4 X
u5 50 S.N
u6 40 S.N
u7 200 S.N
u8 X
u9 X
u10 X
u11 X

800
20
60
mx
120
1100
80

Estimate Grand Total	\$	16,394.28
----------------------	----	-----------

LKK Auto Consultants hence notify the Repairer of the following:

Acknowledged by Repairer

P-4677.70

202

2- 3742.16

S.N-335.00

4-2180.00

6257.16

5004



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19021539/Usf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 31-12-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3580S	Veh. Inspected	SME 1335Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007690MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU LIMEI	Assign Date	05/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71216139	Colour	WHITE	
Odometer	80775	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2019	Inspection Date	06/12/2019	
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 1335Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BADLY DENTED	1,950.00	1,250.00
1	TAILGATE LOCK	SHORTED	285.00	285.00
1	TAILGATE LOCK SENSOR	NOT NECESSARY	320.00	-
1	TAILGATE WEATHERSTRIP	TWISTED	221.00	221.00
1	TAILGATE "HONDA" LOGO	NECESSARY	99.70	38.50
1	TAILGATE "SHUTTLE" EMBLEM	NECESSARY	79.80	79.80
1	TAILGATE INNER TRIM	NOT NECESSARY	745.00	-
1	TAILGATE CHROME MOULDING	NOT NECESSARY	385.00	-
2	TAILGATE LAMP @\$590.00	NOT NECESSARY	1,180.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	194.00	194.00
1	REAR BUMPER	DENTED / DEFORMED	1,299.30	1,120.20
2	REAR BUMPER SIDE RETAINER @\$76.00	NOT NECESSARY	152.00	-
2	REAR BUMPER BRACKET @\$68.00	NOT NECESSARY	136.00	-
1	REAR BUMPER REINFORCEMENT	NO SUCH PARTS	691.70	-
1	REAR BUMPER SPONGE	NO SUCH PARTS	161.50	-
2	REAR BUMPER REFLECTOR @\$199.20	NOT NECESSARY	398.40	-
2	REAR BUMPER REFLECTOR GARNISH @\$200.70	NOT NECESSARY	401.40	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	69.50	-
2	TAILLAMP @\$689.00	N/S CRACKED	1,378.00	520.20
2	TAILLAMP PANEL @\$165.00	TO REPAIR SEE LABOUR	330.00	-
1	SMART BUZZER SENSOR	NOT NECESSARY	269.00	-
1	REAR ANTENNA SENSOR	NOT NECESSARY	281.70	-
1	END PANEL	DENTED	685.00	685.00
1	END PANEL TOP GARNISH	TWISTED	284.00	284.00
2	TAILGATE HINGE @\$135.00	NOT NECESSARY	270.00	-
2	TAILGATE ABSORBER @\$177.00	NOT NECESSARY	354.00	-
2	TAILGATE STOPPER @\$16.00	NOT NECESSARY	32.00	-
2	REAR FENDER INNER TRIM @\$476.00	NOT NECESSARY	952.00	-
1	EXHAUST ASSY	NOT NECESSARY	797.00	-

Report Ref No. CS/FC119021539/Usf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST ASSY GASKET	NOT NECESSARY	34.00	-
2	EXHAUST ASSY MOUNTING @\$45.00	NOT NECESSARY	90.00	-
1	EXHAUST ASSY HEATSHIELD	NOT NECESSARY	210.60	-
	LESS 20% DISCOUNT		-2,947.32	-935.54
			11,789.28	3,742.16
	SPECIAL NETT ITEMS			
8	TAILGATE INNER TRIM CLIPS @\$4.50 (SN)	NOT NECESSARY	36.00	-
10	REAR BUMPER CLIPS @\$4.50 (SN)	NECESSARY	45.00	45.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	450.00	-
1	REAR LICENCE PLATE & FRAME (SN)	NOT NECESSARY	55.00	-
1	END PANEL SEALANT (SN)	NECESSARY	80.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	TAILLAMP PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
6	END PANEL TOP GARNISH CLIPS @\$4.50 (SN)	NOT NECESSARY	27.00	-
16	REAR FENDER INNER TRIM CLIPS @\$4.50 (SN)	NOT NECESSARY	72.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			1,255.00	335.00
	LABOUR			
	TO DISMANTLE/RENEW AACCIDENT DAMAGED PORTION,TO PANEL BEAT,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS,INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL.		1,400.00	800.00
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS.		50.00	20.00
	TO REMOVE,REFIT TAILGATE COMPONENTS TO REPLACE TAILGATE,CHECK AND RE-ADJUST CLOSE GAP,ALIGNMENT AND WATER SEEPAGE.		100.00	60.00
	TO REMOVE AND REFIT,STRAIGHTEN,READJUST AND REPLACE EXHAUST SILENCER.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR WORK.		150.00	120.00

Report Ref No. CS/FCI19021539/Usf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY TAILGATE, REAR BUMPER, END PANEL AND OTHER AFFECTED AREA/PANEL.		1,400.00	1,100.00
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.		100.00	80.00
			3,350.00	2,180.00
GRAND TOTAL			16,394.28	6,257.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS/FC119021539/Usf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.