Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021546/FKA3Q2

Date: 09/07/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700019536-02 Claimant Insured Vehicle No: SCP9033B SHC8506U

Vehicle No:

Date of Loss: 05/12/2019 Nature of Claim: TP Claim No: 1549686174SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SHC8506U Reg No:

Make & Model: HYUNDAI 140, 1.7 D (A) Engine No: D4FDFU580576

Reg. Date: 07/01/2016 (Man. Year: 2015) Chassis No: KMHLB41UMGU083051

Colour: Odometer: 622716 km Blue

**Engine Capacity:** 1685 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm Front Right Side: Rear Right Side: West Lake 7 mm West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		909.54	0.00	909.54	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		730.00	440.00	290.00	39.73
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Gross Total	I (S\$)	1,639.54	440.00	1,199.54	73.16
+ GST 7.00/7.00%	s (S\$)	114.77	30.80	83.97	73.16
Nett Amount	t (S\$)	1,754.31	470.80	1,283.51	73.16
+ Loss of U	se (2.5 x S\$	50.00/day) (S\$)	125.00		
+ Car Renta	al (2.5 x S\$1 <sup>,</sup>	12.67/day) (S\$)	281.68		
	+ Doc/S	earch Fee (S\$)	7.49		
	Ne	tt Liability (S\$)	884.97		
G	lobal Sum S	Settlement (S\$)	850.00		

**INSPECTION** 

Date of Assignment: 05/12/2019

ComfortDelGro Engineering Pte Ltd Date Inspected: 06/12/2019 Inspected At:

(Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days Adjuster Report Page 2 of 4

Adjuster: PARASURAM SHANMUGAM Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	553.00 FL	*- FL
2	10		*REAR BUMPER CLIP	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER UNDER COVER	Not Necessary	228.00 FL	*- FL
4	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
5	1		*REAR BUMPER REFLECTOR LAMP (RH)	Not Necessary	30.60 FL	*- FL
6	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	135.70 FS	*- FS
7	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc.	*		
				Sub Total (S\$)	1,090.50	0.00
- List Item Discount on L Items 20.00/20.00% (S\$)				180.96	0.00	
				Total Parts (S\$)	909.54	0.00
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	350.00	240.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	WIRING CHARGE	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	0.00
		Gross Labour Cost (S\$)	730.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >