

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19021550/GGA3Q2

Date: 26/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SKQ772K	Insured Vehicle No :	SHC2644T
Date of Loss: 03/12/2019	Nature of Claim: TP	Claim No: MCT19120059

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ772K		
Make & Model:	NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)	Engine No:	HR16950729B
Reg. Date:	31/10/2014 (Man. Year: 2014)	Chassis No:	MNTBBAB17Z0020865
Colour:	White	Odometer:	80949 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,625.52	1,355.69	1,269.83	48.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	640.00	530.00	45.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,795.52	1,995.69	1,799.83	47.42
+ GST 7.00/7.00% (S\$)	265.69	139.70	125.99	47.42
Nett Amount (S\$)	4,061.21	2,135.39	1,925.82	47.42
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,677.84		
Global Sum Settlement (S\$)		2,600.00		

INSPECTION

Date of Assignment:	05/12/2019	
Date Inspected:	05/12/2019 Inspected At:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2020)
Parts:	143	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ772K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	687.00 FN	*574.30 FN
2	1		*REAR BUMPER CLIPS	Necessary	31.20 FN	*31.20 FN
3	1		*REAR BUMPER BRACKET RH	Bent	96.10 FN	*78.50 FN
4	1		*REAR BUMPER SPONGE (CENTER)	Cracked	146.00 FN	*78.60 FN
5	1		*REAR BUMPER SPONGE (SIDE)	Cracked	85.10 FN	*68.00 FN
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	385.00 FN	*- FN
7	1		*REAR BUMPER REFLECTOR RH	Cracked	102.00 FN	*45.00 FN
8	1		*REAR BUMPER AUTO BOOT SENSOR	Damaged	245.00 FN	*155.90 FN
9	1		*BOOT EMBLEM	Necessary	110.00 FN	*45.00 FN
10	1		*BOOT BADGE SYLPHY	Necessary	95.60 FN	*42.00 FN
11	1		*BOOT XTRONIC CVT	Necessary	89.80 FN	*45.60 FN
12	1		*BOOT OUTER LOWER MOULDING	Scratched	350.00 FN	*120.00 FN
13	1		*BOOT OUTER LOWER MOULDING	Not Necessary	165.00 FS	*- FS
14	1		*REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	2,867.80	1,484.10
- Nett Item Discount on N Items 10.00/10.00% (S\$)	242.28	128.41
Total Parts (S\$)	2,625.52	1,355.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT FRONT ELECTRICAL CHECK ,REPLACE REVERSE SENSOR ,MODULE REWIRING ETC	New	120.00	40.00
2	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF BOOT ,END PANEL,AND PARTS REPLACEMENT	New	450.00	200.00
3	TO SPRAY PAINT AFFECTED AREAS	New	600.00	400.00
Gross Labour Cost (\$\$)			1,170.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >