

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021567/AEA3N2

Date: 20/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100218524-09

Claimant
Vehicle No : SMJ1833A **Insured Vehicle No :** SJX7824Z

Date of Loss: 03/12/2019 Nature of Claim: TP Claim No: 9968610951SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ1833A	Engine No:	27091030880495
Make & Model:	MERCEDES-BENZ A180, 1.6 (A)	Chassis No:	WDD1760422V125480
Reg. Date:	24/06/2016 (Man. Year: 2015)	Odometer:	32142 km
Colour:	Blue		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,719.37	3,101.40	3,617.97	53.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,240.00	1,990.00	61.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,949.37	4,341.40	5,607.97	56.37
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	9,949.37	3,400.00	6,549.37	65.83
+ GST 7.00/7.00% (S\$)	696.46	238.00	458.46	65.83
Nett Amount (S\$)	10,645.83	3,638.00	7,007.83	65.83
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,005.45		

INSPECTION

Date of Assignment: 05/12/2019

Date Inspected: 05/12/2019 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR	Dented	1,855.30 FL	*1,766.00 FL
2	1		*REAR DOOR	Dented	1,788.60 FL	*1,680.00 FL
3	1		*REAR FENDER	Repair	2,155.40 FL	*- FL
4	1		*WHEEL RIM	Not Necessary	1,500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,299.30	3,446.00
- List Item Discount on L Items 10.00/10.00% (\$)	579.93	344.60
Total Parts (\$)	6,719.37	3,101.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	New	1,400.00	400.00
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	New	1,200.00	600.00
3	TUFF COAT	New	250.00	0.00
4	REMOVE AND REFIX FRONT DOOR MECHANISM	New	140.00	80.00
5	REMOVE AND REFIX REAR DOOR MECHANISM	New	140.00	80.00
6	WHEEL ALIGNMENT	New	100.00	80.00
Gross Labour Cost (\$\$)			3,230.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >