Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021572/KBA3Q2

**Date:** 27/08/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant GBD3391G Insured Vehicle No: SKK4641K

Vehicle No: GBD3391G Insured vehicle No: SKK4041K

Date of Loss: 02/12/2019 Nature of Claim: TP Claim No: 3000603109SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GBD3391G

 Make & Model:
 NISSAN NV200, 1.5 L (M)
 Engine No:
 K9KC400D053836

 Reg. Date:
 17/09/2014 (Man. Year: 2014)
 Chassis No:
 VSKYBAM20Z0089149

 Colour:
 Red
 Odometer:
 165099 km

Colour: Red Engine Capacity: 1461 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/65 R14 Rear Tyre Size: 185/65 R14
Front Left Side: KAPSEN 9 mm Rear Left Side: KAPSEN 2 mm
Front Right Side: KAPSEN 9 mm Rear Right Side: KAPSEN 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,845.04	5,450.51	1,394.53	20.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	2,020.00	420.00	17.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,285.04	7,470.51	1,814.53	19.54
Approved Total (Overridden) (S\$)		5,950.00		
(S\$)	9,285.04	5,950.00	3,335.04	35.92
+ GST 7.00/7.00% (S\$)	649.95	416.50	233.45	35.92
Nett Amount (S\$)	9,934.99	6,366.50	3,568.49	35.92
+ Loss of Use (9.0 x S	540.00			
+ Doc/S	+ Doc/Search Fee (S\$) Nett Liability (S\$)			
Ne				
Global Sum	6,900.00			

**INSPECTION** 

Date of Assignment: 04/12/2019

Date Inspected: 04/12/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun

Industrial Park A Singapore 768761

Estimated Period of Repair: 7.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Buckled	655.20 FN	*655.20 FN
2	1		*FRONT BUMPER LH SIDE RETAINER	Cracked	25.90 FN	*25.90 FN
3	6		*FRONT BUMPER CLIPS	Necessary	28.80 FN	*28.80 FN
4	1		*LH HEADLAMP	Mtg Broken	615.90 FN	*615.90 FN
5	1		*HEADLAMP LOWER GARNISH	Buckled	368.50 FN	*368.50 FN
6	1		*BONNET	Bent	864.20 FN	*864.20 FN
7	1		*BONNET LH HINGE	Repair	43.70 FN	*- FN
8	1		*FRONT LH FENDER	Bent	555.20 FN	*555.20 FN
9	1		*FRONT LH DOOR	Bent	1,287.50 FN	*1,287.50 FN
10	1		*FRONT LH DOOR SIDE MIRROR	Broken	375.20 FN	*375.20 FN
11	1		*FRONT LH DOOR GLASS CHANNEL	Cut	137.50 FN	*137.50 FN
12	1		*FRONT LH DOOR GLASS	Cut	968.00 FS	*968.00 FS
13	1		*LH SLIDING PANEL GLASS	Serviceable	1,355.20 FS	*-FS
14	1		*FRONT LH DOOR COY STICKER	Necessary	20.00 FS	*20.00 FS
15	1		*ROLL REAR LH FENDER GLASS GUM	Necessary	40.00 FS	*40.00 FS
F=Fra	ınchise	part. S=SpcN	lett. N=NettItemDisc.			
				Sub Total (S\$)	7,340.80	5,941.90
		- Nett Item Discount on N Items 10.00/10.00% (S\$)		495.76	491.39	
				Total Parts (S\$)	6,845.04	5,450.51
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REFIX FRT BUMPER ASSY ,HEADLAMP ,BONNET ,FRT LH FENDER ,FRT LH DOOR & ATTACHMENT ,KNOCK & REPAIR FRT LH W/SCREEN PILLAR ,FRT SUPPOT PANEL & REALIGN THE SAME	New	900.00	800.00
2	REMOVE & REFIX FRT LH DOOR GLASS	New	60.00	60.00
3	REMOVE & REFIX REAR LH PANEL GLASS	New	120.00	0.00
4	PUTTY & RESPRAY ON FRT LH FENDER ,BONNET ,FRT LH DOOR ,FRT LH W/SCREEN PILLAR ,LH SIDE PANEL ,FRT LH HEADLAMP LOWER GARNISH ,FRT SUPPORT PANEL	New	1,300.00	1,100.00
5	RUSTPROOFING	New	60.00	60.00
	Gross Labou	ır Cost (S\$)	2,440.00	2,020.00
	Report was unsubmitted duri	na this print-out.		

< END OF ESTIMATES >