

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021574/FEA3Q2

Date: 08/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900110268

Claimant
Vehicle No : SHD4003A **Insured Vehicle No :** SMP822G

Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: 3836713072SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4003A		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEJU192178
Reg. Date:	01/03/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU141444
Colour:	Blue	Odometer:	28301 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 8 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Davanti 8 mm	Rear Right Side:	Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,181.78	3,110.32	2,071.46	39.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	1,100.00	760.00	40.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,041.78	4,210.32	2,831.46	40.21
+ GST 7.00/7.00% (S\$)	492.92	294.72	198.20	40.21
Nett Amount (S\$)	7,534.70	4,505.04	3,029.66	40.21
+ Loss of Use (10.0 x S\$50.00/day) (S\$)		500.00		
+ Car Rental (10.0 x S\$128.40/day) (S\$)		1,284.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		6,296.53		
Global Sum Settlement (S\$)		6,290.00		

INSPECTION

Date of Assignment: 06/12/2019

Date Inspected: 06/12/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Buckled	2,480.40 FL	*2,480.40 FL
2	1		*BOOT LID LOCK UPPER	Not Necessary	224.00 FL	*- FL
3	1		*BOOT LID LOCK LOWER	Not Necessary	51.30 FL	*- FL
4	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
5	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
6	1		*EMBLEM -IONIQ	Necessary	31.30 FL	*31.30 FL
7	1		*BOOT LID GLASS ,LOWER	Necessary	384.90 FL	*384.90 FL
8	1		*REAR BUMPER	Repair	459.40 FL	*- FL
9	1		*REAR BUMPER CENTRE MOULDING ASSY	Cut	451.25 FL	*451.25 FL
10	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Cracked	155.00 FL	*155.00 FL
11	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
12	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Not Necessary	66.20 FL	*- FL
13	1		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
14	1		*REAR PANEL	Not Necessary	532.00 FL	*- FL
15	1		*REAR PANEL GARNISH	Not Necessary	155.00 FL	*- FL
16	2		*REAR PANEL LOWER PANEL	Not Necessary	78.80 FL	*- FL
17	1		*REAR WINDSCREEN GLASS	Not Necessary	607.20 FL	*- FL
18	1		*REAR WINDSCREEN MOULDING	Not Necessary	28.20 FL	*- FL
19	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	30.00 FS	*30.00 FS
20	1		*REAR NO.PLATE	Cracked	25.00 FS	*25.00 FS
21	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	135.70 FS	*- FS
22	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
23	1		*REAR WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS
24	1		*REAR BUMPER FOGLAMP	Cracked	201.50 FL	*201.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,405.55	3,861.65
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,223.77	751.33
Total Parts (\$\$)	5,181.78	3,110.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	480.00
2	SPRAY PAINTING CHARGE	New	600.00	400.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	30.00
5	TOWING CHARGE	New	60.00	60.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	50.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	50.00
8	REMOVE/REFIX REVERSE SENSOR	New	80.00	0.00
Gross Labour Cost (\$\$)			1,860.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >