

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG19021575/ASF3E2

**Date:** 01/06/2020

### REFERENCE

Insured/Claimant:	CHOI SOON WOONG	Policy No:	1800009645	
Date of Loss:	03/12/2019	Nature of Claim:	OD	Claim No: 9353067059SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW2825K			
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX019687	
Reg. Date:	05/02/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF0J2053783	
Colour:	Black	Odometer:	32901 km	
Engine Capacity:	1984 cc			
Market Value/New Car Price:	S\$168,000.00			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,082.00	8,707.92	6,374.08	42.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,472.00	2,372.00	5,100.00	68.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>22,554.00</b>	<b>11,079.92</b>	<b>11,474.08</b>	<b>50.87</b>
<b>- Excess (\$\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>21,554.00</b>	<b>10,079.92</b>	<b>11,474.08</b>	<b>53.23</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,508.78</b>	<b>705.59</b>	<b>803.19</b>	<b>53.23</b>
<b>Nett Amount (\$\$)</b>	<b>23,062.78</b>	<b>10,785.51</b>	<b>12,277.27</b>	<b>53.23</b>

### INSPECTION

Date of Assignment:	06/12/2019	
Date Inspected:	06/12/2019	Inspected At:
		Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,364.00 FS	*1,891.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	244.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - LH	Not Necessary	34.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	101.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	685.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	156.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	519.00 FS	*- FS
8	1		*FRONT BUMPER END CAP - LH	Not Necessary	83.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	34.00 FS	*27.12 FS
10	1		*FRONT FENDER - LH	Not Necessary	1,301.00 FS	*- FS
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	60.00 FS	*- FS
12	1		*FRONT FENDER BRACKET - LH	Not Necessary	16.00 FS	*- FS
13	1		*FRONT FENDER BRACE - LH	Not Necessary	206.00 FS	*- FS
14	1		*FRONT FENDER CLOSURE PANEL - LH	Not Necessary	28.00 FS	*- FS
15	1		*FRONT FENDER COVER PANEL - LH	Not Necessary	36.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	246.00 FS	*- FS
17	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	35.00 FS	*- FS
18	1		*FRONT WHEEL SPOILER - LH	Not Necessary	146.00 FS	*- FS
19	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,154.00 FS	*922.40 FS
20	1		*HEADLIGHT MOUNTING - LH	Cracked	107.00 FS	*85.60 FS
21	1		*LED HEADLIGHT - LH	Cut	7,227.00 FS	*5,781.60 FS
22	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.					<b>Total Parts (\$\$)</b>	<b>15,082.00      8,707.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	750.00
3	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	4,000.00	950.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>7,472.00</b>	<b>2,372.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >