

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19021582/AGA3Q2

**Date:** 14/01/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SFW2919U	<b>Insured Vehicle No :</b>	SHC1241D
Date of Loss: 04/12/2019	Nature of Claim: TP	Claim No: MCT19120106

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFW2919U</b>		
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGEH743568
Reg. Date:	11/06/2015 (Man. Year: 2014)	Chassis No:	KNAFZ411MF5337240
Colour:	Red	Odometer:	111615 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,903.90	4,203.00	2,700.90	39.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,910.00	2,040.00	1,870.00	47.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,813.90</b>	<b>6,243.00</b>	<b>4,570.90</b>	<b>42.27</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,000.00</b>		
<b>(\$\$)</b>	10,813.90	5,000.00	5,813.90	53.76
<b>+ GST 7.00/7.00% (\$\$)</b>	756.97	350.00	406.97	53.76
<b>Nett Amount (\$\$)</b>	<b>11,570.87</b>	<b>5,350.00</b>	<b>6,220.87</b>	<b>53.76</b>
<b>+ Car Rental (6.0 x \$S100.00/day + 7.00% GST) (\$\$)</b>		642.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>+ Other Costs (\$\$)</b>		100.00		
<b>Nett Liability (\$\$)</b>		<b>6,099.45</b>		

### INSPECTION

Date of Assignment:	06/12/2019	
Date Inspected:	06/12/2019 Inspected At:	Twincar Automotive Pte Ltd BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	6.0 days	

---

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2021)
<b>Parts:</b>	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFW2919U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented	1,277.00 FL	*1,277.00 FL
2	1		*FRONT RH DOOR FRAME BLACK STICKER (UPPER)	Necessary	22.00 FL	*22.00 FL
3	1		*FRONT RH DOOR FRAME BLACK STICKER (VERTICAL)	Necessary	27.00 FL	*27.00 FL
4	1		*FRONT RH DOOR GLASS CHANNEL WEATHER STRIP	Not Necessary	119.00 FL	*- FL
5	1		*FRONT RH DOOR GLASS REGULATOR	Damaged	319.00 FL	*319.00 FL
6	2		*FRONT RH DOOR GUIDE RUBBER STOPPER	Not Necessary	30.00 FL	*- FL
7	1		*FRONT RH DOOR INNER PLASTIC SEAL COVER	Not Necessary	18.00 FL	*- FL
8	1		*FRONT RH DOOR INNER TRIM BOARD	Cracked	565.00 FL	*565.00 FL
9	1		*FRONT RH DOOR WEATHER STRIP SEAL	Not Necessary	123.00 FL	*- FL
10	1		*REAR RH BEARING HUB	Damaged	352.00 FL	*352.00 FL
11	1		*REAR RH DOOR	Dented	1,309.00 FL	*1,309.00 FL
12	1		*REAR RH DOOR FRAME BLACK STICKER (UPPER)	Necessary	22.00 FL	*22.00 FL
13	1		*REAR RH DOOR FRAME BLACK STICKER (VERTICAL)	Necessary	25.00 FL	*25.00 FL
14	1		*REAR RH DOOR GLASS CHANNEL WEATHER STRIP	Not Necessary	161.00 FL	*- FL
15	1		*REAR RH DOOR GLASS REGULATOR	Not Necessary	239.00 FL	*- FL
16	1		*REAR RH DOOR GUIDE RUBBER STOPPER	Not Necessary	15.00 FL	*- FL
17	1		*REAR RH DOOR INNER PLASTIC SEAL COVER	Not Necessary	18.00 FL	*- FL
18	1		*REAR RH DOOR LOWER HINGE	Not Necessary	38.00 FL	*- FL
19	1		*REAR RH DOOR WEATHER STRIP SEAL	Not Necessary	122.00 FL	*- FL
20	1		*REAR RH FENDER TRANSPARENT STICKER	Necessary	52.00 FL	*52.00 FL
21	1		*RH SIDE ROCKER PANEL	Repair	1,304.00 FL	*- FL
22	1		*REAR RH SPORT RIM	Cut	912.60 FS	*600.00 FS
23	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
24	1		*SET REAR RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
25	1		*REAR RH TYRE	Not Necessary	350.00 FS	*- FS
					<b>Sub Total (\$\$)</b>	<b>7,519.60 4,600.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>615.70 397.00</b>
					<b>Total Parts (\$\$)</b>	<b>6,903.90 4,203.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	250.00	0.00
2	TO REMOVE,CHANGE REAR SUSPENSION PARTS,AXLE CARRIAGE,ABSORBER,LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC	New	140.00	60.00
3	TO ROAD TEST DRIVING,CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	100.00	80.00
4	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	200.00	60.00
5	TO TRANSFER DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL,TRIM BOARD,MECHANISM LOCK AND HANDLE	New	200.00	160.00
6	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	800.00
7	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,400.00	800.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,910.00</b>	<b>2,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >