

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 08 Jan 2020

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|--------------------|
| Vehicle No | : SJZ4623X | Accident Date | : 03/12/2019 |
| Make | : BMW 523I | Policy No. | : DMPCSN1834501901 |
| Assignment Date | : 09/12/2019 | Excess | : S\$0.00 |
| Date of Inspection | : 09/12/2019 | Est. Duration of Repair | : 4 days |
| Inspection At | : Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|---------------------------|
| Repairer's Estimate (Gross) | :S\$ | 4,469.69 (inclusive supp) |
| Revised Amount | :S\$ | 3,870.19 (inclusive supp) |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 3,870.19 |
| Lump Sum Repair | :S\$ | 3,850.00 |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 31,000.00 |
| COE / PARF Rebate | :S\$ | 24,269.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 6,731.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 195.00