

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD19021624/APA3Q2

**Date:** 16/04/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00003364-01

**Claimant**  
**Vehicle No :** GBE4484K **Insured Vehicle No :** SKR5908Z

Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: 1201900037669

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBE4484K</b>		
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Engine No:	1KD2559703
Reg. Date:	03/12/2015 (Man. Year: 2015)	Chassis No:	KDH2015019507
Colour:	White	Odometer:	149967 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,293.25	2,206.25	2,087.00	48.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,650.00	1,830.00	52.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,773.25</b>	<b>3,856.25</b>	<b>3,917.00</b>	<b>50.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,050.00</b>		
<b>(S\$)</b>	7,773.25	3,050.00	4,723.25	60.76
<b>+ GST 7.00/7.00% (S\$)</b>	544.13	213.50	330.63	60.76
<b>Nett Amount (S\$)</b>	<b>8,317.38</b>	<b>3,263.50</b>	<b>5,053.88</b>	<b>60.76</b>
<b>+ Loss of Use (8.0 x S\$90.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,990.95</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,990.00</b>		

### INSPECTION

Date of Assignment: 06/12/2019

Date Inspected: 10/12/2019 Inspected At:

MG Solution Pte Ltd (HQ)  
23 Kaki Bukit Avenue 4 #02-03B,  
VICOM Inspection Centre  
Singapore 415933

Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2020)
<b>Parts:</b>	213	TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE4484K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	538.00 FL	*538.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Necessary	65.00 FL	*65.00 FL
3	1		*REAR FENDER	Distorted	1,950.00 FL	*1,454.00 FL
4	1		*REAR FENDER INNER PANEL	Repair	2,100.00 FL	*- FL
5	1		*REAR FENDER GLASS MOULDING	Necessary	190.00 FL	*190.00 FL
6	1		*TAILLAMP LH	Cracked	328.00 FL	*328.00 FL
7	1		*TAILLAMPS LOWER PANEL	Cracked	170.00 FL	*170.00 FL
8	1		*BUMPER AIR VENT	Cracked	90.00 FL	*90.00 FL
9	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
10	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
11	1		*REAR FENDER WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,651.00</b>	<b>2,915.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,357.75	708.75
<b>Total Parts (S\$)</b>	<b>4,293.25</b>	<b>2,206.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,600.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	TUFF COAT	New	250.00	80.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILTATE REPAIR	New	150.00	60.00
5	TO REMOVE AND REFIX REVERSE SENSOR SETTING	New	80.00	50.00
6	TRANSFER TAILGATE MECHANISM	New	80.00	0.00
7	REMOVE AND REFIX FENDER WINDSCREEN	New	120.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>3,480.00</b>	<b>1,650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >