

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021625/UDS3Q2

Date: 09/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100445230

Claimant
Vehicle No : SLT7727T **Insured Vehicle No :** SGY1128U

Date of Loss: 07/12/2019 Nature of Claim: TP Claim No: 2938658690SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT7727T		
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Engine No:	LEB5065353
Reg. Date:	20/05/2016 (Man. Year: 2015)	Chassis No:	RU31115341
Colour:	White	Odometer:	49864 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,437.20	3,866.16	4,571.04	54.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	1,890.00	1,100.00	36.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,427.20	5,756.16	5,671.04	49.63
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	11,427.20	4,600.00	6,827.20	59.75
+ GST 7.00/7.00% (S\$)	799.90	322.00	477.90	59.74
Nett Amount (S\$)	12,227.10	4,922.00	7,305.10	59.75
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,164.00		

INSPECTION

Date of Assignment: 09/12/2019

Date Inspected: 09/12/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	121.30 F	*121.30 FL
2	1		*TAILGATE	Dented	1,100.90 F	*953.00 FL
3	1		*TAILGATE VEZEL EMBLEM	Necessary	56.20 F	*56.20 FL
4	1		*TAILGATE HYBRID EMBLEM	Necessary	85.50 F	*85.50 FL
5	1		*TAILGATE INNER LOCK	Not Necessary	245.50 F	*- FL
6	1		*TAILGATE INNER TRIM	Not Necessary	388.20 F	*- FL
7	2		*TAILGATE REFLECTORS	Not Necessary	590.00 F	*- FL
8	1		*TAILGATE WEATHERSTRIP	Not Necessary	281.20 F	*- FL
9	1		*REAR BUMPER	Dented / Deformed	788.20 F	*762.70 FL
10	1		*REAR BUMPER SIDES	N/S Torn	598.00 F	*299.00 FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	91.00 F	*- FL
12	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
13	1		*REAR BUMPER REFLECTORS	N/S Cracked	302.00 F	*151.00 FL
14	1		*TAILLAMPS	N/S Cracked	970.00 F	*460.20 FL
15	2		*TAILLAMP HOUSING PANELS	Not Necessary	390.00 F	*- FL
16	1		*REAR END PANEL	Dented / Bent	571.00 F	*514.00 FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	245.00 F	*- FL
18	1		*REAR DIFFUSER	Deformed / Warped	420.20 F	*366.50 FL
19	1		*SET REAR DIFFUSER CLIPS	Necessary	50.00 F	*50.00 FL
20	1		*REAR SPLASH SHIELD N/S	Torn	382.00 F	*282.30 FL
21	1		*REAR FENDER OUTER PROTECTOR N/S	Torn	281.00 F	*281.00 FL
22	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
23	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
24	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
25	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,437.20	4,752.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	886.54
Total Parts (\$\$)	8,437.20	3,866.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACING REAR REVERSE CAMERA	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO SPRAY RUST PROOFING	New	100.00	60.00
7	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	880.00	600.00
9	TO PUTTY & SPRAY PAINTING	New	1,380.00	900.00
Gross Labour Cost (\$)			2,990.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >