Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021644/AKA3Q2

Date: 30/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900247254

Claimant
Vehicle No: SJR7656Z

Insured Vehicle No: SMQ4057S

Date of Loss: 05/12/2019 Nature of Claim: TP Claim No: 4038936435SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR7656Z

 Make & Model:
 HONDA FREED, 1.5 G (A)
 Engine No:
 L15A2334671

 Reg. Date:
 13/07/2009 (Man. Year: 2008)
 Chassis No:
 GB31034258

 Colour:
 White
 Odometer:
 217987 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,640.00	3,473.60	7,166.40	67.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,720.00	1,230.00	41.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,590.00	5,193.60	8,396.40	61.78
Approved Total (Overridden) (S\$)		4,150.00		
(S\$)	13,590.00	4,150.00	9,440.00	69.46
+ GST 7.00/7.00% (S\$)	951.30	290.50	660.80	69.46
Nett Amount (S\$)	14,541.30	4,440.50	10,100.80	69.46
+ Car Rental (7.0 x S\$120.00/day + 7	.00% GST) (S\$)	898.80		
Ne	ett Liability (S\$)	5,339.30		
Global Sum Settlement (S\$)		5,330.00		

INSPECTION

Date of Assignment: 09/12/2019

Date Inspected: 09/12/2019 Inspected At: V-tec Asia Automotive Pte Ltd (HQ)

8 KAKI BUKIT AVE 4, #07-08/09

PREMIER@KB Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

rt No. Particulars	Condition	Repairer's	Amount
*REPLACE NEW REAR BOOT WITH WINDSCREEN	Distorted	2,950.00 F	*1,247.00 FL
*REPLACE NEW REAR BUMPER	Deformed	1,850.00 F	*695.00 FL
*HONDA & FREED EMBLEM	Necessary	250.00 F	*95.00 FL
*SET REAR TAIL LIGHT	Not Necessary	1,100.00 F	*-FL
*CARPLATE	Bent	50.00 F	*30.00 FL
*CARPLATE HOLDER	Deformed	60.00 F	*30.00 FL
*REVERSE SENSOR	Damaged	320.00 FS	*200.00 FS
*REAR BUMPER RETAINER	Necessary	580.00 F	*35.00 FL
*REAR END PANEL	Dented	780.00 F	*590.00 FL
*REAR EXHAUST	Not Necessary	620.00 F	*-FL
*REAR BUMPER BRACKET	Not Necessary	360.00 F	*-FL
*REVERSE CAMERA	Damaged	180.00 F	*180.00 FL
*REAR DOOR LOCKING SYSTEM	Damaged	480.00 F	*480.00 FL
*REAR DOOR ABSORBER HINGE	Not Necessary	350.00 F	*- FL
*WEATHER STRIP	Cut	280.00 F	*280.00 FL
*REAR BOOT COVER	Cracked	250.00 F	*250.00 FL
*REAR END PANEL COVER	Deformed	180.00 F	*180.00 FL
. S=SpcNett. L=ListItemDisc.			
	Sub Total (S\$)	•	4,292.00
- List Item Discount on L Items 0.00/20.00% (S\$)			818.40
	Total Parts (S\$)	10,640.00	3,473.60
		Total Parts (S\$)	Total Parts (S\$) 10,640.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR FOR REMOVE AND INSTALLATION OF DAMAGED & AFFECTED PARTS REAR BUMPER AND REAR BOOT WITH WINDSCREEN & NECESSARY PARTS	New	890.00	800.00
2	SPRAY PAINTING TO REAR BUMPER ,REAR BOOT & REVERSE SENSOR & NECESSARY PARTS	New	820.00	800.00
3	DIAGNOSTIC TO VEHICLE & ELECTRICAL SYSTEM	New	250.00	0.00
4	REWIRING OF CAMERA & REVERSE SENSOR	New	220.00	120.00
5	PANEL BEATING & RE-ALIGNMENT OF CHASSIS BODY	New	490.00	0.00
6	REMOVE AND INSTALL REAR EXHAUST	New	280.00	0.00
	Gross Labour Cost (S\$)		2,950.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >