

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19021649/GEA3Q2

**Date:** 05/05/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** SHC5830C **Insured Vehicle No :** SML1176C

**Date of Loss:** 04/12/2019 **Nature of Claim:** TP **Claim No:** 7438731046SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC5830C</b>		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002827
Reg. Date:	03/08/2015 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC282211
Colour:	Red	Odometer:	395512 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 5 mm	Rear Left Side:	Sailun 5 mm
Front Right Side:	Sailun 5 mm	Rear Right Side:	Sailun 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,411.29	3,440.48	10,970.81	76.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,830.00	1,220.00	12,610.00	91.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>28,241.29</b>	<b>4,660.48</b>	<b>23,580.81</b>	<b>83.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,700.00</b>		
<b>(S\$)</b>	28,241.29	3,700.00	24,541.29	86.90
<b>+ GST 7.00/7.00% (S\$)</b>	1,976.89	259.00	1,717.89	86.90
<b>Nett Amount (S\$)</b>	<b>30,218.18</b>	<b>3,959.00</b>	<b>26,259.18</b>	<b>86.90</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$124.61/day) (S\$)</b>		498.44		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,664.89</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,660.00</b>		

### INSPECTION

Date of Assignment: 06/12/2019

Date Inspected: 06/12/2019 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 4.0 days

---

**Adjuster:** XING GUO QIANG

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR LH	Buckled	758.70 FL	*758.70 FL
2	1		*DOOR GUIDE REAR LH	Not Necessary	136.40 FL	*- FL
3	1		*DOOR HINGE UPPER LH L70Y	Not Necessary	180.70 FL	*- FL
4	1		*DOOR HINGE LOWER L70Y	Not Necessary	169.90 FL	*- FL
5	1		*DOOR CHECK REAR LH	Not Necessary	114.90 FL	*- FL
6	1		*DOOR SEAL REAR LH	Torn	119.40 FL	*119.40 FL
7	1		*DOOR WAIST SEAL OUTER REAR LH	Not Necessary	169.60 FL	*- FL
8	1		*DOOR GLASS RUNNER SEAL REAR LH	Not Necessary	116.10 FL	*- FL
9	1		*DOOR WEATHERSTRIP REAR LH	Not Necessary	240.50 FL	*- FL
10	1		*DOOR PANEL FRT LH	Buckled	2,844.66 FL	*2,844.66 FL
11	1		*DOOR REGULATOR FRT LH	Not Necessary	758.10 FL	*- FL
12	1		*DOOR REGULATOR MOTOR FRT LH	Not Necessary	501.40 FL	*- FL
13	1		*DOOR REGULATOR GUIDE FRT LH	Not Necessary	69.00 FL	*- FL
14	1		*DOOR HANDLE OUTER FRONT LH	Repair	169.50 FL	*- FL
15	1		*DOOR HANDLE CAP FRONT LH	Not Necessary	17.30 FL	*- FL
16	1		*DOOR LOCK FRT LH	Not Necessary	453.80 FL	*- FL
17	1		*DOOR SEAL FRONT LH	Not Necessary	69.60 FL	*- FL
18	1		*DOOR SEAL LOWER FRONT LH	Not Necessary	93.90 FL	*- FL
19	1		*DOOR WEATHERSTRIP FRONT LH	Not Necessary	316.00 FL	*- FL
20	1		*DOOR GLASS RUBBER SEAL FRONT LH	Not Necessary	332.00 FL	*- FL
21	1		*DOOR WAIST SEAL OUTER FRONT LH	Not Necessary	92.20 FL	*- FL
22	1		*DOOR MOULDING FRONT LH	Not Necessary	100.50 FL	*- FL
23	1		*DOOR MIRROR ASSY LH	Not Necessary	727.90 FL	*- FL
24	1		*DOOR HARNESS WIRE LH	Not Necessary	2,670.00 FL	*- FL
25	1		*ROCKER PANEL INNER GARNISH LH	Not Necessary	466.51 FL	*- FL
26	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
27	1		*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL
28	1		*ROCKER PANEL CENTER LH	Repair	990.25 FL	*- FL
29	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
30	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
31	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
32	1		*DOOR HINGE NUT LH	Not Necessary	14.60 FS	*- FS
33	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
34	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
35	1		*DOOR LOCK SCREW K70Y	Not Necessary	6.12 FS	*- FS
36	1		*FRONT LEFT TYRE	Not Necessary	300.00 FS	*- FS
37	1		*FRONT LEFT TYRE RIM	Not Necessary	380.00 FS	*- FS
38	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
39	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*30.00 FS
40	1		*REAR DOOR STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>15,900.15</b>	<b>3,812.76</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,488.86	372.28
<b>Total Parts (\$\$)</b>	<b>14,411.29</b>	<b>3,440.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	6,000.00	500.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	600.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
8	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
10	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>13,830.00</b>	<b>1,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >