

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Dec 2019 Edit Reg		09 Dec 2019 00:00 Edit Adj Rpt	S\$6,200.00 Edit Estimates	S\$6,200.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	KENNETH RICHARD EYEARS , Co. Reg. No.: -		
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHB397A	Date of Loss:	06/12/2019 14:00 - :59 [57 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9008269340SG	Policy/Cover Note No.:	1800010163 (Comprehensive)
Vehicle Reg. No. (Insured):	SLU3221G	Policy No. (Claimant):	D-19093197MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 19/12/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (13/10/2020): **Alert - Adj Mandate Approved (S\$7886.92) - SHB397A - Claim Handler: Lee, Ming-Ya...**
- AIG_SG_EXPRESS (30/07/2020): **Alert - Adj Mandate Approved (S\$7734.20) - SHB397A - Claim Handler: Lee, Ming-Ya...**
- AIG_SG_EXPRESS (27/05/2020): **Alert - Adj Mandate Approved (S\$7428.76) - SHB397A - Claim Handler: Lee, Ming-Ya...**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SHB397A (9008269340SG)**
[SLU3221G]
TP
SMRT TAXIS PTE LTD
Dec 6 2019 2:00PM
[KENNETH RICHARD EYEARS]
SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	31/01/20 11:35	Video - Accident (TP)														Load MP4				
Letters/Correspondences															1 per page					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown														Edit				
Photos/Images															3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	17/01/20 09:22	Chassis Number														Load JPG				
2	17/01/20 09:22	Odometer Reading														Load JPG				
3	17/01/20 09:22	General View														Load JPG				
4	17/01/20 09:22	General View														Load JPG				
5	17/01/20 09:22	General View														Load JPG				
6	17/01/20 09:22	General View														Load JPG				
7	17/01/20 09:22	General View														Load JPG				
8	17/01/20 09:22	General View														Load JPG				
9	17/01/20 09:22	General View														Load JPG				
10	17/01/20 09:22	General View														Load JPG				
11	17/01/20 09:22	General View														Load JPG				
12	17/01/20 09:22	General View														Load JPG				
13	17/01/20 09:22	General View														Load JPG				
14	17/01/20 09:22	General View														Load JPG				
15	17/01/20 09:22	General View														Load JPG				
16	17/01/20 09:22	General View														Load JPG				
17	17/01/20 09:22	General View														Load JPG				
18	17/01/20 09:22	General View														Load JPG				
19	17/01/20 09:22	General View														Load JPG				
20	17/01/20 09:22	General View														Load JPG				
21	17/01/20 09:22	General View														Load JPG				
22	17/01/20 09:22	General View														Load JPG				
23	17/01/20 09:22	General View														Load JPG				
24	17/01/20 09:22	General View														Load JPG				
25	17/01/20 09:22	General View														Load JPG				
26	17/01/20 09:22	General View														Load JPG				
27	17/01/20 09:22	General View														Load JPG				
28	17/01/20 09:22	General View														Load JPG				

Video			1 per page ▾	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	17/01/20 09:22	General View	 Load JPG	☒
30	17/01/20 09:22	General View	 Load JPG	☒
31	17/01/20 09:22	General View	 Load JPG	☒
32	17/01/20 09:22	General View	 Load JPG	☒
33	17/01/20 09:22	General View	 Load JPG	☒
34	17/01/20 09:22	General View	 Load JPG	☒
35	17/01/20 09:22	General View	 Load JPG	☒
36	17/01/20 09:22	General View	 Load JPG	☒
37	17/01/20 09:22	General View	 Load JPG	☒
38	17/01/20 09:22	General View	 Load JPG	☒
39	17/01/20 09:22	General View	 Load JPG	☒
40	17/01/20 09:22	General View	 Load JPG	☒
41	17/01/20 09:22	General View	 Load JPG	☒
42	17/01/20 09:22	General View	 Load JPG	☒
43	17/01/20 09:22	General View	 Load JPG	☒
44	17/01/20 09:22	General View	 Load JPG	☒
45	17/01/20 09:22	General View	 Load JPG	☒
46	17/01/20 09:22	General View	 Load JPG	☒
47	17/01/20 09:22	General View	 Load JPG	☒
48	17/01/20 09:22	General View	 Load JPG	☒
49	17/01/20 09:22	General View	 Load JPG	☒
50	17/01/20 09:22	General View	 Load JPG	☒
51	17/01/20 09:22	General View	 Load JPG	☒
52	17/01/20 09:22	General View	 Load JPG	☒
53	17/01/20 09:22	General View	 Load JPG	☒
54	17/01/20 09:22	General View	 Load JPG	☒
55	17/01/20 09:22	General View	 Load JPG	☒
56	17/01/20 09:22	General View	 Load JPG	☒
57	17/01/20 09:22	General View	 Load JPG	☒
58	17/01/20 09:22	General View	 Load JPG	☒
59	17/01/20 09:22	General View	 Load JPG	☒
60	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
61	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
62	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
63	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
64	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
65	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
66	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
67	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
68	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
69	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
70	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
71	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
72	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
73	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
74	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
75	17/01/20 09:24	Dismantled Parts	 Load JPG	☒
76	17/01/20 09:24	Dismantled Parts	Load JPG	☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
77	17/01/20 09:24	Dismantled Parts		Load JPG ☒
78	17/01/20 09:24	Dismantled Parts		Load JPG ☒
79	17/01/20 09:24	Dismantled Parts		Load JPG ☒
80	17/01/20 09:24	Dismantled Parts		Load JPG ☒
81	17/01/20 09:24	Dismantled Parts		Load JPG ☒
82	17/01/20 09:24	Dismantled Parts		Load JPG ☒
83	17/01/20 09:24	Dismantled Parts		Load JPG ☒
84	17/01/20 09:24	Dismantled Parts		Load JPG ☒
85	17/01/20 09:24	Dismantled Parts		Load JPG ☒
86	17/01/20 09:24	Dismantled Parts		Load JPG ☒
87	17/01/20 09:24	Dismantled Parts		Load JPG ☒
88	17/01/20 09:24	Dismantled Parts		Load JPG ☒
89	17/01/20 09:24	Dismantled Parts		Load JPG ☒
90	17/01/20 09:24	Dismantled Parts		Load JPG ☒
91	17/01/20 09:24	Dismantled Parts		Load JPG ☒
92	17/01/20 09:24	Dismantled Parts		Load JPG ☒
93	17/01/20 09:24	Dismantled Parts		Load JPG ☒
94	17/01/20 09:24	Dismantled Parts		Load JPG ☒
95	17/01/20 09:24	Dismantled Parts		Load JPG ☒
96	17/01/20 09:24	Dismantled Parts		Load JPG ☒
97	17/01/20 09:25	After Repair Photo		Load JPG ☒
98	17/01/20 09:25	After Repair Photo		Load JPG ☒
99	17/01/20 09:25	After Repair Photo		Load JPG ☒
100	17/01/20 09:25	After Repair Photo		Load JPG ☒
101	17/01/20 09:25	After Repair Photo		Load JPG ☒
102	17/01/20 09:25	After Repair Photo		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	10/12/19 17:50	TP ESTIMATE- MARKED		Load PDF
2	10/12/19 17:50	TP GIA REPORT		Load PDF
3	31/01/20 11:29	TP ESTIMATE - MARKED		Load PDF
4	20/02/20 17:21	LOD		Load PDF
5	20/02/20 17:21	LTA SEARCH		Load PDF
6	20/02/20 17:21	RENTAL MILEAGE		Load PDF
7	20/02/20 17:21	RENTAL RECEIPT		Load PDF
8	15/10/20 11:21	LETTER TO OI		Load PDF
9	19/10/20 14:17	Authorisation to Act		Load PDF
10	19/10/20 14:17	Release Voucher		Load PDF
11	19/10/20 14:17	WORKSHOP INVOICE		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	11/12/19 15:23	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLU3221G (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHB397A (TP veh)		
Date of Accident:	06/12/2019		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	19,013.92
Final Repair Cost	:	\$	6,200.00
Loss of Use	:	\$	550.00
Rental (if any)	:	\$	1,129.92
LTA / GIA Search Fee	:	\$	7.00
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	7,886.92
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:	\$ 7,886.92
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

19 Oct
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19021718/QDS3S2**Date:** 19/10/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800010163
Claimant Vehicle No :	SHB397A	Insured Vehicle No :	SLU3221G
Date of Loss:	06/12/2019	Nature of Claim:	TP
		Claim No:	9008269340SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB397A	Engine No:	2ZR1503576
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36UX05757870
Reg. Date:	11/02/2015 (Man. Year: 2014)	Odometer:	441840 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,246.92	5,383.67	9,863.25	64.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,767.00	1,810.00	1,957.00	51.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,013.92	7,193.67	11,820.25	62.17
Approved Total (Overridden) (\$\$)		6,200.00		
Nett Amount (\$\$)	19,013.92	6,200.00	12,813.92	67.39
+ Loss of Use (11.0 x S\$50.00/day) (\$\$)		550.00		
+ Car Rental (11.0 x S\$102.72/day) (\$\$)		1,129.92		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		7,886.92		

INSPECTION

Date of Assignment:	09/12/2019	
Date Inspected:	09/12/2019	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	6.0 days	

10/19/2020

Adjuster Report

Adjuster: OI SUN PIN

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER ENERGY ABSORBER FRT (DISC 25%)	Crushed	78.80 F	*59.10 F
2	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
3	1		*BUMPER FRT (DISC 25%)	Crushed	482.00 F	*361.50 F
4	1		*BUMPER CLIPS (DISC 25%) 10pcs	Necessary	16.10 F	*12.08 F
5	1		*BUMPER SUPPORT F/RH (DISC 25%)	Broken	76.40 F	*57.30 F
6	1		*EMBLEM FRONT (DISC 25%)	Necessary	86.50 F	*64.88 F
7	1		*UNDER COVER SIDE/RH (DISC 25%)	Crushed	46.10 F	*34.58 F
8	1		*FENDER FRT/RH (DISC 25%)	Dented	723.40 F	*542.55 F
9	1		*LENS & BODY, FR TURN RH (DISC 10%)	Crushed	511.80 F	*460.62 F
10	1		*HEAD LAMP RH (DISC 10%)	Crushed	945.20 F	*850.68 F
11	1		*NUMBER PLATE FRAME (SN)	Cracked	12.00 F	*12.00 F
12	1		*BRACKET, FR BUMPER	Serviceable	110.40 F	*- F
13	1		*NUMBER PLATE	Serviceable	15.00 F	*- F
14	1		*WIRE, ENGINE ROOM, NO.3	Serviceable	242.00 F	*- F
15	1		*FOG LAMP RH	Serviceable	295.20 F	*- F
16	1		*FOG LAMP LH	Serviceable	280.10 F	*- F
17	1		*BRACKET, FR TURN LOWER RH	Serviceable	26.00 F	*- F
18	1		*LENS & BODY, FR TURN RH	Serviceable	511.80 F	*- F
19	1		*NAME PLATE (HYBRID)	Serviceable	51.90 F	*- F
20	1		*FENDER FRT/LH	Serviceable	723.40 F	*- F
21	1		*HEAD LAMP LH	Serviceable	945.20 F	*- F
22	1		*LENS & BODY, FR TURN LH	Serviceable	511.80 F	*- F
23	1		*SUPPORT SUB-ASSY	Serviceable	1,480.40 F	*- F
24	1		*BUMPER SUPPORT F/LH	Serviceable	76.40 F	*- F
25	1		*GRILLE, RADIATOR	Serviceable	310.60 F	*- F
26	1		*GRILLE, RADIATOR LOWER NO.2	Serviceable	94.60 F	*- F
27	1		*BUMPER LIP FRT	Serviceable	139.60 F	*- F
28	1		*BUMPER FRT ABSORBER LOWER	Serviceable	127.70 F	*- F
29	1		*UNDER COVER CENTER	Serviceable	448.30 F	*- F
30	1		*UNDER COVER SIDE/LH	Serviceable	46.10 F	*- F
31	1		*BUMPER GRILLE SUB-ASSY, LOWER	Serviceable	311.10 F	*- F
32	1		*HOOD PANEL	Repair	748.10 F	*- F
33	1		*DOOR FRT/RH	Repair	894.40 F	*- F
34	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*148.44 F
35	1		*GRILLE, RADIATOR (DISC 25%)	Cracked	310.60 F	*232.95 F
36	1		*BUMPER LIP FRT (DISC 25%)	Crushed	139.60 F	*104.70 F
37	1		*BUMPER FRT ABSORBER LOWER (DISC 25%)	Cracked	127.70 F	*95.78 F
38	1		*ARM SUB-ASSY, FR BUMPER RH (DISC 25%)	Bent	250.40 F	*187.80 F
39	1		*BUMPER REINFORCEMENT FRT (DISC 25%)	Bent	498.40 F	*373.80 F
40	1		*DEFLECTOR, RADIATOR RH (DISC 25%)	Crushed	83.50 F	*62.63 F
41	1		*HOOD HINGE RH (DISC 25%)	Bent	55.90 F	*41.93 F
42	1		*BRACKET, FR BUMPER (DISC 25%)	Cracked	110.40 F	*82.80 F
43	1		*SUPPORT SUB-ASSY (DISC 25%)	Bent	1,460.40 F	*1,095.30 F
44	1		*FOG LAMP RH (DISC 10%)	Cracked	295.20 F	*265.68 F
45	4		*COOLANT (SN)	Necessary	49.20 F	*49.20 F
46	1		*ADVERTISEMENT STICKER (SN)	Necessary	148.44 F	*148.44 F

F=Franchise part.

Total Parts (\$\$) 15,246.92 5,383.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	857.00	700.00
2	SPRAY PAINT.	New	2,430.00	950.00
3	TO CONDUCT RADIATOR PRESSURE CHECK.	New	120.00	0.00
4	TO REPLACE SUNDRY PARTS.	New	100.00	20.00
5	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	20.00
6	TO WASH AND VACUUM.	New	60.00	0.00
7	TO TOP UP A/C GAS.	New	120.00	120.00
Gross Labour Cost (\$\$)			3,767.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >