

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19021719/UEA3Q2**Date:** 24/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994056
Claimant Vehicle No :	SMN1869B	Insured Vehicle No :	SGH2063E
Date of Loss:	02/12/2019	Nature of Claim:	TP
		Claim No:	1482364503SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN1869B		
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Engine No:	LEB5638351
Reg. Date:	26/07/2019 (Man. Year: 2019)	Chassis No:	GB71097937
Colour:	Grey	Odometer:	5820 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,315.52	2,191.44	1,124.08	33.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,990.00	1,030.00	960.00	48.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,305.52	3,221.44	2,084.08	39.28
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	5,305.52	2,500.00	2,805.52	52.88
+ GST 7.00/7.00% (S\$)	371.39	175.00	196.39	52.88
Nett Amount (S\$)	5,676.91	2,675.00	3,001.91	52.88
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	09/12/2019		
Date Inspected:	09/12/2019	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,409.10 FL	*1,193.70 FL
2	1		*FREED MEBLEM	Necessary	68.30 FL	*68.30 FL
3	1		*HYBRID EMBLEM	Necessary	81.90 FL	*81.90 FL
4	1		*H EMBLEM	Necessary	48.80 FL	*48.80 FL
5	1		*TAILGATE W/STRIP	Not Necessary	146.30 FL	*- FL
6	1		*REAR BUMPER	Deformed	977.50 FL	*977.50 FL
7	2		*REAR BUMPER RETAINERS	Necessary	41.00 FL	*41.00 FL
8	4		*REAR BUMPER CLIPS	Necessary	15.60 FL	*15.60 FL
9	2		*REAR BUMPER BEAM	Not Necessary	100.40 FL	*- FL
10	1		*END PANEL	Not Necessary	880.50 FL	*- FL
11	1		*REAR W/SCREEN GUM	Necessary	50.00 FS	*50.00 FS
12	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,069.40	2,676.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	753.88	485.36
Total Parts (\$\$)	3,315.52	2,191.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	800.00	400.00
3	WIRING	New	30.00	30.00
4	TRANSFER TAILGATE FITTING	New	80.00	80.00
5	REMOVE & REFIT REAR W/SCREEN	New	120.00	120.00
6	RUST PROOFING	New	80.00	0.00
7	UPHOLSTERY	New	80.00	0.00
Gross Labour Cost (\$\$)			1,990.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >